

# ECO INSPECTION CERTIFICATE

Premium

Order ID : 58820

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

<b>Ordered By :</b> JAVED ALAM SHAIKH	<b>Inspection Date :</b> 2019-04-06	<b>Valid Till :</b> 2019-07-06
--	--	-----------------------------------

## 7/10

Overall Score

- ✔ Evaluated across **6** segments
- ✔ Covered **121+** checkpoints
- ✔ **120** does not need attention
- ✔ **1** Owner , **2** Years Vehicle Age
- ✔ No Accidental History

**Inspected By**

✔ **Verified Technician**

122+ vehicle inspected  
1+ years experience

**Praveen Singh**

## Yamaha Fz25 250CC, 2017



### VEHICLE INFORMATION

<b>MAKE</b>	YAMAHA	<b>LOCATION</b>	MUMBAI CENTRAL
<b>MODEL</b>	FZ25	<b>REGISTRATION NO.</b>	MH01CW4468
<b>YEAR</b>	2017	<b>VIN/CHASIS NUMBER</b>	ME1RG4215H0013968
<b>TRIM</b>	250CC	<b>KMS RUN</b>	12751
<b>COLOR</b>	WHITE	<b>INSURANCE EXPIRY</b>	2018-10-16
<b>FUEL TYPE</b>	PETROL	<b>ENGINE SOUND LINK</b>	<a href="#">LISTEN ENGINE SOUND</a>

### KEY OBSERVATIONS

<b>FLOOD DAMAGE</b>	NO	<b>MAJOR ACCIDENT(S)</b>	NO	<b>SERVICE LOGS AVAILABLE</b>	NO
<b>TYRE LIFE REMAINING (KM)</b>	12,000	<b>RC COPY AVAILABLE</b>	YES (ORIGINAL)	<b>BANK HYPOTHECATION</b>	YES
<b>DENT</b>	NO	<b>INSURANCE COPY AVAILABLE</b>	NO	<b>BANK NOC</b>	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

**94,574**




Very Good Condition

### ECO SCORE & REPAIR COST ESTIMATE

#### ECO SCORE

<b>Tyre</b>	<div style="width: 70%;"></div>	<b>7 / 10</b>
<b>Control</b>	<div style="width: 70%;"></div>	<b>7 / 10</b>
<b>Light</b>	<div style="width: 70%;"></div>	<b>7 / 10</b>
<b>Oil</b>	<div style="width: 70%;"></div>	<b>7 / 10</b>
<b>Chassis</b>	<div style="width: 70%;"></div>	<b>7 / 10</b>
<b>Stand</b>	<div style="width: 70%;"></div>	<b>7 / 10</b>

#### TOTAL ESTIMATE SPEND 0



[www.droom.in/eco](http://www.droom.in/eco)

[eco@droom.in](mailto:eco@droom.in)

Contact No. 18004070707 (Toll Free)

-a service by .in

Ordered by: JAVED ALAM SHAIKH | Inspected date: 2019-04-06

Order Id: 58820

Overall Score



7/10



94,574

## TYRE



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRONT TYRE CONDITION & AIR PRESSURE	7	GOOD TREAD & PROPER	0
REAR TYRE CONDITION & AIR PRESSURE	7	GOOD TREAD & PROPER	0
WHEEL SPOKES FRONT	7	GOOD	0
WHEEL SPOKES REAR	7	GOOD	0
WHEEL RIM FRONT	7	NO WEAR & TEAR	0
WHEEL RIM REAR	7	NO WEAR & TEAR	0
WHEEL BEARINGS FRONT	7	WORKING	0
WHEEL BEARINGS REAR	7	WORKING	0
WHEEL SEALS FRONT	7	PROPER	0
WHEEL SEALS REAR	7	PROPER	0
BRAKE FUNCTION FRONT	7	GOOD BRAKE	0
BRAKE FUNCTION REAR	7	GOOD BRAKE	0
BRAKES CONDITION FRONT	7	GOOD	0
BRAKES CONDITION REAR	7	GOOD	0

## IMAGES



Ordered by: JAVED ALAM SHAIKH | Inspected date: 2019-04-06

Order Id: 58820

Overall Score



7/10



94,574

## STAND



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
CENTRE STAND CONDITION	7	GOOD CONDITION	0
CENTRE STAND RETENTION	7	PROPER RETENTION	0
SIDE STAND CONDITION	7	GOOD CONDITION	0
SIDE STAND RETENTION	7	PROPER RETENTION	0

## IMAGES



## CONTROL



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
HANDLEBARS CONDITION	7	GOOD CONDITION	0
LEVERS & PEDAL CONDITION	7	GOOD	0
PIVOTS	7	WORKING	0
CABLES CONDITION	7	GOOD	0
CABLES ROUTING	7	PROPER	0
HOSES CONDITION	7	GOOD	0
HOSES ROUTING	7	PROPER	0
THROTTLE OPERATION	7	NORMAL	0

Ordered by: JAVED ALAM SHAIKH | Inspected date: 2019-04-06

Order Id: 58820

Overall Score



7/10



94,574

## IMAGES




## OIL



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LEVELS - ENGINE OIL	6	MORE THEN MINIMUM LEVEL	0
LEVELS - GEAR OIL/SHAFT DRIVE (YES)	6	MORE THEN MINIMUM LEVEL	0
LEVELS - HYDRAULIC FLUID (YES)	7	MAX LEVEL	0
LEVELS - COOLANT (NO)	10		0
LEVELS - FUEL	6	MORE THEN MINIMUM LEVEL	0
LEAKS - ENGINE OIL	7	NO LEAKAGE	0
LEAKS - GEAR OIL	7	NO LEAKAGE	0
LEAKS - HYDRAULIC FLUID	7	NO LEAKAGE	0
LEAKS - FUEL	7	NO LEAKAGE	0
LEAKS - COOLANT	5	NA	0

## IMAGES



Ordered by: JAVED ALAM SHAIKH | Inspected date: 2019-04-06

Order Id: 58820

Overall Score



7/10



94,574


## LIGHT



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
BATTERY CONDITION	7	FULLY CHARGED	0
BATTERY VENT TUBE	7	NO DAMAGE FOUND	0
HEADLAMP CONDITION	7	GOOD	0
TAILLAMP/BRAKELAMP CONDITION	7	GOOD	0
TAILLAMP/BRAKELAMP OPERATION	7	WORKING	0
TURN SIGNALS OPERATION FRONT LEFT	7	WORKING	0
TURN SIGNALS OPERATION FRONT RIGHT	7	WORKING	0
TURN SIGNALS OPERATION REAR LEFT	7	WORKING	0
TURN SIGNALS OPERATION REAR RIGHT	7	WORKING	0
SWITCHES OPERATION	7	OPERATING	0
MIRRORS CONDITION	7	GOOD	0
MIRRORS AIM	7	PROPER AIM	0
LENSES & REFLECTORS CONDITION	7	GOOD	0
WIRING CONDITION	7	GOOD	0
WIRING ROUTING	7	PROPER	0

## IMAGES



Ordered by: JAVED ALAM SHAIKH | Inspected date: 2019-04-06

Order Id: 58820

Overall Score  **7/10**



**94,574**

## CHASSIS

**7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRAME CONDITION	7	GOOD CONDITION	0
FRAME STEERING-HEAD BEARINGS	7	NO DAMAGE	0
FRAME SWINGARM BUSHINGS	7	NO DAMAGE	0
SUSPENSION FRONT FORKS LEFT	7	WORKING	0
SUSPENSION FRONT FORKS RIGHT	7	WORKING	0
SUSPENSION REAR SHOCKS LEFT	7	WORKING	0
SUSPENSION REAR SHOCKS RIGHT	7	WORKING	0
CHAIN/BELT TENSION	7	CHAIN TENSION	0
CHAIN/BELT LUBRICATION	7	GOOD LUBRICATION	0
CHAIN/BELT SPROCKETS	7	CHAIN SPROCKET	0
FASTENERS THREADED	7	GOOD THREADED	0
FASTENERS CLIPS & COTTER PINS	7	PROPER FIX	0
ENGINE	7	MINIMUM NOISE	0
TRANSMISSION	7	SMOOTH GEAR SHIFTING	0

## IMAGES



Ordered by: JAVED ALAM SHAIKH | Inspected date: 2019-04-06

Order Id: 58820

Overall Score



7/10



94,574



## DOCUMENTS



## DESCRIPTION

good bike insurance copy not available



Ordered by: JAVED ALAM SHAIKH | Inspected date: 2019-04-06

Order Id: 58820

Overall Score




7/10



94,574

IMAGES



Ordered by: JAVED ALAM SHAIKH | Inspected date: 2019-04-06

Order Id: 58820

Overall Score



7/10



94,574

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.