

ECO INSPECTION CERTIFICATE

Premium

Order ID : 59065

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.


Ordered By : SYED HAIDER	Inspection Date : 2019-04-07	Valid Till : 2019-07-09
-----------------------------	---------------------------------	----------------------------

7/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 119 does not need attention
- ✓ 1 Owner , 5 Years Vehicle Age
- ✓ No Accidental History

Inspected By



✓ **Verified Technician**
288+ vehicle inspected
1+ years experience

Hemant Kumar

Skoda Rapid 1.6 Tdi Mt Active, 2014



VEHICLE INFORMATION

MAKE	SKODA	TRANSMISSION TYPE	MANUAL
MODEL	RAPID	REGISTRATION NO.	DL6CM6679
YEAR	2014	VIN/CHASIS NUMBER	018048
TRIM	1.6 TDI MT ACTIVE	KMS RUN	74101
COLOR	RED	INSURANCE EXPIRY	2020-1-23
BODY TYPE	SEDAN	LOCATION	DELHI
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	25,000	RC COPY AVAILABLE	YES (ORIGINAL)	BANK HYPOTHECATION	NO
DENT	YES	INSURANCE COPY AVAILABLE	YES (ZERO DEPRECIATION)	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

3,77,078




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 70%;"></div>	7 / 10
Wheel	<div style="width: 70%;"></div>	7 / 10
Test Drive	<div style="width: 70%;"></div>	7 / 10
Exterior	<div style="width: 70%;"></div>	7 / 10
Hood	<div style="width: 70%;"></div>	7 / 10

TOTAL ESTIMATE SPEND 12,000



Ordered by: SYED HAIDER | Inspected date: 2019-04-07

Order Id: 59065

Overall Score **7/10**





3,77,078

INTERIOR

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7	GOOD	0
DOOR HINGES	7	GOOD	0
CARPET & FLOOR MAT	7	GOOD	0
SEAT & SEAT BELT	7	GOOD	0
DASHBOARD & INSTRUMENT PANEL	7	GOOD	0
HORN	7	GOOD	0
SPEAKERS & MUSIC SYSTEM	7	GOOD	0
HANDBRAKE	7	GOOD	0
STEERING-MOUNTED CONTROLS	7	GOOD	0
PEDALS	7	GOOD	0
CENTRAL LOCK	7	GOOD	0
A/C VENTS & HEATER	7	GOOD	0
CUP HOLDERS	7	GOOD	0
NAVIGATION (NO)	10		0
ODOMETER	7	GOOD	0
POWER WINDOWS (YES)	8	GOOD	0
HAZARD LIGHT	7	GOOD	0

IMAGES



Ordered by: SYED HAIDER | Inspected date: 2019-04-07

Order Id: 59065

Overall Score **7/10**




3,77,078

TEST DRIVE

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7	GOOD	0
BRAKE PERFORMANCE	7	GOOD	0
CLUTCH PERFORMANCE	7	GOOD	0
ENGINE NOISE	7	GOOD	0
IGNITION SYSTEM	7	GOOD	0
SUSPENSION PERFORMANCE	7	GOOD	0
SUSPENSION FRONT SHOCKS	7	GOOD	0
SUSPENSION REAR SHOCKS	7	GOOD	0
TRANSMISSION ENGAGE	7	GOOD	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (YES)	7	GOOD	0
REAR VIEW CAMERA (YES)	7	GOOD	0

IMAGES




WHEEL

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7	GOOD	0
SPARE TYRE (YES)	7	GOO	0
WHEEL ASSEMBLY (ALLOY RIM)	7	GOOD	0

 IMAGES




 HOOD



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7	GOOD	0
RH APRON	7	GOOD	0
RADIATOR	7	GOOD	0
WIRING	7	GOOD	0
BATTERY	7	GOOD	0
BRAKE FLUID LEVEL	7	GOOD	0
ENGINE OIL	7	GOOD	0
COOLANT LEVEL	7	GOOD	0
BRAKE & COOLANT HOSE PIPES	7	GOOD	0
UNDERCARRIAGE	7	GOOD	0
EXHAUST SYSTEM	7	GOOD	0

 IMAGES



Ordered by: SYED HAIDER | Inspected date: 2019-04-07

Order Id: 59065

Overall Score



7/10



3,77,078

 EXTERIOR



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7	GOOD	0
FRONT BUMPER	6	FAIR CONDITION MINOR SCRATCHES	1000
HEAD LIGHTS	7	GOOD	0
GRILLE	7	GOOD	0
TURN SIGNAL	7	GOOD	0
HOOD	7	GOOD	0
PILLAR	7	GOOD	0
FRONT WINDSHIELD	7	GOOD	0
SIDE VIEW MIRRORS	7	GOOD	0
LH FRONT DOOR	6	FAIR CONDITION MINOR SCRATCHES	1000
LH REAR DOOR	6	MINOR DENT MINOR SCRATCHES	2000
LH RUNNING BOARD	7	GOOD	0
LH QUARTER PANEL	6	FAIR CONDITION MINOR SCRATCHES	500
FUEL LID	7	GOOD	0
REAR WINDSHIELD	7	GOOD	0
REAR BUMPER	6	FAIR CONDITION MINOR SCRATCHES	1500
TAIL LIGHT	7	GOOD	0
TRUNK LID/TAIL GATE	7	GOOD	0
LUGGAGE COMPARTMENT LIGHT	7	GOOD	0
RH QUARTER PANEL	7	GOOD	0
RH RUNNING BOARD	7	GOOD	0
RH REAR DOOR	6	FAIR CONDITION MINOR SCRATCHES	1000

RH FRONT DOOR	6	FAIR CONDITION MINOR SCRATCHES	1000
RH FENDER	7	GOOD	0

Ordered by: SYED HAIDER | Inspected date: 2019-04-07

Order Id: 59065

Overall Score **7/10**



3,77,078


EXTERIOR (CONTINUED)

7/10



INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
BODY RUST	7	GOOD	0
ROOF (REGULAR)	7	GOOD	0
PAINT CONDITION	7	GOOD	0
FOG LAMPS	0	NA	0
LH FENDER	3	DENT NEED TO REPAIR	4000

IMAGES






NEED ATTENTION



DOCUMENTS



DESCRIPTION

left hand fender dent minor scratches in body minor scratches in doors

Ordered by: SYED HAIDER | Inspected date: 2019-04-07

Order Id: 59065

Overall Score











7/10



3,77,078

IMAGES





Ordered by: SYED HAIDER | Inspected date: 2019-04-07

Order Id: 59065

Overall Score



7/10



3,77,078

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.