

ECO INSPECTION CERTIFICATE

Premium

Order ID : 61793

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By :
Ankit Tiwari

Inspection Date :
2019-04-13

Location :
PUNE

7/10

Overall Score

- ✓ Evaluated across 6 segments
- ✓ Covered 121+ checkpoints
- ✓ 118 does not need attention
- ✓ 1 Owner , 6 Years Vehicle Age
- ✓ No Accidental History

Inspected By



Abhishek
Shelar

- ✓ Verified Technician
- 41+ vehicle inspected
- 1+ years experience

Yamaha Yzf-R15 2.0 150CC, 2013



VEHICLE INFORMATION

MAKE	YAMAHA	ENGINE NUMBER	1CK1010578
MODEL	YZF-R15 2.0	REGISTRATION NO.	MH12HQ6939
YEAR	2013	VIN/CHASSIS NUMBER	ME11CK01BB2010515
TRIM	150CC	ODOMETER READING	50092
COLOR	BLUE	INSURANCE EXPIRY	2019-9-20
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY OBSERVATIONS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	8,000	RC COPY AVAILABLE	YES (ORIGINAL)	BANK HYPOTHECATION	NO
DENT	YES	INSURANCE COPY AVAILABLE	YES (COMPREHENSIVE)	BANK NOC	NO



orangebookvalue.com

Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

64,282




Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Tyre	<div style="width: 60%;"></div>	6 / 10
Control	<div style="width: 60%;"></div>	6 / 10
Light	<div style="width: 70%;"></div>	7 / 10
Oil	<div style="width: 80%;"></div>	8 / 10
Chassis	<div style="width: 60%;"></div>	6 / 10
Stand	<div style="width: 60%;"></div>	6 / 10

TOTAL ESTIMATE SPEND 0



www.droom.in/eco

eco@droom.in

Contact No. 18004070707 (Toll Free)

-a service by .in

Ordered by: Ankit Tiwari | Inspected date: 2019-04-13

Order Id: 61793

Overall Score  **7/10**



64,282

TYRE

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRONT TYRE CONDITION & AIR PRESSURE	6	OK	0
WHEEL SPOKES FRONT	6	OK	0
WHEEL SPOKES REAR	6	OK	0
WHEEL RIM FRONT	6	OK	0
WHEEL RIM REAR	6	OK	0
WHEEL BEARINGS FRONT	6	OK	0
WHEEL BEARINGS REAR	6	OK	0
WHEEL SEALS FRONT	6	OK	0
WHEEL SEALS REAR	6	OK	0
BRAKE FUNCTION FRONT	6	OK	0
BRAKE FUNCTION REAR	6	OK	0
BRAKES CONDITION FRONT	6	OK	0
BRAKES CONDITION REAR	7	OK	0
REAR TYRE CONDITION & AIR PRESSURE	5	OK	0

IMAGES





Ordered by: Ankit Tiwari | Inspected date: 2019-04-13

Order Id: 61793

Overall Score



7/10



64,282



NEED ATTENTION



STAND



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
CENTRE STAND CONDITION	6	OK	0
CENTRE STAND RETENTION	6	OK	0
SIDE STAND CONDITION	6	GOOD	0
SIDE STAND RETENTION	7	OK	0



IMAGES





CONTROL



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
HANDLEBARS CONDITION	6	OK	0
LEVERS & PEDAL CONDITION	7	OK	0
PIVOTS	6	OK	0
CABLES CONDITION	7	OK	0
CABLES ROUTING	6	OK	0
HOSES CONDITION	6	OK	0
HOSES ROUTING	6	OK	0
THROTTLE OPERATION	6	GOOD	0



IMAGES



OIL



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LEVELS - ENGINE OIL	7	OK	0
LEVELS - GEAR OIL/SHAFT DRIVE (NO)	10		0
LEVELS - HYDRAULIC FLUID (NO)	10		0
LEVELS - COOLANT (NO)	10		0
LEVELS - FUEL	7	GOOD	0
LEAKS - ENGINE OIL	7	NO LEAK	0
LEAKS - GEAR OIL	6	OK	0

LEAKS - HYDRAULIC FLUID	7	OK	0
LEAKS - COOLANT	7	OK	0
LEAKS - FUEL	6	NO LEAK OK	0

IMAGES



Ordered by: Ankit Tiwari | Inspected date: 2019-04-13

Order Id: 61793

Overall Score **7/10**




64,282

LIGHT

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
BATTERY CONDITION	6	OK	0
BATTERY VENT TUBE	6	OK	0
HEADLAMP CONDITION	7	GOOD	0
TAILLAMP/BRAKELAMP CONDITION	7	OK	0
TAILLAMP/BRAKELAMP OPERATION	7	OK	0
TURN SIGNALS OPERATION FRONT LEFT	7	OK	0
TURN SIGNALS OPERATION FRONT RIGHT	6	OK	0
TURN SIGNALS OPERATION REAR LEFT	7	GOOD	0
TURN SIGNALS OPERATION REAR RIGHT	6	GOOD	0
SWITCHES OPERATION	6	OK	0
LENSES & REFLECTORS CONDITION	7	OK	0
WIRING CONDITION	7	OK	0
WIRING ROUTING	6	OK	0
MIRRORS CONDITION	0	REMOVED	0
MIRRORS AIM	0	REMOVED	0

IMAGES



Ordered by: Ankit Tiwari | Inspected date: 2019-04-13

Order Id: 61793

Overall Score **7/10**



64,282

 **NEED ATTENTION** 



 **CHASSIS**

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRAME CONDITION	6	SCRATCH	0
FRAME STEERING-HEAD BEARINGS	6	OK	0
FRAME SWINGARM BUSHINGS	6	OK	0
SUSPENSION FRONT FORKS LEFT	6	OK	0
SUSPENSION FRONT FORKS RIGHT	6	GOOD	0
SUSPENSION REAR SHOCKS LEFT	6	OK	0
SUSPENSION REAR SHOCKS RIGHT	7	GOOD	0
CHAIN/BELT TENSION	7	GOOD	0
CHAIN/BELT LUBRICATION	7	OK	0
CHAIN/BELT SPROCKETS	6	OK	0
FASTENERS THREADED	7	OK	0
FASTENERS CLIPS & COTTER PINS	6	OK	0
ENGINE	6	OK	0
TRANSMISSION	6	OK	0

Ordered by: Ankit Tiwari | Inspected date: 2019-04-13

Order Id: 61793

Overall Score



7/10




64,282

IMAGES



DOCUMENTS



DESCRIPTION

regular use. running ok. little small scatch

Overall Score






7/10



64,282

IMAGES





Ordered by: Ankit Tiwari | Inspected date: 2019-04-13

Order Id: 61793

Overall Score



7/10



64,282

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.