

# ECO INSPECTION CERTIFICATE

Premium

Order ID : 58853

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Monika Sharma	Inspection Date : 2019-04-09	Valid Till : 2019-07-12
-------------------------------	---------------------------------	----------------------------

## 6/10

**Overall Score**

- ✔ Evaluated across **5** segments
- ✔ Covered **121+** checkpoints
- ✔ **116** does not need attention
- ✔ **1** Owner , **7** Years Vehicle Age
- ✔ No Accidental History

**Inspected By**

✔ **Verified Technician**

842+ vehicle inspected

2+ years experience

**Santosh Kumar**

## Volkswagen Polo 1.2 TDI HIGHLINE, 2012



### VEHICLE INFORMATION

MAKE	VOLKSWAGEN	TRANSMISSION TYPE	MANUAL
MODEL	POLO	REGISTRATION NO.	UP14BR0846
YEAR	2012	VIN/CHASIS NUMBER	032540
TRIM	1.2 TDI HIGHLINE	KMS RUN	60651
COLOR	GREY	INSURANCE EXPIRY	2019-4-27
BODY TYPE	HATCHBACK	LOCATION	GHAZIABAD
FUEL TYPE	DIESEL	ENGINE SOUND LINK	<a href="#">LISTEN ENGINE SOUND</a>

### KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	45,000	RC COPY AVAILABLE	YES (ORIGINAL)	BANK HYPOTHECATION	NO
DENT	NO	INSURANCE COPY AVAILABLE	YES (COMPREHENSIVE)	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

**3,27,115**




### ECO SCORE & REPAIR COST ESTIMATE

#### ECO SCORE

Interior	<div style="width: 70%; background-color: green;"></div>	<b>7 / 10</b>
Wheel	<div style="width: 70%; background-color: green;"></div>	<b>7 / 10</b>
Test Drive	<div style="width: 70%; background-color: green;"></div>	<b>7 / 10</b>
Exterior	<div style="width: 60%; background-color: yellow;"></div>	<b>6 / 10</b>
Hood	<div style="width: 60%; background-color: yellow;"></div>	<b>6 / 10</b>
Odometer Assurance	<div style="width: 50%; background-color: orange;"></div>	<b>5 / 10</b>

#### TOTAL ESTIMATE SPEND 13,750



[www.droom.in/eco](http://www.droom.in/eco)

[eco@droom.in](mailto:eco@droom.in)

Contact No. 18004070707 (Toll Free)

-a service by  **droom**.in

Ordered by: Monika Sharma | Inspected date: 2019-04-09

Order Id: 58853

Overall Score



6/10



3,27,115



## INTERIOR




7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7	GOOD	0
DOOR HINGES	7	GOOD	0
SEAT & SEAT BELT	7	GOOD	0
DASHBOARD & INSTRUMENT PANEL	7	GOOD	0
HORN	7	GOOD	0
SPEAKERS & MUSIC SYSTEM	7	GOOD	0
HANDBRAKE	6	FAIR	0
STEERING-MOUNTED CONTROLS	7	GOOD	0
PEDALS	7	GOOD	0
CENTRAL LOCK	7	GOOD	0
A/C VENTS & HEATER	6	FAIR	0
CUP HOLDERS	7	GOOD	0
NAVIGATION (NO)	10		0
ODOMETER	7	GOOD	0
POWER WINDOWS (YES)	7	GOOD	0
HAZARD LIGHT	7	GOOD	0
CARPET & FLOOR MAT	5	NEED DRYCLINIG	2500



## IMAGES



Ordered by: Monika Sharma | Inspected date: 2019-04-09

Order Id: 58853

Overall Score **6/10**



**3,27,115**

## TEST DRIVE

**7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7	GOOD	0
BRAKE PERFORMANCE	7	GOOD	0
CLUTCH PERFORMANCE	6	FAIR	0
ENGINE NOISE	6	FAIR	0
IGNITION SYSTEM	7	GOOD	0
SUSPENSION PERFORMANCE	7	GOOD	0
SUSPENSION FRONT SHOCKS	7	GOOD	0
SUSPENSION REAR SHOCKS	7	GOOD	0
TRANSMISSION ENGAGE	7	GOOD	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (YES)	7	GOOD	0
REAR VIEW CAMERA (NO)	10		0

## IMAGES



## WHEEL

**7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	8	GOOD	0
SPARE TYRE (YES)	7	GOOD	0
WHEEL ASSEMBLY (ALLOY RIM)	7	GOOD	0

 IMAGES




 HOOD



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7	GOOD	0
RH APRON	7	GOOD	0
RADIATOR	6	FAIR	0
WIRING	7	GOOD	0
BATTERY	6	FAIR	0
BRAKE FLUID LEVEL	6	FAIR	0
BRAKE & COOLANT HOSE PIPES	7	GOOD	0
UNDERCARRIAGE	7	GOOD	0
EXHAUST SYSTEM	6	FAIR	0
ENGINE OIL	4	POOR	3000
COOLANT LEVEL	4	POOR	750

 IMAGES



Ordered by: Monika Sharma | Inspected date: 2019-04-09

Order Id: 58853

Overall Score  **6/10**



**3,27,115**

 **EXTERIOR**

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7	GOOD	0
FRONT BUMPER	6	PAINTED	0
HEAD LIGHTS	6	FAIR	0
GRILLE	7	GOOD	0
TURN SIGNAL	7	GOOD	0
HOOD	6	PAINTED	0
PILLAR	7	GOOD	0
FRONT WINDSHIELD	6	ALREADY CHANGED	0
SIDE VIEW MIRRORS	6	PAINTED	0
LH FENDER	6	PAINTED	0
LH FRONT DOOR	6	PAINTED	0
LH REAR DOOR	6	PAINTED	0
LH RUNNING BOARD	6	PAINTED	0
LH QUARTER PANEL	6	PAINTED	0
FUEL LID	6	PAINTED	0
REAR BUMPER	6	PAINTED	0
TAIL LIGHT	6	FAIR	0
TRUNK LID/TAIL GATE	6	PAINTED	0
LUGGAGE COMPARTMENT LIGHT	7	GOOD	0
RH QUARTER PANEL	6	PAINTED	0
RH RUNNING BOARD	6	PAINTED	0
RH REAR DOOR	6	PAINTED	0
RH FRONT DOOR	6	PAINTED	0
RH FENDER	6	PAINTED	0

Ordered by: Monika Sharma | Inspected date: 2019-04-09

Order Id: 58853

Overall Score  **6/10**



**3,27,115**

**EXTERIOR (CONTINUED)**

**6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
BODY RUST	7	GOOD	0
ROOF (REGULAR)	7	GOOD	0
PAINT CONDITION	6	FULL CAR IS PAINTED WITHOUT ROOF	0
FOG LAMPS	4	POOR	2000
REAR WINDSHIELD	4	SCRATCH	5500

**IMAGES**



**NEED ATTENTION ⚠**



Ordered by: Monika Sharma | Inspected date: 2019-04-09

Order Id: 58853

Overall Score




6/10



3,27,115



## DOCUMENTS



## DESCRIPTION

car is fair condition car full car is painted without roof need to be service



Ordered by: Monika Sharma | Inspected date: 2019-04-09

Order Id: 58853

Overall Score




6/10



3,27,115

IMAGES



Ordered by: Monika Sharma | Inspected date: 2019-04-09

Order Id: 58853

Overall Score



6/10



3,27,115

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.