

# ECO INSPECTION CERTIFICATE

Premium

Order ID : 62802

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.


<b>Ordered By :</b> Sanjeev Kumar Juneja	<b>Inspection Date :</b> 2019-04-16	<b>Location :</b> DELHI
---	--	----------------------------

## 7/10

**Overall Score**

- ✔ Evaluated across **5** segments
- ✔ Covered **121+** checkpoints
- ✔ **119** does not need attention
- ✔ **1** Owner , **8** Years Vehicle Age
- ✔ No Accidental History

**Inspected By**



**Verified Technician**  
261+ vehicle inspected  
1+ years experience










Mohit Kumar

## Hyundai I10 SPORTZ 1.2 AT, 2011



VEHICLE INFORMATION			
MAKE	HYUNDAI	ENGINE NUMBER	658182
MODEL	I10	REGISTRATION NO.	DL3CBR6465
MFG. DATE	2019-04-01	VIN/CHASSIS NUMBER	900868
TRIM	SPORTZ 1.2 AT	ODOMETER READING	33910
COLOR	RED	INSURANCE EXPIRY	2018-10-10
BODY TYPE	HATCHBACK	VEHICLE PASSING	PRIVATE
FUEL TYPE	PETROL	ENGINE SOUND LINK	<a href="#">LISTEN ENGINE SOUND</a>

## KEY HIGHLIGHTS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	24,000	 RC COPY AVAILABLE	ORIGINAL	 BANK HYPOTHECATION	NO
 DENT	NO	 INSURANCE COPY AVAILABLE	NO	 BANK NOC	NO








Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.  
With this evaluation, the Fair Market Price for this vehicle comes to be:

Orange Book Value Not Available




## ECO SCORE & REPAIR COST ESTIMATE

### ECO SCORE

 Interior	<div style="width: 70%; background-color: green;"></div>	<b>7 / 10</b>
 Wheel	<div style="width: 80%; background-color: green;"></div>	<b>8 / 10</b>
 Test Drive	<div style="width: 80%; background-color: green;"></div>	<b>8 / 10</b>
 Exterior	<div style="width: 70%; background-color: green;"></div>	<b>7 / 10</b>
 Hood	<div style="width: 70%; background-color: green;"></div>	<b>7 / 10</b>

### TOTAL ESTIMATE SPEND 1,000



Ordered by: Sanjeev Kumar Juneja | Inspected date: 2019-04-16

Order Id: 62802

Overall Score  **7/10**




Orange Book Value Not Available

## INTERIOR

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7		0
DOOR HINGES	7		0
CARPET & FLOOR MAT	7		0
SEAT & SEAT BELT	7		0
DASHBOARD & INSTRUMENT PANEL	7		0
HORN	7		0
SPEAKERS & MUSIC SYSTEM	7		0
HANDBRAKE	7		0
PEDALS	7		0
CENTRAL LOCK	7		0
A/C VENTS & HEATER	7		0
CUP HOLDERS	7		0
NAVIGATION (NO)	10		0
ODOMETER	7		0
POWER WINDOWS (YES)	7		0
HAZARD LIGHT	7		0
STEERING-MOUNTED CONTROLS	0	NOT AVAILABLE	0

## IMAGES





## TEST DRIVE




8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7		0
BRAKE PERFORMANCE	7		0
CLUTCH PERFORMANCE	7		0
ENGINE NOISE	7		0
IGNITION SYSTEM	7		0
SUSPENSION PERFORMANCE	7		0
SUSPENSION FRONT SHOCKS	7		0
SUSPENSION REAR SHOCKS	7		0
TRANSMISSION ENGAGE	7		0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0



## IMAGES




## WHEEL



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	8		0
SPARE TYRE (YES)	8		0
WHEEL ASSEMBLY (STEEL RIM)	7		0

 IMAGES



 HOOD



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7		0
RH APRON	7		0
RADIATOR	7		0
WIRING	7		0
BATTERY	7		0
BRAKE FLUID LEVEL	7		0
ENGINE OIL	7		0
COOLANT LEVEL	7		0
BRAKE & COOLANT HOSE PIPES	7		0
UNDERCARRIAGE	7		0
EXHAUST SYSTEM	7		0

 IMAGES





Ordered by: Sanjeev Kumar Juneja | Inspected date: 2019-04-16

Order Id: 62802

Overall Score



7/10



Orange Book Value Not Available



EXTERIOR



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7		0
FRONT BUMPER	7		0
HEAD LIGHTS	7		0
GRILLE	7		0
TURN SIGNAL	6	RHS MIRROR TURN SIGNAL NOT WORKING NEED TO CHECK	500
HOOD	7		0
PILLAR	7		0
FRONT WINDSHIELD	7		0
SIDE VIEW MIRRORS	7		0
LH FENDER	7		0
LH FRONT DOOR	7		0
LH REAR DOOR	7		0
LH RUNNING BOARD	7		0
LH QUARTER PANEL	7		0
FUEL LID	7		0
REAR WINDSHIELD	7		0
REAR BUMPER	7		0
TAIL LIGHT	6	LHS NOT WORKING NEED TO CHECK	500
TRUNK LID/TAIL GATE	7		0
LUGGAGE COMPARTMENT LIGHT	7		0
RH QUARTER PANEL	7		0
RH RUNNING BOARD	7		0
RH REAR DOOR	7		0
RH FRONT DOOR	7		0





Ordered by: Sanjeev Kumar Juneja | Inspected date: 2019-04-16

Order Id: 62802

Overall Score



7/10



Orange Book Value Not Available



## EXTERIOR (CONTINUED)



7/10


INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FENDER	7		0
BODY RUST	7		0
ROOF (REGULAR)	7		0
PAINT CONDITION	7		0
FOG LAMPS	0	NOT AVAILABLE	0



## IMAGES








**NEED ATTENTION**



**DOCUMENTS**



**DESCRIPTION**

All body is good condition and all lights working properly without rhs mirror turn signal and LHS t



Ordered by: Sanjeev Kumar Juneja | Inspected date: 2019-04-16

Order Id: 62802

Overall Score




7/10




Orange Book Value Not Available

IMAGES









[www.droom.in/eco](http://www.droom.in/eco)

[eco@droom.in](mailto:eco@droom.in)

Contact No. 18004070707 (Toll Free)

-a service by  **droom**.in



Ordered by: Sanjeev Kumar Juneja | Inspected date: 2019-04-16

Order Id: 62802

Overall Score



7/10



Orange Book Value Not Available

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.