



ECO INSPECTION CERTIFICATE

Premium

Order ID : 60858

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Khalid Shekh	Inspection Date : 2019-04-19	Location : BANGALORE	 Inspected By  Abhishek By
------------------------------	---------------------------------	-------------------------	---

7/10

Overall Score

- ✔ Evaluated across **5** segments
- ✔ Covered **121+** checkpoints
- ✔ **120** does not need attention
- ✔ **1** Owner , **5** Years Vehicle Age
- ✔ No Accidental History

✔ **Verified Technician**

125+ vehicle inspected
1+ years experience










Maruti Suzuki Ciaz Zxi, 2014



VEHICLE INFORMATION

MAKE	MARUTI SUZUKI	ENGINE NUMBER	K14BN70503
MODEL	CIAZ	REGISTRATION NO.	KA51MG2743
MFG. DATE	2015-12-25	VIN/CHASSIS NUMBER	MA3EXMG1S00117924
TRIM	ZXI	ODOMETER READING	88127
COLOR	SILVER	INSURANCE EXPIRY	2019-1-10
BODY TYPE	SEDAN	VEHICLE PASSING	PRIVATE
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	10,000	 RC COPY AVAILABLE	ORIGINAL	 BANK HYPOTHECATION	NO
 DENT	NO	 INSURANCE COPY AVAILABLE	NO	 BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

5,06,673




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

 Interior	<div style="width: 80%; background-color: #0070C0;"></div>	8 / 10
 Wheel	<div style="width: 80%; background-color: #0070C0;"></div>	8 / 10
 Test Drive	<div style="width: 70%; background-color: #0070C0;"></div>	7 / 10
 Exterior	<div style="width: 80%; background-color: #0070C0;"></div>	8 / 10
 Hood	<div style="width: 70%; background-color: #0070C0;"></div>	7 / 10

TOTAL ESTIMATE SPEND 0



Ordered by: Khalid Shekh | Inspected date: 2019-04-19

Order Id: 60858

Overall Score **7/10**






5,06,673


INTERIOR

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	8		0
DOOR HINGES	7		0
CARPET & FLOOR MAT	7		0
SEAT & SEAT BELT	7		0
DASHBOARD & INSTRUMENT PANEL	8		0
HORN	7		0
SPEAKERS & MUSIC SYSTEM	8		0
HANDBRAKE	8		0
STEERING-MOUNTED CONTROLS	8		0
PEDALS	8		0
CENTRAL LOCK	7		0
A/C VENTS & HEATER	8		0
CUP HOLDERS	8		0
NAVIGATION (NO)	10		0
ODOMETER	8		0
POWER WINDOWS (YES)	7		0
HAZARD LIGHT	8		0

IMAGES






TEST DRIVE

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7		0
BRAKE PERFORMANCE	7		0
CLUTCH PERFORMANCE	7		0
ENGINE NOISE	7		0
IGNITION SYSTEM	7		0
SUSPENSION PERFORMANCE	7		0
SUSPENSION REAR SHOCKS	7		0
TRANSMISSION ENGAGE	7		0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (YES)	8		0
REAR VIEW CAMERA (YES)	8		0
SUSPENSION FRONT SHOCKS	5	LEAKAGE	0



IMAGES



WHEEL

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7		0
SPARE TYRE (YES)	8		0
WHEEL ASSEMBLY (ALLOY RIM)	8		0

 IMAGES



 HOOD



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	8		0
RH APRON	6		0
RADIATOR	7		0
WIRING	8		0
BATTERY	8		0
BRAKE FLUID LEVEL	7		0
ENGINE OIL	7		0
COOLANT LEVEL	7		0
BRAKE & COOLANT HOSE PIPES	7		0
UNDERCARRIAGE	8		0
EXHAUST SYSTEM	8		0

 IMAGES



Ordered by: Khalid Shekh | Inspected date: 2019-04-19

Order Id: 60858

Overall Score  **7/10**



5,06,673

 **EXTERIOR**

 **8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7		0
FRONT BUMPER	7		0
HEAD LIGHTS	7		0
GRILLE	8		0
TURN SIGNAL	8		0
FOG LAMPS	7		0
HOOD	8		0
PILLAR	7		0
FRONT WINDSHIELD	8		0
SIDE VIEW MIRRORS	8		0
LH FENDER	8		0
LH FRONT DOOR	7		0
LH REAR DOOR	8		0
LH RUNNING BOARD	8		0
LH QUARTER PANEL	8		0
FUEL LID	7		0
REAR WINDSHIELD	8		0
REAR BUMPER	7		0
TAIL LIGHT	7		0
TRUNK LID/TAIL GATE	7		0
LUGGAGE COMPARTMENT LIGHT	7		0
RH QUARTER PANEL	8		0
RH RUNNING BOARD	8		0
RH REAR DOOR	8		0

Ordered by: Khalid Shekh | Inspected date: 2019-04-19

Order Id: 60858

Overall Score **7/10**



5,06,673

EXTERIOR (CONTINUED)

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	8		0
RH FENDER	7		0
BODY RUST	8		0
ROOF (REGULAR)	8		0
PAINT CONDITION	9		0

IMAGES





 DOCUMENTS



 DESCRIPTION

front shocks leakage

Ordered by: Khalid Shekh | Inspected date: 2019-04-19

Order Id: 60858

Overall Score












7/10



5,06,673

IMAGES





Ordered by: Khalid Shekh | Inspected date: 2019-04-19

Order Id: 60858

Overall Score



7/10



5,06,673

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.