




ECO INSPECTION CERTIFICATE

Premium

Order ID : 62852






121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : KARAM VEER	Inspection Date : 2019-04-22	Location : DELHI	 Inspected By  Mohit Kumar  Verified Technician 270+ vehicle inspected 1+ years experience
----------------------------	---------------------------------	---------------------	---

7/10

Overall Score

-  Evaluated across **5** segments
-  Covered **121+** checkpoints
-  **121** does not need attention
-  **1** Owner , **3** Years Vehicle Age
-  No Accidental History



Ford Ecosport Trend 1.5L TDCi, 2016



VEHICLE INFORMATION

MAKE	FORD	ENGINE NUMBER	M26641
MODEL	ECOSPORT	REGISTRATION NO.	DL1CU5452
MFG. DATE	2015-11-30	VIN/CHASSIS NUMBER	M26641
TRIM	TREND 1.5L TDCI	ODOMETER READING	62107
COLOR	WHITE	INSURANCE EXPIRY	2019-12-26
BODY TYPE	COMPACT SUV	VEHICLE PASSING	PRIVATE
FUEL TYPE	DIESEL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	25,000	 RC COPY AVAILABLE	ORIGINAL	 BANK HYPOTHECATION	NO
 DENT	NO	 INSURANCE COPY AVAILABLE	YES (COMPREHENSIVE)	 BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:


6,77,811




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

 Interior	<div style="width: 70%;"></div>	7 / 10
 Wheel	<div style="width: 80%;"></div>	8 / 10
 Test Drive	<div style="width: 70%;"></div>	7 / 10
 Exterior	<div style="width: 70%;"></div>	7 / 10
 Hood	<div style="width: 70%;"></div>	7 / 10

TOTAL ESTIMATE SPEND 4,000



Ordered by: KARAM VEER | Inspected date: 2019-04-22

Order Id: 62852

Overall Score **7/10**



6,77,811

INTERIOR

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7		0
DOOR HINGES	7		0
CARPET & FLOOR MAT	7		0
SEAT & SEAT BELT	6	REAR SEAT BELT BROKEN NEED REPLACE	2000
DASHBOARD & INSTRUMENT PANEL	7		0
HORN	7		0
SPEAKERS & MUSIC SYSTEM	7		0
HANDBRAKE	7		0
STEERING-MOUNTED CONTROLS	7		0
PEDALS	7		0
CENTRAL LOCK	7		0
A/C VENTS & HEATER	7		0
CUP HOLDERS	7		0
NAVIGATION (NO)	10		0
ODOMETER	7		0
POWER WINDOWS (YES)	7		0
HAZARD LIGHT	7		0

IMAGES





TEST DRIVE



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7		0
BRAKE PERFORMANCE	7		0
CLUTCH PERFORMANCE	7		0
ENGINE NOISE	7		0
IGNITION SYSTEM	7		0
SUSPENSION PERFORMANCE	7		0
SUSPENSION FRONT SHOCKS	7		0
SUSPENSION REAR SHOCKS	7		0
TRANSMISSION ENGAGE	7		0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (YES)	7		0
REAR VIEW CAMERA (YES)	6	CAMERA SCREEN BLURING NEED TO CHECK AND REPAIR	2000



IMAGES




WHEEL



8/10


INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	8		0
SPARE TYRE (YES)	7		0

 IMAGES

 HOOD

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7		0
RH APRON	7		0
RADIATOR	7		0
WIRING	7		0
BATTERY	7		0
BRAKE FLUID LEVEL	7		0
ENGINE OIL	7		0
COOLANT LEVEL	7		0
BRAKE & COOLANT HOSE PIPES	7		0
UNDERCARRIAGE	7		0
EXHAUST SYSTEM	7		0

 IMAGES

Ordered by: KARAM VEER | Inspected date: 2019-04-22

Order Id: 62852

Overall Score  **7/10**



6,77,811

 **EXTERIOR**

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7		0
FRONT BUMPER	7		0
HEAD LIGHTS	7		0
GRILLE	7		0
TURN SIGNAL	7		0
FOG LAMPS	7		0
HOOD	7		0
PILLAR	7		0
FRONT WINDSHIELD	7		0
SIDE VIEW MIRRORS	7		0
LH FENDER	7		0
LH FRONT DOOR	7		0
LH REAR DOOR	7		0
LH RUNNING BOARD	7		0
LH QUARTER PANEL	7		0
FUEL LID	7		0
REAR WINDSHIELD	7		0
REAR BUMPER	7		0
TAIL LIGHT	7		0
TRUNK LID/TAIL GATE	7		0
LUGGAGE COMPARTMENT LIGHT	7		0
RH QUARTER PANEL	7		0
RH RUNNING BOARD	7		0
RH REAR DOOR	7		0

Ordered by: KARAM VEER | Inspected date: 2019-04-22

Order Id: 62852

Overall Score **7/10**



6,77,811


EXTERIOR (CONTINUED)

7/10


INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	7		0
RH FENDER	7		0
BODY RUST	7		0
ROOF (REGULAR)	7		0
PAINT CONDITION	7		0

IMAGES





 DOCUMENTS



 DESCRIPTION

All body is good condition and all lights working properly seal belt broken need to replace and c

Ordered by: KARAM VEER | Inspected date: 2019-04-22

Order Id: 62852

Overall Score





7/10





6,77,811

IMAGES







Ordered by: KARAM VEER | Inspected date: 2019-04-22

Order Id: 62852

Overall Score



7/10



6,77,811

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.