



ECO INSPECTION CERTIFICATE

Premium

Order ID : 64797

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : JALIL	Inspection Date : 2019-04-22	Location : PUNE	 Inspected By  Verified Technician 24+ vehicle inspected 1+ years experience Ameya Aranke
-----------------------	---------------------------------	--------------------	---

7/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 119 does not need attention
- ✓ 1 Owner , 1 Year Vehicle Age
- ✓ No Accidental History









Maruti Suzuki Wagon R LXI CNG, 2018



VEHICLE INFORMATION

MAKE	MARUTI SUZUKI	ENGINE NUMBER	
MODEL	WAGON R	REGISTRATION NO.	MH14GU2529
MFG. DATE	0000-00-00	VIN/CHASSIS NUMBER	85811
TRIM	LXI CNG	ODOMETER READING	43851
COLOR	BLACK	INSURANCE EXPIRY	2019-4-13
BODY TYPE	HATCHBACK	VEHICLE PASSING	COMMERCIAL
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	10,000	 RC COPY AVAILABLE	ORIGINAL	 BANK HYPOTHECATION	YES
 DENT	NO	 INSURANCE COPY AVAILABLE	NO	 BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:




4,77,710




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

 Interior	<div style="width: 70%;"></div>	7 / 10
 Wheel	<div style="width: 70%;"></div>	7 / 10
 Test Drive	<div style="width: 80%;"></div>	8 / 10
 Exterior	<div style="width: 70%;"></div>	7 / 10
 Hood	<div style="width: 70%;"></div>	7 / 10

TOTAL ESTIMATE SPEND 800



Ordered by: JALIL | Inspected date: 2019-04-22

Order Id: 64797

Overall Score



7/10



4,77,710



INTERIOR







7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7	GOOD CONDITION	0
DOOR HINGES	7	GOOD HINGES	0
CARPET & FLOOR MAT	7	GOOD CONDITION	0
SEAT & SEAT BELT	7	PROPER MOVEMENT	0
DASHBOARD & INSTRUMENT PANEL	7	GOOD CONDITION	0
HORN	7	WORKING	0
SPEAKERS & MUSIC SYSTEM	7	GOOD SOUND	0
HANDBRAKE	7	PROPER HOLD	0
STEERING-MOUNTED CONTROLS	7	NOT AVAILABLE	0
PEDALS	7	GOOD CONDITION	0
CENTRAL LOCK	7	WORKING	0
A/C VENTS & HEATER	7	GOOD COOLING	0
CUP HOLDERS	7	GOOD CONDITION	0
NAVIGATION (NO)	10		0
ODOMETER	7	GOOD CONDITION	0
POWER WINDOWS (YES - FRONT ONLY)	6	WORKING	0
HAZARD LIGHT	7	WORKING	0



IMAGES



Ordered by: JALIL | Inspected date: 2019-04-22

Order Id: 64797

Overall Score **7/10**





4,77,710

TEST DRIVE

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7	GOOD MOVEMENT	0
BRAKE PERFORMANCE	7	GOOD PERFORMANCE	0
CLUTCH PERFORMANCE	7	GOOD PERFORMANCE	0
ENGINE NOISE	7	NORMAL WORKING NOISE	0
IGNITION SYSTEM	7	WORKING	0
SUSPENSION PERFORMANCE	7	GOOD PERFORMANCE	0
SUSPENSION FRONT SHOCKS	7	NO SHOCKS	0
SUSPENSION REAR SHOCKS	7	NO SHOCKS	0
TRANSMISSION ENGAGE	7	PROPER ENGAGE	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0

IMAGES




WHEEL

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7	GOOD TREAD	0
SPARE TYRE (YES)	7	GOOD CONDITION	0
WHEEL ASSEMBLY (STEEL RIM)	7	GOOD CONDITION	0

 IMAGES




 HOOD



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7	GOOD CONDITION	0
RH APRON	7	GOOD CONDITION	0
RADIATOR	7	GOOD CONDITION	0
WIRING	7	GOOD CONDITION	0
BATTERY	7	FULLY CHARGE	0
BRAKE FLUID LEVEL	7	MAX LEVEL	0
ENGINE OIL	7	MAX LEVEL	0
COOLANT LEVEL	7	MAX LEVEL	0
BRAKE & COOLANT HOSE PIPES	7	GOOD CONDITION	0
UNDERCARRIAGE	7	NO RUSTY	0
EXHAUST SYSTEM	7	NO SMOKE	0

 IMAGES



Ordered by: JALIL | Inspected date: 2019-04-22

Order Id: 64797

Overall Score  **7/10**



4,77,710

 **EXTERIOR**

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7	GOOD CONDITION	0
FRONT BUMPER	7	SCRATCH ON IT	0
HEAD LIGHTS	7	GOOD CONDITION	0
GRILLE	7	GOOD CONDITION	0
TURN SIGNAL	7	WORKING	0
HOOD	7	GOOD CONDITION	0
PILLAR	7	GOOD CONDITION	0
FRONT WINDSHIELD	7	GOOD VISIBILITY	0
SIDE VIEW MIRRORS	7	GOOD CONDITION	0
LH FENDER	7	GOOD CONDITION	0
LH FRONT DOOR	7	GOOD CONDITION	0
LH REAR DOOR	6	SCRATCH ON IT	800
LH RUNNING BOARD	7	GOOD CONDITION	0
LH QUARTER PANEL	6	SCRATCH ON IT	0
FUEL LID	7	GOOD CONDITION	0
REAR WINDSHIELD	7	GOOD VISIBILITY	0
REAR BUMPER	7	SCRATCH ON IT	0
TAIL LIGHT	7	GOOD CONDITION	0
TRUNK LID/TAIL GATE	7	GOOD CONDITION	0
RH QUARTER PANEL	7	GOOD CONDITION	0
RH RUNNING BOARD	6	DAMAGED	0
RH REAR DOOR	7	GOOD CONDITION	0
RH FRONT DOOR	7	GOOD CONDITION	0
RH FENDER	7	GOOD CONDITION	0

Ordered by: JALIL | Inspected date: 2019-04-22

Order Id: 64797

Overall Score **7/10**



4,77,710

EXTERIOR (CONTINUED)

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
BODY RUST	7	NO BODY RUST	0
ROOF (REGULAR)	7	GOOD CONDITION	0
PAINT CONDITION	7	GOOD CONDITION	0
FOG LAMPS	5	NOT AVAILABLE	0
LUGGAGE COMPARTMENT LIGHT	5	NO SPACE	0

IMAGES






NEED ATTENTION



DOCUMENTS



DESCRIPTION

Good condition

Ordered by: JALIL | Inspected date: 2019-04-22

Order Id: 64797

Overall Score





7/10



4,77,710

IMAGES





Ordered by: JALIL | Inspected date: 2019-04-22

Order Id: 64797

Overall Score



7/10



4,77,710

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.