


ECO INSPECTION CERTIFICATE

Premium

Order ID : 65813

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Gurpreet .	Inspection Date : 2019-04-25	Location : KHARAR	Inspected By  GAGAN GUPTA
Overall Score: 7/10			Verified Technician 179+ vehicle inspected 1+ years experience

- Evaluated across 5 segments
- Covered 121+ checkpoints
- 121 does not need attention
- 1 Owner , 11 Years Vehicle Age
- No Accidental History










Hyundai Accent Executive, 2008



VEHICLE INFORMATION

MAKE	HYUNDAI	ENGINE NUMBER	203137
MODEL	ACCENT	REGISTRATION NO.	PB11AJ6033
MFG. DATE	0000-00-00	VIN/CHASSIS NUMBER	202824
TRIM	EXECUTIVE	ODOMETER READING	93516
COLOR	WHITE	INSURANCE EXPIRY	2019-5-11
BODY TYPE	SEDAN	VEHICLE PASSING	PRIVATE
FUEL TYPE	DIESEL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	5,000	 RC COPY AVAILABLE	ORIGINAL	 BANK HYPOTHECATION	NO
 DENT	NO	 INSURANCE COPY AVAILABLE	NO	 BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

1,36,658




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

 Interior	<div style="width: 70%;"></div>	7 / 10
 Wheel	<div style="width: 70%;"></div>	7 / 10
 Test Drive	<div style="width: 80%;"></div>	8 / 10
 Exterior	<div style="width: 70%;"></div>	7 / 10
 Hood	<div style="width: 70%;"></div>	7 / 10

TOTAL ESTIMATE SPEND 0



Ordered by: Gurpreet . | Inspected date: 2019-04-25

Order Id: 65813

Overall Score **7/10**



1,36,658

INTERIOR

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7	GOOD	0
DOOR HINGES	7	OK	0
CARPET & FLOOR MAT	7	GOOD	0
SEAT & SEAT BELT	7	SAFE	0
DASHBOARD & INSTRUMENT PANEL	7	OK	0
HORN	7	OK	0
SPEAKERS & MUSIC SYSTEM	7	WORKING	0
HANDBRAKE	7	SAFE	0
STEERING-MOUNTED CONTROLS	8	GOOD	0
PEDALS	7	SAFE	0
CENTRAL LOCK	6	OK	0
A/C VENTS & HEATER	7	WORKING	0
CUP HOLDERS	6	OK	0
NAVIGATION (NO)	10		0
ODOMETER	7	OK	0
POWER WINDOWS (YES - FRONT ONLY)	7	OK	0
HAZARD LIGHT	6	OK	0

IMAGES



Ordered by: Gurpreet . | Inspected date: 2019-04-25

Order Id: 65813

Overall Score **7/10**




1,36,658

TEST DRIVE

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7	GOOD	0
BRAKE PERFORMANCE	7	SAFE	0
CLUTCH PERFORMANCE	7	GOOD	0
ENGINE NOISE	7	LESS NOISE	0
IGNITION SYSTEM	7	SMOOTH	0
SUSPENSION PERFORMANCE	7	OKK	0
SUSPENSION FRONT SHOCKS	7	GOOD	0
SUSPENSION REAR SHOCKS	7	OK	0
TRANSMISSION ENGAGE	7	GOOD	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0

IMAGES




WHEEL

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7	GOOD	0
SPARE TYRE (YES)	6	OK	0
WHEEL ASSEMBLY (STEEL RIM)	7	GOOD	0

 IMAGES




 HOOD




7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7	GOOD	0
RH APRON	7	GOOD	0
RADIATOR	7	GOOD	0
WIRING	8	WORKING	0
BATTERY	8	GOOD	0
BRAKE FLUID LEVEL	8	ABOVE AVRAGE	0
ENGINE OIL	7	GOOD	0
COOLANT LEVEL	7	SAFE	0
BRAKE & COOLANT HOSE PIPES	7	GOOD	0
UNDERCARRIAGE	6	OK	0
EXHAUST SYSTEM	7	OK	0

 IMAGES





Ordered by: Gurpreet . | Inspected date: 2019-04-25

Order Id: 65813

Overall Score  **7/10**



1,36,658

 **EXTERIOR**

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7	GOOD	0
FRONT BUMPER	7	OK	0
HEAD LIGHTS	8	WORKING	0
GRILLE	7	GOOD	0
TURN SIGNAL	7	OK	0
FOG LAMPS	7	GOOD	0
HOOD	7	GOOD	0
PILLAR	7	SAFE	0
FRONT WINDSHIELD	7	NO SCRATCHES	0
SIDE VIEW MIRRORS	7	FINE	0
LH FENDER	7	OK	0
LH FRONT DOOR	7	SAFE	0
LH REAR DOOR	7	OK	0
LH RUNNING BOARD	7	OK	0
LH QUARTER PANEL	7	OK	0
FUEL LID	7	GOOD	0
REAR WINDSHIELD	7	NO SCRATCHES	0
REAR BUMPER	6	SOME SCRATCHE	0
TAIL LIGHT	7	WORKING	0
TRUNK LID/TAIL GATE	7	OKK	0
LUGGAGE COMPARTMENT LIGHT	7	BETTER	0
RH QUARTER PANEL	7	GOOD	0
RH RUNNING BOARD	7	OK	0
RH REAR DOOR	6	OK	0

Ordered by: Gurpreet . | Inspected date: 2019-04-25

Order Id: 65813

Overall Score **7/10**



1,36,658



EXTERIOR (CONTINUED)

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	7	OK	0
RH FENDER	7	GOOD	0
BODY RUST	7	NO RUST	0
ROOF (REGULAR)	7	OK	0
PAINT CONDITION	7	OK	0

IMAGES





DESCRIPTION

good

Ordered by: Gurpreet . | Inspected date: 2019-04-25

Order Id: 65813

Overall Score













7/10



1,36,658

IMAGES





Ordered by: Gurpreet . | Inspected date: 2019-04-25

Order Id: 65813

Overall Score



7/10



1,36,658

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.