


# ECO INSPECTION CERTIFICATE

Premium

Order ID : 58114

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Harshit	Inspection Date : 2019-04-15	Location : SAMA	Inspected By  Sagar Pawar
-------------------------	---------------------------------	--------------------	--------------------------------------------------------------------------------------------------------------------

## 7/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 114 does not need attention
- ✓ 1 Owner , 8 Years Vehicle Age
- ✓ No Accidental History

✓ **Verified Technician**  
24+ vehicle inspected  
1+ years experience

## Tata Safari 4X2 VX DICOR BS IV, 2011



VEHICLE INFORMATION			
MAKE	TATA	ENGINE NUMBER	J18554
MODEL	SAFARI	REGISTRATION NO.	GJ06DQ8573
MFG. DATE	0000-00-00	VIN/CHASSIS NUMBER	YJ10513
TRIM	4X2 VX DICOR BS IV	ODOMETER READING	78505
COLOR	WHITE	INSURANCE EXPIRY	2019-10-10
BODY TYPE	SEDAN	VEHICLE PASSING	
FUEL TYPE	PETROL	ENGINE SOUND LINK	<a href="#">LISTEN ENGINE SOUND</a>

KEY HIGHLIGHTS			
FLOOD DAMAGE	YES	MAJOR ACCIDENT(S)	NO
TYRE LIFE REMAINING (KM)	10,000	RC COPY AVAILABLE	YES (ORIGINAL)
DENT	YES	INSURANCE COPY AVAILABLE	NO (3RD PARTY)
		SERVICE LOGS AVAILABLE	NO
		BANK HYPOTHECATION	NO
		BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

## 3,85,311




Very Good Condition

## ECO SCORE & REPAIR COST ESTIMATE

### ECO SCORE

Interior	<div style="width: 70%;"></div>	7 / 10
Wheel	<div style="width: 70%;"></div>	7 / 10
Test Drive	<div style="width: 80%;"></div>	8 / 10
Exterior	<div style="width: 60%;"></div>	6 / 10
Hood	<div style="width: 80%;"></div>	8 / 10

### TOTAL ESTIMATE SPEND 57,000



Ordered by: Harshit | Inspected date: 2019-04-15

Order Id: 58114

Overall Score



7/10



3,85,311



## INTERIOR





7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7		0
DOOR HINGES	7		0
CARPET & FLOOR MAT	7		0
SEAT & SEAT BELT	8		0
DASHBOARD & INSTRUMENT PANEL	7		0
HORN	7		0
SPEAKERS & MUSIC SYSTEM	7		0
HANDBRAKE	7		0
STEERING-MOUNTED CONTROLS	6	NO	5000
PEDALS	7		0
CENTRAL LOCK	7		0
A/C VENTS & HEATER	7		0
CUP HOLDERS	7		0
NAVIGATION (YES)	7		0
ODOMETER	7		0
POWER WINDOWS (YES - FRONT ONLY)	7		0
HAZARD LIGHT	7		0



## IMAGES



Ordered by: Harshit | Inspected date: 2019-04-15

Order Id: 58114

Overall Score  **7/10**




**3,85,311**

## TEST DRIVE

**8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7		0
BRAKE PERFORMANCE	7		0
CLUTCH PERFORMANCE	7		0
ENGINE NOISE	7		0
IGNITION SYSTEM	7		0
SUSPENSION PERFORMANCE	7		0
SUSPENSION FRONT SHOCKS	7		0
SUSPENSION REAR SHOCKS	7		0
TRANSMISSION ENGAGE	8		0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0

## IMAGES



## WHEEL

**7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7		0
SPARE TYRE (YES)	7		0
WHEEL ASSEMBLY (ALLOY RIM)	7		0

 IMAGES



 HOOD



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7		0
RH APRON	7		0
RADIATOR	8		0
WIRING	9		0
BATTERY	8		0
BRAKE FLUID LEVEL	8		0
ENGINE OIL	9		0
COOLANT LEVEL	9		0
BRAKE & COOLANT HOSE PIPES	10		0
UNDERCARRIAGE	9		0
EXHAUST SYSTEM	8		0

 IMAGES





Ordered by: Harshit | Inspected date: 2019-04-15

Order Id: 58114

Overall Score  **7/10**



**3,85,311**

 **EXTERIOR**

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
GRILLE	7		0
TURN SIGNAL	7		0
FOG LAMPS	7		0
HOOD	7		0
PILLAR	7		0
FRONT WINDSHIELD	7		0
SIDE VIEW MIRRORS	7		0
LH RUNNING BOARD	6	NORMAL SCRTCH	3000
LH QUARTER PANEL	6	SCRTCH	3000
FUEL LID	7		0
REAR WINDSHIELD	7		0
REAR BUMPER	7		0
TAIL LIGHT	7	TAIL.LAMP BROKEN	5000
LUGGAGE COMPARTMENT LIGHT	7		0
RH QUARTER PANEL	7	DENTED	4000
RH RUNNING BOARD	7		0
RH REAR DOOR	7	SCRTCH	3000
RH FRONT DOOR	6	SCRTCHE	2000
RH FENDER	6	DENTED AND SCRTCH	3000
BODY RUST	6	SCRTCH	0
ROOF (REGULAR)	7		0
PAINT CONDITION	7		0
LICENSE PLATE	2	NORMAL	1000
FRONT BUMPER	5	SCRTCH AND COLOR DEMEGIS	3000

Ordered by: Harshit | Inspected date: 2019-04-15

Order Id: 58114

Overall Score



7/10



3,85,311



## EXTERIOR (CONTINUED)





6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
HEAD LIGHTS	5	HED LIGHT GLASS DALL	5000
LH FENDER	4	SCRATCH	5000
LH FRONT DOOR	5	SCRATCH	2000
LH REAR DOOR	5	SCRATCH	3000
TRUNK LID/TAIL GATE	5	NOT WORKING	10000






## IMAGES







**NEED ATTENTION**



**DOCUMENTS**



**DESCRIPTION**

some body part and scrch and dented



Ordered by: Harshit | Inspected date: 2019-04-15

Order Id: 58114

Overall Score














7/10



3,85,311

IMAGES





Ordered by: Harshit | Inspected date: 2019-04-15

Order Id: 58114

Overall Score



7/10



3,85,311

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.