



ECO INSPECTION CERTIFICATE

Premium

Order ID : 58024

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : V M VENKATAREDDY	Inspection Date : 2019-04-30	Location : BANGALORE	 Inspected By  Abhishek By
----------------------------------	---------------------------------	-------------------------	--

8/10

Overall Score

- ✔ Evaluated across **5** segments
- ✔ Covered **121+** checkpoints
- ✔ **121** does not need attention
- ✔ **1** Owner , **6** Years Vehicle Age
- ✔ No Accidental History










✔ **Verified Technician**

151+ vehicle inspected
1+ years experience

Chevrolet Beat Lt Diesel, 2013



VEHICLE INFORMATION			
MAKE	CHEVROLET	ENGINE NUMBER	10FCDZ1303
MODEL	BEAT	REGISTRATION NO.	KA13N3285
MFG. DATE	0000-00-00	VIN/CHASSIS NUMBER	MA6BFBBNDCT056434
TRIM	LT DIESEL	ODOMETER READING	67169
COLOR	S GREY	INSURANCE EXPIRY	2019-6-21
BODY TYPE	SEDAN	VEHICLE PASSING	PRIVATE
FUEL TYPE	DIESEL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS			
 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO
 TYRE LIFE REMAINING (KM)	15,000	 RC COPY AVAILABLE	ORIGINAL
 DENT	NO	 INSURANCE COPY AVAILABLE	YES (COMPREHENSIVE)
		 SERVICE LOGS AVAILABLE	NO
		 BANK HYPOTHECATION	NO
		 BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.
With this evaluation, the Fair Market Price for this vehicle comes to be:






2,68,301




Very Good Condition


ECO SCORE & REPAIR COST ESTIMATE


ECO SCORE


 Interior	<div style="width: 80%; height: 10px; background: linear-gradient(to right, green, grey);"></div>	8 / 10
 Wheel	<div style="width: 80%; height: 10px; background: linear-gradient(to right, green, grey);"></div>	8 / 10
 Test Drive	<div style="width: 80%; height: 10px; background: linear-gradient(to right, green, grey);"></div>	8 / 10
 Exterior	<div style="width: 80%; height: 10px; background: linear-gradient(to right, green, grey);"></div>	8 / 10
 Hood	<div style="width: 80%; height: 10px; background: linear-gradient(to right, green, grey);"></div>	8 / 10


TOTAL ESTIMATE SPEND 0

0


0


0


0


0


Ordered by: V M VENKATAREDDY | Inspected date: 2019-04-30

Order Id: 58024

Overall Score **8/10**



2,68,301

INTERIOR

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	8		0
DOOR HINGES	8		0
CARPET & FLOOR MAT	7		0
SEAT & SEAT BELT	7		0
DASHBOARD & INSTRUMENT PANEL	8		0
HORN	8		0
SPEAKERS & MUSIC SYSTEM	7		0
HANDBRAKE	7		0
STEERING-MOUNTED CONTROLS	7		0
PEDALS	8		0
CENTRAL LOCK	8		0
A/C VENTS & HEATER	7		0
CUP HOLDERS	8		0
NAVIGATION (NO)	10		0
ODOMETER	8		0
POWER WINDOWS (YES)	8		0
HAZARD LIGHT	8		0

IMAGES





TEST DRIVE




8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7		0
BRAKE PERFORMANCE	7		0
CLUTCH PERFORMANCE	8		0
ENGINE NOISE	7		0
IGNITION SYSTEM	7		0
SUSPENSION PERFORMANCE	8		0
SUSPENSION FRONT SHOCKS	8		0
SUSPENSION REAR SHOCKS	8		0
TRANSMISSION ENGAGE	7		0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0



IMAGES



WHEEL



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7		0
SPARE TYRE (YES)	8		0
WHEEL ASSEMBLY (STEEL RIM)	8		0

 IMAGES



 HOOD



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	8		0
RH APRON	8		0
RADIATOR	8		0
WIRING	8		0
BATTERY	8		0
BRAKE FLUID LEVEL	8		0
ENGINE OIL	6		0
COOLANT LEVEL	7		0
BRAKE & COOLANT HOSE PIPES	8		0
UNDERCARRIAGE	8		0
EXHAUST SYSTEM	7		0

 IMAGES



Ordered by: V M VENKATAREDDY | Inspected date: 2019-04-30

Order Id: 58024

Overall Score



8/10



2,68,301



EXTERIOR



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7		0
FRONT BUMPER	8		0
HEAD LIGHTS	8		0
GRILLE	8		0
TURN SIGNAL	7		0
FOG LAMPS	8		0
HOOD	8		0
PILLAR	8		0
FRONT WINDSHIELD	8		0
SIDE VIEW MIRRORS	8		0
LH FENDER	8		0
LH FRONT DOOR	8		0
LH REAR DOOR	8		0
LH RUNNING BOARD	8		0
LH QUARTER PANEL	8		0
FUEL LID	8		0
REAR WINDSHIELD	8		0
REAR BUMPER	6		0
TAIL LIGHT	8		0
TRUNK LID/TAIL GATE	8		0
LUGGAGE COMPARTMENT LIGHT	8		0
RH QUARTER PANEL	8		0
RH RUNNING BOARD	7		0
RH REAR DOOR	8		0

Ordered by: V M VENKATAREDDY | Inspected date: 2019-04-30

Order Id: 58024

Overall Score



8/10



2,68,301



EXTERIOR (CONTINUED)



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	7		0
RH FENDER	8		0
BODY RUST	8		0
ROOF (REGULAR)	8		0
PAINT CONDITION	8		0





IMAGES





 DOCUMENTS



 DESCRIPTION

good condition

Ordered by: V M VENKATAREDDY | Inspected date: 2019-04-30

Order Id: 58024

Overall Score



8/10



2,68,301

IMAGES



Ordered by: V M VENKATAREDDY | Inspected date: 2019-04-30

Order Id: 58024

Overall Score



8/10



2,68,301

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.