

ECO INSPECTION CERTIFICATE

Premium

Order ID : 68554

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.


Ordered By : Sachin	Inspection Date : 2019-05-01	Location : GHAZIABAD
------------------------	---------------------------------	-------------------------

6/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 113 does not need attention
- ✓ 1 Owner , 9 Years Vehicle Age
- ✓ No Accidental History

Inspected By



✓ **Verified Technician**

253+ vehicle inspected

1+ years experience

Kishan Kumar

Chevrolet Spark LS 1.0, 2010



VEHICLE INFORMATION

MAKE	CHEVROLET	ENGINE NUMBER	73KC2
MODEL	SPARK	REGISTRATION NO.	UP14BC1579
MFG. DATE	0000-00-00	VIN/CHASSIS NUMBER	49075
TRIM	LS 1.0	ODOMETER READING	69519
COLOR	LINE BEIGE	INSURANCE EXPIRY	2019-6-30
BODY TYPE	HATCHBACK	VEHICLE PASSING	PRIVATE
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	10,000	RC COPY AVAILABLE	ORIGINAL	BANK HYPOTHECATION	NO
DENT	YES	INSURANCE COPY AVAILABLE	YES (COMPREHENSIVE)	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

1,11,058




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 60%;"></div>	6 / 10
Wheel	<div style="width: 60%;"></div>	6 / 10
Test Drive	<div style="width: 50%;"></div>	5 / 10
Exterior	<div style="width: 60%;"></div>	6 / 10
Hood	<div style="width: 70%;"></div>	7 / 10

TOTAL ESTIMATE SPEND 3,900



Ordered by: Sachin | Inspected date: 2019-05-01

Order Id: 68554

Overall Score



6/10



1,11,058



INTERIOR





6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7		0
DOOR HINGES	7		0
CARPET & FLOOR MAT	7		0
SEAT & SEAT BELT	7		0
DASHBOARD & INSTRUMENT PANEL	7		0
HORN	7		0
SPEAKERS & MUSIC SYSTEM	7		0
HANDBRAKE	7		0
PEDALS	7		0
CENTRAL LOCK	7		0
A/C VENTS & HEATER	7		0
CUP HOLDERS	7		0
ODOMETER	7		0
POWER WINDOWS (YES - FRONT ONLY)	7		0
HAZARD LIGHT	7		0
STEERING-MOUNTED CONTROLS	0	NA	0
NAVIGATION (YES)	0	NA	0



IMAGES



Ordered by: Sachin | Inspected date: 2019-05-01

Order Id: 68554

Overall Score **6/10**



1,11,058

TEST DRIVE

5/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7		0
BRAKE PERFORMANCE	7		0
CLUTCH PERFORMANCE	6	AVERAGE CONDITION	0
ENGINE NOISE	6	AVERAGE CONDITION	0
IGNITION SYSTEM	7		0
SUSPENSION PERFORMANCE	6	AVERAGE CONDITION	0
SUSPENSION FRONT SHOCKS	6	AVERAGE CONDITION	0
SUSPENSION REAR SHOCKS	6	AVERAGE CONDITION	0
TRANSMISSION ENGAGE	7		0
CRUISE CONTROL (YES)	0	NA	0
REAR PARKING SENSORS (YES)	0	NA	0
REAR VIEW CAMERA (YES)	0	NA	0

IMAGES



WHEEL

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	6	AVERAGE CONDITION	0
SPARE TYRE (YES)	6	AVERAGE CONDITION	0
WHEEL ASSEMBLY (STEEL RIM)	6	AVERAGE CONDITION	0

 IMAGES




 HOOD



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7		0
RH APRON	7		0
RADIATOR	6	AVERAGE CONDITION	0
WIRING	6	AVERAGE CONDITION	0
BATTERY	7		0
BRAKE FLUID LEVEL	7		0
ENGINE OIL	7		0
COOLANT LEVEL	7		0
BRAKE & COOLANT HOSE PIPES	6	AVERAGE CONDITION	0
UNDERCARRIAGE	6	AVERAGE CONDITION	0
EXHAUST SYSTEM	7		0

 IMAGES



Ordered by: Sachin | Inspected date: 2019-05-01

Order Id: 68554

Overall Score



6/10



1,11,058

 EXTERIOR



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7		0
FRONT BUMPER	6	SCRATCHES	1000
HEAD LIGHTS	7		0
GRILLE	7		0
TURN SIGNAL	7		0
HOOD	6	AVERAGE CONDITION	0
PILLAR	6	AVERAGE CONDITION	0
FRONT WINDSHIELD	6	AVERAGE CONDITION	0
SIDE VIEW MIRRORS	6	AVERAGE CONDITION	0
LH FENDER	6	SCRATCHES	250
LH FRONT DOOR	6	SCRATCHES	200
LH REAR DOOR	6	SCRATCHES	250
LH QUARTER PANEL	6	SCRATCHES	150
FUEL LID	6	AVERAGE CONDITION	0
REAR WINDSHIELD	6	AVERAGE CONDITION	0
REAR BUMPER	6	SCRATCHES	500
TAIL LIGHT	7		0
TRUNK LID/TAIL GATE	6	AVERAGE CONDITION	0
LUGGAGE COMPARTMENT LIGHT	7		0
RH QUARTER PANEL	6	SCRATCHES	100
RH RUNNING BOARD	6	SCRATCHES	100
RH REAR DOOR	6	SCRATCHES	200
RH FRONT DOOR	6	SCRATCHES	150
BODY RUST	6	AVERAGE CONDITION	0

Ordered by: Sachin | Inspected date: 2019-05-01

Order Id: 68554

Overall Score **6/10**



1,11,058





EXTERIOR (CONTINUED)

6/10


INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
ROOF (REGULAR)	7		0
PAINT CONDITION	6	AVERAGE CONDITION	0
FOG LAMPS	0	NA	0
LH RUNNING BOARD	5	DENT AND SCRATCHES NEED TO BE REPAIR	500
RH FENDER	5	DENT AND SCRATCHES NEED TO BE REAPIR	500

IMAGES







 **NEED ATTENTION** 



 **DOCUMENTS**



 **DESCRIPTION**

all body scratches minor dent need to be repair

Ordered by: Sachin | Inspected date: 2019-05-01

Order Id: 68554

Overall Score




6/10



1,11,058

IMAGES





Ordered by: Sachin | Inspected date: 2019-05-01

Order Id: 68554

Overall Score



6/10



1,11,058

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.