

# ECO INSPECTION CERTIFICATE

Premium

Order ID : 69856

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.


Ordered By : Kritika	Inspection Date : 2019-05-06	Location : GHAZIABAD
-------------------------	---------------------------------	-------------------------

## 5/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 111 does not need attention
- ✓ 2 Owners , 10 Years Vehicle Age
- ✓ No Accidental History

**Inspected By**



✓ **Verified Technician**  
262+ vehicle inspected  
1+ years experience

Kishan Kumar

## Maruti Suzuki Wagon R LXI, 2009



### VEHICLE INFORMATION

MAKE	MARUTI SUZUKI	ENGINE NUMBER	81330
MODEL	WAGON R	REGISTRATION NO.	UP14A7170
MFG. DATE	2009-01-01	VIN/CHASSIS NUMBER	56660
TRIM	LXI	ODOMETER READING	74033
COLOR	ROYAL GOLD	INSURANCE EXPIRY	2020-5-13
BODY TYPE	HATCHBACK	VEHICLE PASSING	PRIVATE
FUEL TYPE	PETROL	ENGINE SOUND LINK	<a href="#">LISTEN ENGINE SOUND</a>

### KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	15,000	RC COPY AVAILABLE	ORIGINAL	BANK HYPOTHECATION	NO
DENT	YES	INSURANCE COPY AVAILABLE	YES (COMPREHENSIVE)	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

**1,25,812**




### ECO SCORE & REPAIR COST ESTIMATE

#### ECO SCORE

Interior	<div style="width: 50%;"></div>	5 / 10
Wheel	<div style="width: 70%;"></div>	7 / 10
Test Drive	<div style="width: 50%;"></div>	5 / 10
Exterior	<div style="width: 60%;"></div>	6 / 10
Hood	<div style="width: 60%;"></div>	6 / 10

#### TOTAL ESTIMATE SPEND 2,450



Ordered by: Kritika | Inspected date: 2019-05-06

Order Id: 69856

Overall Score



5/10



1,25,812



## INTERIOR



5/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7		0
DOOR HINGES	7		0
CARPET & FLOOR MAT	7		0
SEAT & SEAT BELT	7		0
DASHBOARD & INSTRUMENT PANEL	7		0
HORN	7		0
SPEAKERS & MUSIC SYSTEM	7		0
HANDBRAKE	7		0
PEDALS	7		0
A/C VENTS & HEATER	7		0
CUP HOLDERS	7		0
ODOMETER	7		0
HAZARD LIGHT	7		0
STEERING-MOUNTED CONTROLS	0	NA	0
CENTRAL LOCK	0	NA	0
NAVIGATION (YES)	0	NA	0
POWER WINDOWS (YES)	0	NA	0



## IMAGES



Ordered by: Kritika | Inspected date: 2019-05-06

Order Id: 69856

Overall Score **5/10**




**1,25,812**

## TEST DRIVE

**5/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7		0
BRAKE PERFORMANCE	7		0
CLUTCH PERFORMANCE	7		0
ENGINE NOISE	6	AVERAGE CONDITION	0
IGNITION SYSTEM	7		0
SUSPENSION PERFORMANCE	6	AVERAGE CONDITION	0
SUSPENSION FRONT SHOCKS	6	AVERAGE CONDITION	0
SUSPENSION REAR SHOCKS	7		0
TRANSMISSION ENGAGE	7		0
CRUISE CONTROL (YES)	0	NA	0
REAR PARKING SENSORS (YES)	0	NA	0
REAR VIEW CAMERA (YES)	0	NA	0

## IMAGES




## WHEEL

**7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7		0
SPARE TYRE (YES)	7		0
WHEEL ASSEMBLY (STEEL RIM)	6	AVERAGE CONDITION	0

 IMAGES




 HOOD



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	6	AVERAGE CONDITION	0
RH APRON	6	AVERAGE CONDITION	0
RADIATOR	6	AVERAGE CONDITION	0
WIRING	6	AVERAGE CONDITION	0
BATTERY	7		0
BRAKE FLUID LEVEL	7		0
ENGINE OIL	7		0
COOLANT LEVEL	7		0
BRAKE & COOLANT HOSE PIPES	6	AVERAGE CONDITION	0
UNDERCARRIAGE	6	AVERAGE CONDITION	0
EXHAUST SYSTEM	6	AVERAGE CONDITION	0

 IMAGES



Ordered by: Kritika | Inspected date: 2019-05-06

Order Id: 69856

Overall Score  **5/10**



**1,25,812**

 **EXTERIOR**

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	6	AVERAGE CONDITION	0
FRONT BUMPER	6	SCRATCHES	400
HEAD LIGHTS	7		0
GRILLE	7		0
TURN SIGNAL	7		0
HOOD	6	AVERAGE CONDITION	0
PILLAR	6	AVERAGE CONDITION	0
FRONT WINDSHIELD	6	SCRATCHES	150
SIDE VIEW MIRRORS	6	AVERAGE CONDITION	0
LH FENDER	6	SCRATCHES	100
LH FRONT DOOR	6	SCRATCHES	200
LH REAR DOOR	6	SCRATCHES	200
LH RUNNING BOARD	7		0
LH QUARTER PANEL	6	SCRATCHES	100
FUEL LID	6	AVERAGE CONDITION	0
REAR WINDSHIELD	7		0
REAR BUMPER	6	SCRATCHES	350
TAIL LIGHT	7		0
TRUNK LID/TAIL GATE	6	AVERAGE CONDITION	0
LUGGAGE COMPARTMENT LIGHT	7		0
RH QUARTER PANEL	6	SCRATCHES	100
RH RUNNING BOARD	7		0
RH FRONT DOOR	6	SCRATCHES	100
BODY RUST	6	AVERAGE CONDITION	0



Ordered by: Kritika | Inspected date: 2019-05-06

Order Id: 69856

Overall Score



5/10



1,25,812



## EXTERIOR (CONTINUED)



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
ROOF (REGULAR)	6	AVERAGE CONDITION	0
PAINT CONDITION	6	AVERAGE CONDITION	0
FOG LAMPS	0	NA	0
RH REAR DOOR	5	SCRATCHES	500
RH FENDER	5	SCRATCHES AND DENT NEED TO BE REPAIR	250




## IMAGES







NEED ATTENTION



DOCUMENTS



DESCRIPTION

all body scratches and dent need to be repair



Ordered by: Kritika | Inspected date: 2019-05-06

Order Id: 69856

Overall Score




5/10





1,25,812

IMAGES







Ordered by: Kritika | Inspected date: 2019-05-06

Order Id: 69856

Overall Score



5/10



1,25,812

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.