


ECO INSPECTION CERTIFICATE

Premium

Order ID : 65282

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Ritesh	Inspection Date : 2019-05-07	Location : CHHANI	Inspected By  Sagar Pawar
------------------------	---------------------------------	----------------------	--

8/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 118 does not need attention
- ✓ 1 Owner , 9 Years Vehicle Age
- ✓ No Accidental History

- ✓ **Verified Technician**
- 26+ vehicle inspected
- 1+ years experience

Tata Indica Vista AQUA QUADRAJET BS-III, 2010



VEHICLE INFORMATION

MAKE	TATA	ENGINE NUMBER	117657
MODEL	INDICA VISTA	REGISTRATION NO.	GJ06ED2388
MFG. DATE	2008-01-01	VIN/CHASSIS NUMBER	PK83303
TRIM	AQUA QUADRAJET BS-III	ODOMETER READING	77441
COLOR	SILVER	INSURANCE EXPIRY	2018-6-6
BODY TYPE	HATCHBACK	VEHICLE PASSING	PRIVATE
FUEL TYPE	DIESEL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	10,000	RC COPY AVAILABLE	ORIGINAL	BANK HYPOTHECATION	NO
DENT	NO	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

1,53,904




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 80%;"></div>	8 / 10
Wheel	<div style="width: 80%;"></div>	8 / 10
Test Drive	<div style="width: 90%;"></div>	9 / 10
Exterior	<div style="width: 70%;"></div>	7 / 10
Hood	<div style="width: 80%;"></div>	8 / 10

TOTAL ESTIMATE SPEND 33,000



Ordered by: Ritesh | Inspected date: 2019-05-07

Order Id: 65282

Overall Score



8/10



1,53,904



INTERIOR



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7		0
DOOR HINGES	7		0
CARPET & FLOOR MAT	8		0
SEAT & SEAT BELT	8		0
DASHBOARD & INSTRUMENT PANEL	8		0
HORN	8		0
SPEAKERS & MUSIC SYSTEM	8		0
HANDBRAKE	8		0
STEERING-MOUNTED CONTROLS	8		0
PEDALS	8		0
CENTRAL LOCK	8		0
A/C VENTS & HEATER	8		0
CUP HOLDERS	8		0
NAVIGATION (NO)	10		0
ODOMETER	9		0
POWER WINDOWS (YES)	7		0
HAZARD LIGHT	7		0



IMAGES



Ordered by: Ritesh | Inspected date: 2019-05-07

Order Id: 65282

Overall Score **8/10**



1,53,904

TEST DRIVE

9/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	8		0
BRAKE PERFORMANCE	8		0
CLUTCH PERFORMANCE	8		0
ENGINE NOISE	8		0
IGNITION SYSTEM	8		0
SUSPENSION PERFORMANCE	8		0
SUSPENSION FRONT SHOCKS	8		0
SUSPENSION REAR SHOCKS	9		0
TRANSMISSION ENGAGE	8		0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0

IMAGES




WHEEL

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	8		0
SPARE TYRE (YES)	8		0
WHEEL ASSEMBLY (STEEL RIM)	7		0

 IMAGES




 HOOD

 8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	8		0
RH APRON	7		0
RADIATOR	7		0
WIRING	7		0
BATTERY	8		0
BRAKE FLUID LEVEL	8		0
ENGINE OIL	8		0
COOLANT LEVEL	8		0
BRAKE & COOLANT HOSE PIPES	8		0
UNDERCARRIAGE	8		0
EXHAUST SYSTEM	8		0

 IMAGES





Ordered by: Ritesh | Inspected date: 2019-05-07

Order Id: 65282

Overall Score



8/10



1,53,904



EXTERIOR



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	8		0
HEAD LIGHTS	7		0
GRILLE	7		0
TURN SIGNAL	7		0
HOOD	7		0
PILLAR	8		0
FRONT WINDSHIELD	8		0
SIDE VIEW MIRRORS	8		0
LH FENDER	8		0
LH FRONT DOOR	7		0
LH REAR DOOR	8	DENTED	3000
LH RUNNING BOARD	7		0
LH QUARTER PANEL	8		0
FUEL LID	8		0
REAR WINDSHIELD	8		0
REAR BUMPER	8	SCRATCH	3000
TAIL LIGHT	7		0
TRUNK LID/TAIL GATE	7		0
LUGGAGE COMPARTMENT LIGHT	9		0
RH QUARTER PANEL	8	SCRATCH	2000
RH RUNNING BOARD	7		0
RH REAR DOOR	8		0
RH FENDER	8		0
BODY RUST	8		0

Ordered by: Ritesh | Inspected date: 2019-05-07

Order Id: 65282

Overall Score



8/10



1,53,904



EXTERIOR (CONTINUED)




7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
ROOF (REGULAR)	8		0
PAINT CONDITION	8	DENTED AND SCRTCH	15000
FRONT BUMPER	5	SCRATCH	2000
FOG LAMPS	3	NOT WORKING	5000
RH FRONT DOOR	4	DENTED AND SCRTCH	3000




IMAGES





NEED ATTENTION



DOCUMENTS



DESCRIPTION

some body parys

Ordered by: Ritesh | Inspected date: 2019-05-07

Order Id: 65282

Overall Score







8/10



1,53,904

IMAGES





Ordered by: Ritesh | Inspected date: 2019-05-07

Order Id: 65282

Overall Score



8/10



1,53,904

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.