

ECO INSPECTION CERTIFICATE

Premium

Order ID : 70194

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Prashanth	Inspection Date : 2019-05-07	Location : PUNE	Inspected By Hrutvij Patil ✓ Verified Technician 33+ vehicle inspected 1+ years experience
7/10 Overall Score		✓ Evaluated across 6 segments ✓ Covered 121+ checkpoints ✓ 121 does not need attention ✓ 1 Owner , 2 Years Vehicle Age ✓ No Accidental History	

Um Renegade Commando 280CC, 2017



VEHICLE INFORMATION

MAKE	UM	ENGINE NUMBER	
MODEL	RENEGADE COMMANDO	REGISTRATION NO.	MH12PJ0087
YEAR	2017	VIN/CHASSIS NUMBER	MDCM3RBG1KK300007
TRIM	280CC	ODOMETER READING	16087
COLOR	BROWN	INSURANCE EXPIRY	2019-5-7
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY OBSERVATIONS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	5,000	RC COPY AVAILABLE	ORIGINAL	BANK HYPOTHECATION	NO
DENT	NO	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

1,54,094




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Tyre		7 / 10
Control		7 / 10
Light		7 / 10
Oil		7 / 10
Chassis		7 / 10
Stand		7 / 10

TOTAL ESTIMATE SPEND 1,000



Ordered by: Prashanth | Inspected date: 2019-05-07

Order Id: 70194

Overall Score **7/10**






1,54,094

TYRE

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRONT TYRE CONDITION & AIR PRESSURE	7	GOOD CONDITION	0
REAR TYRE CONDITION & AIR PRESSURE	7	GOOD CONDITION	0
WHEEL SPOKES FRONT	7	GOOD CONDITION	0
WHEEL SPOKES REAR	7	GOOD CONDITION	0
WHEEL RIM FRONT	7	GOOD CONDITION	0
WHEEL RIM REAR	7	GOOD CONDITION	0
WHEEL BEARINGS FRONT	7	GOOD CONDITION	0
WHEEL BEARINGS REAR	7	GOOD CONDITION	0
WHEEL SEALS FRONT	7	GOOD CONDITION	0
WHEEL SEALS REAR	7	GOOD CONDITION	0
BRAKE FUNCTION FRONT	7	WORKING	0
BRAKE FUNCTION REAR	7	WORKING	0
BRAKES CONDITION FRONT	7	GOOD CONDITION	0
BRAKES CONDITION REAR	7	GOOD CONDITION	0

IMAGES



Ordered by: Prashanth | Inspected date: 2019-05-07

Order Id: 70194

Overall Score **7/10**





1,54,094

STAND

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
CENTRE STAND CONDITION	7	GOOD CONDITION	0
CENTRE STAND RETENTION	7	GOOD RETENTION	0
SIDE STAND CONDITION	7	GOOD CONDITION	0
SIDE STAND RETENTION	7	GOOD RETENTION	0

IMAGES



CONTROL

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
HANDLEBARS CONDITION	7	GOOD CONDITION	0
LEVERS & PEDAL CONDITION	7	GOOD CONDITION	0
PIVOTS	7	GOOD CONDITION	0
CABLES CONDITION	7	GOOD CONDITION	0
CABLES ROUTING	7	GOOD ROUTING	0
HOSES CONDITION	7	GOOD CONDITION	0
HOSES ROUTING	7	GOOD ROUTING	0
THROTTLE OPERATION	7	GOOD OPERATION	0

Ordered by: Prashanth | Inspected date: 2019-05-07

Order Id: 70194

Overall Score



7/10



1,54,094

IMAGES




OIL



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LEVELS - ENGINE OIL	7	MAXIMUM LEVEL	0
LEVELS - GEAR OIL/SHAFT DRIVE (YES)	7	MAXIMUM LEVEL	0
LEVELS - HYDRAULIC FLUID (YES)	7	MAXIMUM LEVEL	0
LEVELS - COOLANT (YES)	6	LOW LEVEL	1000
LEVELS - FUEL	6	AVERAGE	0
LEAKS - ENGINE OIL	7	NO LEAKAGE	0
LEAKS - GEAR OIL	7	NO LEAKAGE	0
LEAKS - HYDRAULIC FLUID	7	NO LEAKAGE	0
LEAKS - COOLANT	7	NO LEAKAGE	0
LEAKS - FUEL	7	NO LEAKAGE	0

IMAGES



Ordered by: Prashanth | Inspected date: 2019-05-07

Order Id: 70194

Overall Score **7/10**



1,54,094

LIGHT

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
BATTERY CONDITION	7	FULLY CHARGED	0
BATTERY VENT TUBE	7	GOOD CONDITION	0
HEADLAMP CONDITION	7	GOOD CONDITION	0
TAILLAMP/BRAKELAMP CONDITION	7	GOOD CONDITION	0
TAILLAMP/BRAKELAMP OPERATION	7	WORKING	0
TURN SIGNALS OPERATION FRONT LEFT	7	WORKING	0
TURN SIGNALS OPERATION FRONT RIGHT	7	WORKING	0
TURN SIGNALS OPERATION REAR LEFT	7	WORKING	0
TURN SIGNALS OPERATION REAR RIGHT	7	WORKING	0
SWITCHES OPERATION	7	WORKING	0
MIRRORS CONDITION	8	GOOD CONDITION	0
MIRRORS AIM	7	GOOD AIM	0
LENSES & REFLECTORS CONDITION	7	GOOD CONDITION	0
WIRING CONDITION	7	GOOD CONDITION	0
WIRING ROUTING	7	GOOD ROUTING	0

IMAGES



Ordered by: Prashanth | Inspected date: 2019-05-07

Order Id: 70194

Overall Score



7/10



1,54,094



CHASSIS




7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRAME CONDITION	7	GOOD CONDITION	0
FRAME STEERING-HEAD BEARINGS	7	GOOD CONDITION	0
FRAME SWINGARM BUSHINGS	7	GOOD CONDITION	0
SUSPENSION FRONT FORKS LEFT	7	GOOD CONDITION	0
SUSPENSION FRONT FORKS RIGHT	7	GOOD CONDITION	0
SUSPENSION REAR SHOCKS LEFT	7	MINIMUM SHOCK	0
SUSPENSION REAR SHOCKS RIGHT	7	MINIMUM SHOCK	0
CHAIN/BELT TENSION	7	CHAIN TENSION	0
CHAIN/BELT LUBRICATION	7	CHAIN LUBRICATION	0
CHAIN/BELT SPROCKETS	7	CHAIN SPROCKET	0
FASTENERS THREADED	7	GOOD CONDITION	0
FASTENERS CLIPS & COTTER PINS	7	GOOD CONDITION	0
ENGINE	7	NORMAL OPERATING NOISE	0
TRANSMISSION	7	PROPERLY ENGAGE	0



IMAGES



Ordered by: Prashanth | Inspected date: 2019-05-07

Order Id: 70194

Overall Score



7/10



1,54,094



DOCUMENTS



DESCRIPTION

good condition

Ordered by: Prashanth | Inspected date: 2019-05-07

Order Id: 70194

Overall Score




7/10



1,54,094

IMAGES



Ordered by: Prashanth | Inspected date: 2019-05-07

Order Id: 70194

Overall Score



7/10



1,54,094

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.