


ECO INSPECTION CERTIFICATE

Premium

Order ID : 70702

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Rahul Tituriya	Inspection Date : 2019-05-08	Location : NEWDELHI	Inspected By  Arshad Ali
--------------------------------	---------------------------------	------------------------	---

7/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 120 does not need attention
- ✓ 1 Owner , 5 Years Vehicle Age
- ✓ No Accidental History

✓ **Verified Technician**
232+ vehicle inspected
1+ years experience

Hyundai Xcent S 1.1 CRDI OPT, 2014



VEHICLE INFORMATION

MAKE	HYUNDAI	ENGINE NUMBER	55723
MODEL	XCENT	REGISTRATION NO.	DL7CP7472
MFG. DATE	2014-06-01	VIN/CHASSIS NUMBER	29527
TRIM	S 1.1 CRDI OPT	ODOMETER READING	32289
COLOR	WHITE	INSURANCE EXPIRY	2019-3-5
BODY TYPE	COMPACT SEDAN	VEHICLE PASSING	PRIVATE
FUEL TYPE	DIESEL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	32,000	RC COPY AVAILABLE	ORIGINAL	BANK HYPOTHECATION	NO
DENT	NO	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

3,80,255




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 70%;"></div>	7 / 10
Wheel	<div style="width: 70%;"></div>	7 / 10
Test Drive	<div style="width: 70%;"></div>	7 / 10
Exterior	<div style="width: 70%;"></div>	7 / 10
Hood	<div style="width: 70%;"></div>	7 / 10

TOTAL ESTIMATE SPEND 200



Ordered by: Rahul Tituriya | Inspected date: 2019-05-08

Order Id: 70702

Overall Score **7/10**




3,80,255

INTERIOR

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	9	VERY GOOD CONDITION	0
DOOR HINGES	7	GOOD WORKING(CHECKED)	0
CARPET & FLOOR MAT	7	GOOD CONDITION	0
SEAT & SEAT BELT	7	GOOD WORKING(CHECKED)	0
DASHBOARD & INSTRUMENT PANEL	7	GOOD CONDITION	0
HORN	7	GOOD SOUND(CHECKED)	0
SPEAKERS & MUSIC SYSTEM	9	VERY GOOD CONDITION AND SOUNDS(CHECKED)	0
HANDBRAKE	7	GOOD WORKING(CHECKED)	0
STEERING-MOUNTED CONTROLS	7	GOOD CONDITION	0
PEDALS	7	GOOD WORKING(CHECKED)	0
CENTRAL LOCK	7	GOOD WORKING(CHECKED)	0
A/C VENTS & HEATER	7	GOOD CONDITION AND WORKS(CHECKED)	0
CUP HOLDERS	7	GOOD CONDITION	0
NAVIGATION (NO)	10		0
ODOMETER	7	GOOD WORKING(CHECKED)	0
POWER WINDOWS (YES)	7	BOTH ARE GOOD WORKING(CHECKED)	0
HAZARD LIGHT	7	GOOD(CHECKED)	0

IMAGES



Ordered by: Rahul Titoriya | Inspected date: 2019-05-08

Order Id: 70702

Overall Score



7/10



3,80,255


INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7	GOOD CONDITION AND SMOOTHLY STEER BOTH SIDES	0
BRAKE PERFORMANCE	7	GOOD WORKING(CHECKED)	0
CLUTCH PERFORMANCE	7	GOOD WORKING(CHECKED)	0
ENGINE NOISE	7	GOOD CONDITION AND NOISE	0
IGNITION SYSTEM	7	GOOD WORKING(CHECKED)	0
SUSPENSION PERFORMANCE	6	AVERAGE WORKING(CHECKED)	0
SUSPENSION FRONT SHOCKS	6	AVERAGE CONDITION	0
SUSPENSION REAR SHOCKS	6	AVERAGE CONDITION	0
TRANSMISSION ENGAGE	7	GOOD WORKING(CHECKED)	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (YES)	7	GOOD WORKING(CHECKED)	0
REAR VIEW CAMERA (NO)	10		0

 IMAGES

 WHEEL

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7	GOOD CONDITION	0
SPARE TYRE (YES)	7	GOOD CONDITION	0
WHEEL ASSEMBLY (ALLOY RIM)	6	AVERAGE CONDITION	0

 IMAGES



 HOOD




7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7	GOOD CONDITION	0
RH APRON	7	GOOD CONDITION	0
RADIATOR	6	AVERAGE WORKING	0
WIRING	6	AVERAGE CONDITION	0
BATTERY	7	GOOD CONDITION AND WORKS(CHECKED)	0
BRAKE FLUID LEVEL	7	MAX LEVEL	0
ENGINE OIL	7	MAX LEVEL	0
COOLANT LEVEL	7	MAX LEVEL	0
BRAKE & COOLANT HOSE PIPES	6	AVERAGE CONDITION	0
UNDERCARRIAGE	6	AVERAGE CONDITION	0
EXHAUST SYSTEM	6	AVERAGE CONDITION	0

 IMAGES





Ordered by: Rahul Tituriya | Inspected date: 2019-05-08

Order Id: 70702

Overall Score  **7/10**



3,80,255

 **EXTERIOR**

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7	GOOD CONDITION	0
FRONT BUMPER	7	GOOD CONDITION	0
HEAD LIGHTS	7	GOOD CONDITION AND WORKS(CHECKED)	0
GRILLE	7	GOOD CONDITION	0
FOG LAMPS	7	GOOD WORKING(CHECKED)	0
HOOD	7	GOOD CONDITION	0
PILLAR	7	GOOD CONDITION	0
FRONT WINDSHIELD	7	GOOD CONDITION	0
SIDE VIEW MIRRORS	7	GOOD CONDITION	0
LH FENDER	7	GOOD CONDITION	0
LH FRONT DOOR	7	GOOD CONDITION	0
LH REAR DOOR	7	GOOD CONDITION	0
LH RUNNING BOARD	7	GOOD CONDITION	0
LH QUARTER PANEL	7	GOOD CONDITION	0
FUEL LID	7	GOOD WORKING(CHECKED)	0
REAR WINDSHIELD	7	GOOD CONDITION	0
REAR BUMPER	7	GOOD CONDITION	0
TAIL LIGHT	7	GOOD CONDITION AND WORKS(CHECKED)	0
TRUNK LID/TAIL GATE	7	GOOD CONDITION AND WORKS(CHECKED)	0
LUGGAGE COMPARTMENT LIGHT	7	GOOD CONDITION	0
RH QUARTER PANEL	7	GOOD CONDITION	0
RH RUNNING BOARD	7	GOOD CONDITION	0
RH REAR DOOR	7	GOOD CONDITION	0
RH FRONT DOOR	7	GOOD CONDITION	0

Ordered by: Rahul Tituriya | Inspected date: 2019-05-08

Order Id: 70702

Overall Score **7/10**



3,80,255

EXTERIOR (CONTINUED)

7/10


INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FENDER	7	GOOD CONDITION	0
BODY RUST	7	GOOD(CHECKED)	0
ROOF (REGULAR)	7	GOOD CONDITION	0
PAINT CONDITION	7	GOOD CONDITION	0
TURN SIGNAL	5	LHS LAMP ARE NOT WORKING	200

IMAGES





 **NEED ATTENTION** 



 **DOCUMENTS**



 **DESCRIPTION**

During the inspection time vehicle are good condition but some minor scratches and of all body frame

Ordered by: Rahul Tituriya | Inspected date: 2019-05-08

Order Id: 70702

Overall Score





7/10



3,80,255

 IMAGES





Ordered by: Rahul Titoriya | Inspected date: 2019-05-08

Order Id: 70702

Overall Score



7/10



3,80,255

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.