


ECO INSPECTION CERTIFICATE

Premium

Order ID : 68837

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Kalpana	Inspection Date : 2019-05-08	Location : NAGPUR	Inspected By  Shahbaz Sheikh
-------------------------	---------------------------------	----------------------	---

6/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 119 does not need attention
- ✓ 1 Owner , 6 Years Vehicle Age
- ✓ No Accidental History

✓ **Verified Technician**
68+ vehicle inspected
1+ years experience

Tata Nano LX, 2013



VEHICLE INFORMATION

MAKE	TATA	ENGINE NUMBER	NXYK75224
MODEL	NANO	REGISTRATION NO.	MH31EK1373
MFG. DATE	2013-09-01	VIN/CHASSIS NUMBER	MAT12253CKK74712
TRIM	LX	ODOMETER READING	8162
COLOR	GREEN	INSURANCE EXPIRY	2018-3-23
BODY TYPE	MUV	VEHICLE PASSING	PRIVATE
FUEL TYPE	PETROL	ENGINE SOUND LINK	NIL

KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	1,500	RC COPY AVAILABLE	ORIGINAL	BANK HYPOTHECATION	NO
DENT	YES	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

91,215




ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 60%;"></div>	6 / 10
Wheel	<div style="width: 60%;"></div>	6 / 10
Test Drive	<div style="width: 70%;"></div>	7 / 10
Exterior	<div style="width: 60%;"></div>	6 / 10
Hood	<div style="width: 60%;"></div>	6 / 10

TOTAL ESTIMATE SPEND 7,000



Ordered by: Kalpana | Inspected date: 2019-05-08

Order Id: 68837

Overall Score



6/10



91,215



INTERIOR





6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	6		0
DOOR HINGES	6		0
CARPET & FLOOR MAT	6		0
SEAT & SEAT BELT	6		0
DASHBOARD & INSTRUMENT PANEL	6		0
HORN	6		0
SPEAKERS & MUSIC SYSTEM	6		0
HANDBRAKE	6		0
PEDALS	6		0
CENTRAL LOCK	6		0
A/C VENTS & HEATER	6		0
CUP HOLDERS	6		0
NAVIGATION (NO)	10		0
ODOMETER	6		0
POWER WINDOWS (YES - FRONT ONLY)	6		0
HAZARD LIGHT	6		0
STEERING-MOUNTED CONTROLS	0	NA	5000



IMAGES



Ordered by: Kalpana | Inspected date: 2019-05-08

Order Id: 68837

Overall Score



6/10



91,215



TEST DRIVE



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	6		0
BRAKE PERFORMANCE	6		0
CLUTCH PERFORMANCE	6		0
ENGINE NOISE	6		0
IGNITION SYSTEM	6		0
SUSPENSION PERFORMANCE	6		0
SUSPENSION FRONT SHOCKS	6		0
SUSPENSION REAR SHOCKS	6		0
TRANSMISSION ENGAGE	6		0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0



IMAGES



WHEEL



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	6		0
SPARE TYRE (YES)	6		0
WHEEL ASSEMBLY (STEEL RIM)	6		0

 IMAGES



 HOOD



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	6		0
RH APRON	6		0
RADIATOR	6		0
WIRING	6		0
BATTERY	6		0
BRAKE FLUID LEVEL	6		0
ENGINE OIL	6		0
COOLANT LEVEL	6		0
BRAKE & COOLANT HOSE PIPES	6		0
UNDERCARRIAGE	6		0
EXHAUST SYSTEM	6		0

 IMAGES



Ordered by: Kalpana | Inspected date: 2019-05-08

Order Id: 68837

Overall Score  **6/10**



91,215

 **EXTERIOR**

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	6		0
FRONT BUMPER	6		0
HEAD LIGHTS	6		0
GRILLE	6		0
TURN SIGNAL	6		0
FOG LAMPS	6		0
HOOD	6		0
PILLAR	6		0
FRONT WINDSHIELD	6		0
SIDE VIEW MIRRORS	6		0
LH FRONT DOOR	6		0
LH REAR DOOR	6		0
LH RUNNING BOARD	6		0
LH QUARTER PANEL	6		0
FUEL LID	6		0
REAR WINDSHIELD	6		0
REAR BUMPER	6		0
TAIL LIGHT	6		0
TRUNK LID/TAIL GATE	6		0
LUGGAGE COMPARTMENT LIGHT	6		0
RH QUARTER PANEL	6		0
RH RUNNING BOARD	6		0
RH REAR DOOR	6		0
RH FRONT DOOR	6		0

Ordered by: Kalpana | Inspected date: 2019-05-08

Order Id: 68837

Overall Score



6/10



91,215



EXTERIOR (CONTINUED)




6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FENDER	6		0
BODY RUST	6		0
ROOF (REGULAR)	6		0
PAINT CONDITION	6		0
LH FENDER	5	POOR	2000



IMAGES



NEED ATTENTION



Ordered by: Kalpana | Inspected date: 2019-05-08

Order Id: 68837

Overall Score





6/10



91,215



DOCUMENTS



DESCRIPTION

good condition and well maintain

Ordered by: Kalpana | Inspected date: 2019-05-08

Order Id: 68837

Overall Score



6/10



91,215

IMAGES



Ordered by: Kalpana | Inspected date: 2019-05-08

Order Id: 68837

Overall Score



6/10



91,215

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.