


ECO INSPECTION CERTIFICATE

Premium

Order ID : 71183

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Satnam Kaur	Inspection Date : 2019-05-09	Location : SEC29 GGN	Inspected By  Gagan Gurawaliya
-----------------------------	---------------------------------	-------------------------	---

7/10

Overall Score

- ✔ Evaluated across **5** segments
- ✔ Covered **121+** checkpoints
- ✔ **121** does not need attention
- ✔ **1** Owner , **4** Years Vehicle Age
- ✔ No Accidental History

✔ **Verified Technician**

700+ vehicle inspected
1+ years experience

Mahindra Scorpio S10, 2015



VEHICLE INFORMATION			
MAKE	MAHINDRA	ENGINE NUMBER	22293
MODEL	SCORPIO	REGISTRATION NO.	DL12CA6755
MFG. DATE	2015-01-01	VIN/CHASSIS NUMBER	A11972
TRIM	S10	ODOMETER READING	64608
COLOR	WHITE	INSURANCE EXPIRY	2019-5-9
BODY TYPE	SUV	VEHICLE PASSING	PRIVATE
FUEL TYPE	DIESEL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	25,000	RC COPY AVAILABLE	ORIGINAL	BANK HYPOTHECATION	NO
DENT	NO	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



orangebookvalue.com

Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.
With this evaluation, the Fair Market Price for this vehicle comes to be:

8,53,075



Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 70%; background-color: green;"></div>	7 / 10
Wheel	<div style="width: 70%; background-color: green;"></div>	7 / 10
Test Drive	<div style="width: 70%; background-color: green;"></div>	7 / 10
Exterior	<div style="width: 70%; background-color: green;"></div>	7 / 10
Hood	<div style="width: 70%; background-color: green;"></div>	7 / 10

TOTAL ESTIMATE SPEND 0

0

0

0

0

0

Ordered by: Satnam Kaur | Inspected date: 2019-05-09

Order Id: 71183

Overall Score **7/10**



8,53,075



INTERIOR



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7	GOOD CONDITION	0
DOOR HINGES	7	GOOD CONDITION	0
CARPET & FLOOR MAT	7	GOOD CONDITION	0
SEAT & SEAT BELT	7	GOOD CONDITION	0
DASHBOARD & INSTRUMENT PANEL	7	GOOD CONDITION	0
HORN	7	GOOD CONDITION	0
SPEAKERS & MUSIC SYSTEM	7	GOOD CONDITION	0
HANDBRAKE	7	GOOD CONDITION	0
STEERING-MOUNTED CONTROLS	7	GOOD CONDITION	0
PEDALS	7	GOOD CONDITION	0
CENTRAL LOCK	7	GOOD CONDITION	0
A/C VENTS & HEATER	7	GOOD CONDITION	0
CUP HOLDERS	7	GOOD CONDITION	0
NAVIGATION (NO)	10		0
ODOMETER	7	GOOD CONDITION	0
POWER WINDOWS (YES)	7	GOOD CONDITION	0
HAZARD LIGHT	7	GOOD CONDITION	0



IMAGES



Ordered by: Satnam Kaur | Inspected date: 2019-05-09

Order Id: 71183

Overall Score **7/10**



8,53,075

TEST DRIVE

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7	GOOD CONDITION	0
BRAKE PERFORMANCE	7	GOOD CONDITION	0
CLUTCH PERFORMANCE	7	GOOD CONDITION	0
ENGINE NOISE	7	GOOD CONDITION	0
IGNITION SYSTEM	7	GOOD CONDITION	0
SUSPENSION PERFORMANCE	7	GOOD CONDITION	0
SUSPENSION FRONT SHOCKS	7	GOOD CONDITION	0
SUSPENSION REAR SHOCKS	7	GOOD CONDITION	0
TRANSMISSION ENGAGE	7	GOOD CONDITION	0
CRUISE CONTROL (YES)	7	GOOD CONDITION	0
REAR PARKING SENSORS (YES)	7	GOOD CONDITION	0
REAR VIEW CAMERA (NO)	10		0

IMAGES



WHEEL

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7	GOOD CONDITION	0
SPARE TYRE (YES)	7	GOOD CONDITION	0
WHEEL ASSEMBLY (ALLOY RIM)	7	GOOD CONDITION	0

 IMAGES



 HOOD



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7	GOOD CONDITION	0
RH APRON	7	GOOD CONDITION	0
RADIATOR	7	GOOD CONDITION	0
WIRING	7	GOOD CONDITION	0
BATTERY	7	GOOD CONDITION	0
BRAKE FLUID LEVEL	7	MAX	0
ENGINE OIL	7	MAX	0
COOLANT LEVEL	7	MAX	0
BRAKE & COOLANT HOSE PIPES	7	GOOD CONDITION	0
UNDERCARRIAGE	7	GOOD CONDITION	0
EXHAUST SYSTEM	7	GOOD CONDITION	0

 IMAGES



Ordered by: Satnam Kaur | Inspected date: 2019-05-09

Order Id: 71183

Overall Score  **7/10**



8,53,075

 **EXTERIOR**

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7	GOOD CONDITION	0
FRONT BUMPER	7	GOOD CONDITION	0
HEAD LIGHTS	7	GOOD CONDITION	0
GRILLE	7	GOOD CONDITION	0
TURN SIGNAL	7	GOOD CONDITION	0
FOG LAMPS	7	GOOD CONDITION	0
HOOD	7	GOOD CONDITION	0
PILLAR	7	GOOD CONDITION	0
FRONT WINDSHIELD	7	GOOD VISIBILITY	0
SIDE VIEW MIRRORS	7	GOOD CONDITION	0
LH FENDER	7	GOOD CONDITION	0
LH FRONT DOOR	7	GOOD CONDITION	0
LH REAR DOOR	7	GOOD CONDITION	0
LH RUNNING BOARD	7	GOOD CONDITION	0
LH QUARTER PANEL	7	GOOD CONDITION	0
FUEL LID	7	GOOD CONDITION	0
REAR WINDSHIELD	7	GOOD VISIBILITY	0
REAR BUMPER	7	GOOD CONDITION	0
TAIL LIGHT	7	GOOD CONDITION	0
TRUNK LID/TAIL GATE	7	GOOD CONDITION	0
LUGGAGE COMPARTMENT LIGHT	7	GOOD CONDITION	0
RH QUARTER PANEL	7	GOOD CONDITION	0
RH RUNNING BOARD	7	GOOD CONDITION	0
RH REAR DOOR	7	GOOD CONDITION	0

Ordered by: Satnam Kaur | Inspected date: 2019-05-09

Order Id: 71183

Overall Score **7/10**



8,53,075

EXTERIOR (CONTINUED)

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	7	GOOD CONDITION	0
RH FENDER	7	GOOD CONDITION	0
BODY RUST	7	GOOD CONDITION	0
ROOF (REGULAR)	7	GOOD CONDITION	0
PAINT CONDITION	7	GOOD CONDITION	0

IMAGES



DOCUMENTS



DESCRIPTION

car fully painted

Ordered by: Satnam Kaur | Inspected date: 2019-05-09

Order Id: 71183

Overall Score




7/10



8,53,075

IMAGES





Ordered by: Satnam Kaur | Inspected date: 2019-05-09

Order Id: 71183

Overall Score



7/10



8,53,075

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.