

ECO INSPECTION CERTIFICATE

Premium

Order ID : 71117

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By :
Vaibhav Jain

Inspection Date :
2019-05-10

Location :
GHAZIABAD

Inspected By

6/10



Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 115 does not need attention
- ✓ 1 Owner , 8 Years Vehicle Age
- ✓ No Accidental History



Kishan Kumar

- ✓ Verified Technician
- 270+ vehicle inspected
- 1+ years experience

Maruti Suzuki Wagon R LXI CNG, 2011



VEHICLE INFORMATION

MAKE	MARUTI SUZUKI	ENGINE NUMBER	43538
MODEL	WAGON R	REGISTRATION NO.	DL8CR8229
MFG. DATE	2011-11-01	VIN/CHASSIS NUMBER	50099
TRIM	LXI CNG	ODOMETER READING	255285
COLOR	SILKY SILVER	INSURANCE EXPIRY	2019-12-20
BODY TYPE	HATCHBACK	VEHICLE PASSING	PRIVATE
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	12,000	RC COPY AVAILABLE	ORIGINAL	BANK HYPOTHECATION	YES
DENT	NO	INSURANCE COPY AVAILABLE	YES (COMPREHENSIVE)	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

1,37,075




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 60%;"></div>	6 / 10
Wheel	<div style="width: 70%;"></div>	7 / 10
Test Drive	<div style="width: 50%;"></div>	5 / 10
Exterior	<div style="width: 70%;"></div>	7 / 10
Hood	<div style="width: 70%;"></div>	7 / 10

TOTAL ESTIMATE SPEND 0



Ordered by: Vaibhav Jain | Inspected date: 2019-05-10

Order Id: 71117

Overall Score **6/10**



1,37,075

INTERIOR

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7		0
DOOR HINGES	7		0
CARPET & FLOOR MAT	7		0
SEAT & SEAT BELT	7		0
DASHBOARD & INSTRUMENT PANEL	7		0
HORN	7		0
SPEAKERS & MUSIC SYSTEM	7		0
HANDBRAKE	7		0
PEDALS	7		0
CENTRAL LOCK	7		0
A/C VENTS & HEATER	6	AVERAGE COOLING	0
CUP HOLDERS	7		0
ODOMETER	7		0
POWER WINDOWS (YES - FRONT ONLY)	7		0
HAZARD LIGHT	7		0
STEERING-MOUNTED CONTROLS	0	NA	0
NAVIGATION (YES)	0	NA	0

IMAGES



Ordered by: Vaibhav Jain | Inspected date: 2019-05-10

Order Id: 71117

Overall Score **6/10**



1,37,075

TEST DRIVE

5/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7		0
BRAKE PERFORMANCE	7		0
CLUTCH PERFORMANCE	7		0
ENGINE NOISE	6	AVERAGE CONDITION	0
IGNITION SYSTEM	7		0
SUSPENSION PERFORMANCE	6	AVERAGE CONDITION	0
SUSPENSION FRONT SHOCKS	6	AVERAGE CONDITION	0
SUSPENSION REAR SHOCKS	6	AVERAGE CONDITION	0
TRANSMISSION ENGAGE	7		0
CRUISE CONTROL (YES)	0	NA	0
REAR PARKING SENSORS (YES)	0	NA	0
REAR VIEW CAMERA (YES)	0	NA	0

IMAGES



WHEEL

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7		0
SPARE TYRE (YES)	6	AVERAGE CONDITION	0
WHEEL ASSEMBLY (STEEL RIM)	7		0

 IMAGES




 HOOD



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7		0
RH APRON	7		0
RADIATOR	6	AVERAGE CONDITION	0
WIRING	6	AVERAGE CONDITION	0
BATTERY	7		0
BRAKE FLUID LEVEL	7		0
ENGINE OIL	7		0
COOLANT LEVEL	7		0
BRAKE & COOLANT HOSE PIPES	6	AVERAGE CONDITION	0
UNDERCARRIAGE	6	AVERAGE CONDITION	0
EXHAUST SYSTEM	6	AVERAGE CONDITION	0

 IMAGES



Ordered by: Vaibhav Jain | Inspected date: 2019-05-10

Order Id: 71117

Overall Score  **6/10**



1,37,075

 **EXTERIOR**

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7		0
FRONT BUMPER	7		0
HEAD LIGHTS	7		0
GRILLE	7		0
TURN SIGNAL	7		0
HOOD	6	AVERAGE CONDITION	0
PILLAR	7		0
FRONT WINDSHIELD	6		0
SIDE VIEW MIRRORS	7		0
LH FENDER	7		0
LH FRONT DOOR	7		0
LH REAR DOOR	7		0
LH RUNNING BOARD	7		0
LH QUARTER PANEL	7		0
FUEL LID	7		0
REAR WINDSHIELD	6	AVERAGE CONDITION	0
REAR BUMPER	7		0
TAIL LIGHT	7		0
TRUNK LID/TAIL GATE	7		0
LUGGAGE COMPARTMENT LIGHT	7		0
RH QUARTER PANEL	7		0
RH RUNNING BOARD	7		0
RH REAR DOOR	7		0
RH FRONT DOOR	7		0

Ordered by: Vaibhav Jain | Inspected date: 2019-05-10

Order Id: 71117

Overall Score



6/10




1,37,075

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FENDER	7		0
BODY RUST	7		0
ROOF (REGULAR)	7		0
PAINT CONDITION	6	AVERAGE CONDITION	0
FOG LAMPS	0	NA	0

IMAGES



NEED ATTENTION ⚠️



Ordered by: Vaibhav Jain | Inspected date: 2019-05-10

Order Id: 71117

Overall Score




6/10



1,37,075

DOCUMENTS



DESCRIPTION

all body minor scratches

Ordered by: Vaibhav Jain | Inspected date: 2019-05-10

Order Id: 71117

Overall Score




6/10



1,37,075

IMAGES



REGN. NO : DL8CR 8229

REG. DT:	26/12/2011	Q SMC:	DL
CH. NO.:	MAHARASHTRA	REG. CD:	DL
PO:	K100N434336	COLOUR:	SILVER SILV
		CLASS:	M1
NAME:	SHIV KUMAR		
SNOW OF:	RAMSINGH		
ADDRESS:	1548,BLOCKJ		
	JAMNAGAR PUNJ		
	DELHI		

PLEASE STATE BANK OF INDIA (17003)

MODEL : WAGON R LXI GREEN BS4

NO. OF : 840000 NO. OF CYL : 3

SEATING : 5 UNLADEN WT : 870

REG. DT. : 11/2011 SEATING C. : 5

REG. NO. : DL8CR 8229 SEATING C. : 5

REG. DT. : 25/12/11 CU CAP : 398

REG. DT. : 07/11

Ordered by: Vaibhav Jain | Inspected date: 2019-05-10

Order Id: 71117

Overall Score



6/10



1,37,075

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.