


ECO INSPECTION CERTIFICATE

Premium

Order ID : 69850

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : SANDEEP JINDAL	Inspection Date : 2019-05-11	Location : PANTHUR	Inspected By  Muruganandham A
--------------------------------	---------------------------------	-----------------------	---

7/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 121 does not need attention
- ✓ 1 Owner , 2 Years Vehicle Age
- ✓ No Accidental History

✓ **Verified Technician**
75+ vehicle inspected
1+ years experience










Skoda Rapid 1.6 MPI AMBITION, 2017



VEHICLE INFORMATION

MAKE	SKODA	ENGINE NUMBER	CLS612059
MODEL	RAPID	REGISTRATION NO.	HR20AY5073
MFG. DATE	2017-08-01	VIN/CHASSIS NUMBER	TMBBDHNA2HG107292
TRIM	1.6 MPI AMBITION	ODOMETER READING	17478
COLOR	CARBON STEEL	INSURANCE EXPIRY	2019-12-10
BODY TYPE	SEDAN	VEHICLE PASSING	PRIVATE
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	20,000	 RC COPY AVAILABLE	ORIGINAL	 BANK HYPOTHECATION	YES
 DENT	NO	 INSURANCE COPY AVAILABLE	YES (COMPREHENSIVE)	 BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

6,86,777




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

 Interior	<div style="width: 80%;"></div>	8 / 10
 Wheel	<div style="width: 80%;"></div>	8 / 10
 Test Drive	<div style="width: 80%;"></div>	8 / 10
 Exterior	<div style="width: 80%;"></div>	8 / 10
 Hood	<div style="width: 70%;"></div>	7 / 10

TOTAL ESTIMATE SPEND 0



Ordered by: SANDEEP JINDAL | Inspected date: 2019-05-11

Order Id: 69850

Overall Score **7/10**



6,86,777

INTERIOR

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7		0
DOOR HINGES	7		0
CARPET & FLOOR MAT	7		0
SEAT & SEAT BELT	7		0
DASHBOARD & INSTRUMENT PANEL	8		0
HORN	8		0
SPEAKERS & MUSIC SYSTEM	8		0
HANDBRAKE	7		0
STEERING-MOUNTED CONTROLS	8		0
PEDALS	8		0
CENTRAL LOCK	8		0
A/C VENTS & HEATER	7		0
CUP HOLDERS	8		0
NAVIGATION (NO)	10		0
ODOMETER	7		0
POWER WINDOWS (YES)	7		0
HAZARD LIGHT	7		0

IMAGES



Ordered by: SANDEEP JINDAL | Inspected date: 2019-05-11

Order Id: 69850

Overall Score **7/10**



6,86,777

TEST DRIVE

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	8		0
BRAKE PERFORMANCE	8		0
CLUTCH PERFORMANCE	7		0
ENGINE NOISE	8		0
IGNITION SYSTEM	8		0
SUSPENSION PERFORMANCE	7		0
SUSPENSION FRONT SHOCKS	7		0
SUSPENSION REAR SHOCKS	7		0
TRANSMISSION ENGAGE	7		0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (YES)	8		0
REAR VIEW CAMERA (NO)	10		0

IMAGES




WHEEL

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7		0
SPARE TYRE (YES)	9		0
WHEEL ASSEMBLY (ALLOY RIM)	7		0

 IMAGES




 HOOD



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7		0
RH APRON	8		0
RADIATOR	8		0
WIRING	8		0
BATTERY	7		0
BRAKE FLUID LEVEL	7		0
ENGINE OIL	7		0
COOLANT LEVEL	7		0
BRAKE & COOLANT HOSE PIPES	8		0
UNDERCARRIAGE	8		0
EXHAUST SYSTEM	7		0

 IMAGES



Ordered by: SANDEEP JINDAL | Inspected date: 2019-05-11

Order Id: 69850

Overall Score  **7/10**



6,86,777

 **EXTERIOR**

 **8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7		0
FRONT BUMPER	8		0
HEAD LIGHTS	8		0
GRILLE	8		0
TURN SIGNAL	8		0
FOG LAMPS	8		0
HOOD	7		0
PILLAR	8		0
FRONT WINDSHIELD	8		0
SIDE VIEW MIRRORS	8		0
LH FENDER	8		0
LH FRONT DOOR	8		0
LH REAR DOOR	8		0
LH RUNNING BOARD	7		0
LH QUARTER PANEL	7		0
FUEL LID	8		0
REAR WINDSHIELD	8		0
REAR BUMPER	7		0
TAIL LIGHT	7		0
TRUNK LID/TAIL GATE	7		0
LUGGAGE COMPARTMENT LIGHT	7		0
RH QUARTER PANEL	7		0
RH RUNNING BOARD	8		0
RH REAR DOOR	8		0

Ordered by: SANDEEP JINDAL | Inspected date: 2019-05-11

Order Id: 69850

Overall Score **7/10**






6,86,777

EXTERIOR (CONTINUED)



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	7		0
RH FENDER	8		0
BODY RUST	7		0
ROOF (REGULAR)	8		0
PAINT CONDITION	7		0

IMAGES



DOCUMENTS



DESCRIPTION

good

Ordered by: SANDEEP JINDAL | Inspected date: 2019-05-11

Order Id: 69850

Overall Score
















7/10



6,86,777

IMAGES



Ordered by: SANDEEP JINDAL | Inspected date: 2019-05-11

Order Id: 69850

Overall Score



7/10



6,86,777

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.