

ECO INSPECTION CERTIFICATE

Premium

Order ID : 71114

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By :
Vaibhav Jain

Inspection Date :
2019-05-10

Location :
GHAZIABAD

6/10



Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 113 does not need attention
- ✓ 1 Owner , 7 Years Vehicle Age
- ✓ No Accidental History

Inspected By



Kishan Kumar

- ✓ Verified Technician
- 271+ vehicle inspected
- 1+ years experience





Maruti Suzuki Wagon R LXI CNG, 2012



VEHICLE INFORMATION

MAKE	MARUTI SUZUKI	ENGINE NUMBER	67376
MODEL	WAGON R	REGISTRATION NO.	DL3CBC8137
MFG. DATE	2012-12-01	VIN/CHASSIS NUMBER	05784
TRIM	LXI CNG	ODOMETER READING	68000
COLOR	GREY	INSURANCE EXPIRY	2019-12-22
BODY TYPE	HATCHBACK	VEHICLE PASSING	PRIVATE
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	15,000	 RC COPY AVAILABLE	ORIGINAL	 BANK HYPOTHECATION	NO
 DENT	YES	 INSURANCE COPY AVAILABLE	YES (COMPREHENSIVE)	 BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:






2,22,719




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

 Interior	<div style="width: 60%;"></div>	6 / 10
 Wheel	<div style="width: 70%;"></div>	7 / 10
 Test Drive	<div style="width: 50%;"></div>	5 / 10
 Exterior	<div style="width: 60%;"></div>	6 / 10
 Hood	<div style="width: 60%;"></div>	6 / 10

TOTAL ESTIMATE SPEND 1,550



Ordered by: Vaibhav Jain | Inspected date: 2019-05-10

Order Id: 71114

Overall Score **6/10**



2,22,719

INTERIOR

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7		0
DOOR HINGES	7		0
CARPET & FLOOR MAT	7		0
SEAT & SEAT BELT	7		0
DASHBOARD & INSTRUMENT PANEL	7		0
HORN	7		0
SPEAKERS & MUSIC SYSTEM	7		0
HANDBRAKE	7		0
PEDALS	7		0
A/C VENTS & HEATER	7		0
CUP HOLDERS	7		0
ODOMETER	7		0
POWER WINDOWS (YES - FRONT ONLY)	6	AVERAGE CONDITION	0
HAZARD LIGHT	7		0
STEERING-MOUNTED CONTROLS	0	NA	0
CENTRAL LOCK	0	NA	0
NAVIGATION (YES)	0	NA	0

IMAGES



Ordered by: Vaibhav Jain | Inspected date: 2019-05-10

Order Id: 71114

Overall Score **6/10**



2,22,719

TEST DRIVE

5/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7		0
BRAKE PERFORMANCE	7		0
CLUTCH PERFORMANCE	7		0
ENGINE NOISE	6	AVERAGE CONDITION	0
IGNITION SYSTEM	7		0
SUSPENSION PERFORMANCE	6	AVERAGE CONDITION	0
SUSPENSION FRONT SHOCKS	6	AVERAGE CONDITION	0
SUSPENSION REAR SHOCKS	6	AVERAGE CONDITION	0
TRANSMISSION ENGAGE	7		0
CRUISE CONTROL (YES)	0	NA	0
REAR PARKING SENSORS (YES)	0	NA	0
REAR VIEW CAMERA (YES)	0	NA	0

IMAGES



WHEEL

7/10


INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7		0
SPARE TYRE (YES)	6	AVERAGE CONDITION	0
WHEEL ASSEMBLY (STEEL RIM)	7		0

 IMAGES

 HOOD

 6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7		0
RH APRON	7		0
RADIATOR	6	AVERAGE CONDITION	0
WIRING	6	AVERAGE CONDITION	0
BATTERY	6	AVERAGE CONDITION	0
BRAKE FLUID LEVEL	7		0
ENGINE OIL	7		0
COOLANT LEVEL	7		0
BRAKE & COOLANT HOSE PIPES	6	AVERAGE CONDITION	0
UNDERCARRIAGE	6	AVERAGE CONDITION	0
EXHAUST SYSTEM	6	AVERAGE CONDITION	0

 IMAGES


Ordered by: Vaibhav Jain | Inspected date: 2019-05-10

Order Id: 71114

Overall Score



6/10



2,22,719

 EXTERIOR



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7		0
FRONT BUMPER	7		0
HEAD LIGHTS	6	AVERAGE CONDITION	0
TURN SIGNAL	7		0
HOOD	6	AVERAGE CONDITION	0
PILLAR	7		0
FRONT WINDSHIELD	6	AVERAGE CONDITION	0
SIDE VIEW MIRRORS	7		0
LH FENDER	7		0
LH FRONT DOOR	7		0
LH REAR DOOR	6	MINOR DENT	250
LH RUNNING BOARD	7		0
LH QUARTER PANEL	7		0
FUEL LID	7		0
REAR WINDSHIELD	7		0
REAR BUMPER	6	SCRATCHES	150
TAIL LIGHT	7		0
TRUNK LID/TAIL GATE	7		0
LUGGAGE COMPARTMENT LIGHT	7		0
RH QUARTER PANEL	7		0
RH RUNNING BOARD	7		0
RH REAR DOOR	7		0
RH FRONT DOOR	6	SCRATCHES	150
RH FENDER	7		0

Ordered by: Vaibhav Jain | Inspected date: 2019-05-10

Order Id: 71114

Overall Score



6/10



2,22,719



EXTERIOR (CONTINUED)




6/10


INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
BODY RUST	7		0
ROOF (REGULAR)	7		0
PAINT CONDITION	7		0
GRILLE	4	BROKEN NEED TO BE CHANGE	1000
FOG LAMPS	0	NA	0





IMAGES



 **NEED ATTENTION** 



 **DOCUMENTS**



 **DESCRIPTION**

all body scratches minor dent and front grille broken need to change

Ordered by: Vaibhav Jain | Inspected date: 2019-05-10

Order Id: 71114

Overall Score




6/10



2,22,719

IMAGES





Ordered by: Vaibhav Jain | Inspected date: 2019-05-10

Order Id: 71114

Overall Score



6/10



2,22,719

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.