


# ECO INSPECTION CERTIFICATE

Premium

Order ID : 72642

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Vivek	Inspection Date : 2019-05-13	Location : DELHI	Inspected By   Verified Technician 801+ vehicle inspected 1+ years experience Lokesh Kumar
-----------------------	---------------------------------	---------------------	---

**6/10**

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 120 does not need attention
- ✓ 1 Owner , 6 Years Vehicle Age
- ✓ No Accidental History



## Hyundai Accent EXECUTIVE, 2013



### VEHICLE INFORMATION

MAKE	HYUNDAI	ENGINE NUMBER	75543
MODEL	ACCENT	REGISTRATION NO.	DL10CD8611
MFG. DATE	2013-03-01	VIN/CHASSIS NUMBER	371363
TRIM	EXECUTIVE	ODOMETER READING	71319
COLOR	WHITE	INSURANCE EXPIRY	2020-5-12
BODY TYPE	SEDAN	VEHICLE PASSING	PRIVATE
FUEL TYPE	PETROL	ENGINE SOUND LINK	<a href="#">LISTEN ENGINE SOUND</a>

### KEY HIGHLIGHTS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	24,000	 RC COPY AVAILABLE	ORIGINAL	 BANK HYPOTHECATION	NO
 DENT	NO	 INSURANCE COPY AVAILABLE	YES (COMPREHENSIVE)	 BANK NOC	NO








Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

**2,33,506**




### ECO SCORE & REPAIR COST ESTIMATE

#### ECO SCORE

 Interior	<div style="width: 60%;"></div>	6 / 10
 Wheel	<div style="width: 80%;"></div>	8 / 10
 Test Drive	<div style="width: 70%;"></div>	7 / 10
 Exterior	<div style="width: 60%;"></div>	6 / 10
 Hood	<div style="width: 60%;"></div>	6 / 10

#### TOTAL ESTIMATE SPEND 2,000



Ordered by: Vivek | Inspected date: 2019-05-13

Order Id: 72642

Overall Score



6/10



2,33,506



## INTERIOR






6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	6	FAIR	0
DOOR HINGES	6	FAIR	0
CARPET & FLOOR MAT	6	FAIR	0
SEAT & SEAT BELT	6	FAIR	0
DASHBOARD & INSTRUMENT PANEL	6	FAIR	0
HORN	6	FAIR	0
SPEAKERS & MUSIC SYSTEM	6	FAIR	0
HANDBRAKE	6	FAIR	0
STEERING-MOUNTED CONTROLS	6	FAIR	0
PEDALS	6	FAIR	0
CENTRAL LOCK	6	NO	0
A/C VENTS & HEATER	6	FAIR	0
CUP HOLDERS	6	FAIR	0
NAVIGATION (NO)	10		0
ODOMETER	6	FAIR	0
POWER WINDOWS (YES)	6	FAIR	0
HAZARD LIGHT	6	FAIR	0



## IMAGES



Ordered by: Vivek | Inspected date: 2019-05-13

Order Id: 72642

Overall Score  **6/10**



**2,33,506**

## TEST DRIVE

**7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	6	FAIR	0
BRAKE PERFORMANCE	6	FAIR	0
CLUTCH PERFORMANCE	6	FAIR	0
ENGINE NOISE	6	FAIR	0
IGNITION SYSTEM	6	FAIR	0
SUSPENSION PERFORMANCE	6	FAIR	0
SUSPENSION FRONT SHOCKS	6	FAIR	0
SUSPENSION REAR SHOCKS	6	FAIR	0
TRANSMISSION ENGAGE	6	FAIR	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (YES)	6	FAIR	0

## IMAGES



## WHEEL

**8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7	GOOD	0
SPARE TYRE (NO)	10		0
WHEEL ASSEMBLY (STEEL RIM)	6	FAIR	0

 IMAGES




 HOOD



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	6	FAIR	0
RH APRON	6	FAIR	0
RADIATOR	6	FAIR	0
WIRING	6	FAIR	0
BATTERY	6	FAIR	0
BRAKE FLUID LEVEL	6	FAIR	0
ENGINE OIL	6	FAIR	0
COOLANT LEVEL	6	FAIR	0
BRAKE & COOLANT HOSE PIPES	6	FAIR	0
UNDERCARRIAGE	6	FAIR	0
EXHAUST SYSTEM	6	FAIR	0

 IMAGES



Ordered by: Vivek | Inspected date: 2019-05-13

Order Id: 72642

Overall Score  **6/10**



**2,33,506**

 **EXTERIOR**

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	6	FAIR	0
FRONT BUMPER	6	PAINTED, MINOR SCRATCH	0
HEAD LIGHTS	6	FAIR	0
GRILLE	6	FAIR	0
TURN SIGNAL	6	FAIR	0
FOG LAMPS	6	NO	0
HOOD	6	PAINTED	0
PILLAR	6	FAIR	0
FRONT WINDSHIELD	6	FAIR	0
SIDE VIEW MIRRORS	6	FAIR	0
LH FENDER	6	PAINTED	0
LH FRONT DOOR	6	FAIR	0
LH REAR DOOR	6	FAIR	0
LH RUNNING BOARD	6	SCRATCH	0
LH QUARTER PANEL	6	MINOR SCRATCH	0
FUEL LID	6	FAIR	0
REAR WINDSHIELD	6	FAIR	0
TAIL LIGHT	6	FAIR	0
TRUNK LID/TAIL GATE	6	FAIR	0
LUGGAGE COMPARTMENT LIGHT	6	FAIR	0
RH QUARTER PANEL	6	MINOR DENT	0
RH RUNNING BOARD	6	SCRATCH	0
RH REAR DOOR	6	PAINTED	0
RH FRONT DOOR	6	FAIR	0



Ordered by: Vivek | Inspected date: 2019-05-13

Order Id: 72642

Overall Score



6/10



2,33,506



## EXTERIOR (CONTINUED)




6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FENDER	6	PAINTED	0
BODY RUST	6	MINOR	0
ROOF (REGULAR)	6		0
PAINT CONDITION	6	FAIR	0
REAR BUMPER	5	MINOR SCRATCH	2000

## IMAGES



## NEED ATTENTION ⚠



Ordered by: Vivek | Inspected date: 2019-05-13

Order Id: 72642

Overall Score




6/10



2,33,506



DOCUMENTS



DESCRIPTION

fair condition,, minor scratch,, tappet packing major leakage,,tapper noise



Ordered by: Vivek | Inspected date: 2019-05-13

Order Id: 72642

Overall Score



6/10



2,33,506

 IMAGES





Ordered by: Vivek | Inspected date: 2019-05-13

Order Id: 72642

Overall Score



6/10



2,33,506

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.