


ECO INSPECTION CERTIFICATE

Premium

Order ID : 72297

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Arvinder Singh	Inspection Date : 2019-05-14	Location : DELHI	Inspected By  Verified Technician 803+ vehicle inspected 1+ years experience Lokesh Kumar
--------------------------------	---------------------------------	---------------------	---

6/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 121 does not need attention
- ✓ 1 Owner , 5 Years Vehicle Age
- ✓ No Accidental History









Renault Duster 85 PS RXL, 2014



VEHICLE INFORMATION

MAKE	RENAULT	ENGINE NUMBER	49467
MODEL	DUSTER	REGISTRATION NO.	UP16AS8705
MFG. DATE	01/2014	VIN/CHASSIS NUMBER	046709
TRIM	85 PS RXL	ODOMETER READING	46707
COLOR	BROWN	INSURANCE EXPIRY	2019-4-12
BODY TYPE	SUV	VEHICLE PASSING	PRIVATE
FUEL TYPE	DIESEL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	24,000	 RC COPY AVAILABLE	ORIGINAL	 BANK HYPOTHECATION	NO
 DENT	NO	 INSURANCE COPY AVAILABLE	NO	 BANK NOC	NO








Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

5,42,096




ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

 Interior	<div style="width: 60%;"></div>	6 / 10
 Wheel	<div style="width: 60%;"></div>	6 / 10
 Test Drive	<div style="width: 70%;"></div>	7 / 10
 Exterior	<div style="width: 60%;"></div>	6 / 10
 Hood	<div style="width: 60%;"></div>	6 / 10

TOTAL ESTIMATE SPEND 0



Ordered by: Arvinder singh | Inspected date: 2019-05-14

Order Id: 72297

Overall Score



6/10



5,42,096



INTERIOR






6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	6	FAIR	0
DOOR HINGES	6	FAIR	0
CARPET & FLOOR MAT	6	FAIR	0
SEAT & SEAT BELT	6	FAIR	0
DASHBOARD & INSTRUMENT PANEL	6	FAIR	0
HORN	6	FAIR	0
SPEAKERS & MUSIC SYSTEM	6	FAIR	0
HANDBRAKE	6	FAIR	0
STEERING-MOUNTED CONTROLS	6	FAIR	0
PEDALS	6	FAIR	0
CENTRAL LOCK	6	FAIR	0
A/C VENTS & HEATER	6	FAIR	0
CUP HOLDERS	6	FAIR	0
NAVIGATION (NO)	10		0
ODOMETER	6	FAIR	0
POWER WINDOWS (YES)	7	GOOD	0
HAZARD LIGHT	6	FAIR	0



IMAGES



Ordered by: Arvinder singh | Inspected date: 2019-05-14

Order Id: 72297

Overall Score **6/10**




5,42,096

TEST DRIVE

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	6	FAIR	0
BRAKE PERFORMANCE	6	FAIR	0
CLUTCH PERFORMANCE	6	FAIR	0
ENGINE NOISE	6	FAIR	0
IGNITION SYSTEM	6	FAIR	0
SUSPENSION PERFORMANCE	6	FAIR	0
SUSPENSION FRONT SHOCKS	6	FAIR	0
SUSPENSION REAR SHOCKS	6	FAIR	0
TRANSMISSION ENGAGE	6	FAIR	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0

IMAGES






WHEEL

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7	GOOD	0
SPARE TYRE (YES)	6	FAIR	0
WHEEL ASSEMBLY (STEEL RIM)	6	FAIR	0

 IMAGES





 HOOD



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	6	FAIR	0
RH APRON	6	FAIR	0
RADIATOR	6	FAIR	0
WIRING	6	FAIR	0
BATTERY	6	FAIR	0
BRAKE FLUID LEVEL	6	FAIR	0
ENGINE OIL	6	FAIR	0
COOLANT LEVEL	6	FAIR	0
BRAKE & COOLANT HOSE PIPES	6	FAIR	0
UNDERCARRIAGE	6	FAIR	0
EXHAUST SYSTEM	6	FAIR	0

 IMAGES



Ordered by: Arvinder singh | Inspected date: 2019-05-14

Order Id: 72297

Overall Score  **6/10**



5,42,096

 **EXTERIOR**

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	6	FAIR	0
FRONT BUMPER	6	PAINTED	0
HEAD LIGHTS	6	FAIR	0
GRILLE	6	FAIR	0
TURN SIGNAL	6	FAIR	0
FOG LAMPS	6	FAIR	0
HOOD	6	PAINTED	0
PILLAR	6	FAIR	0
FRONT WINDSHIELD	6	FAIR	0
SIDE VIEW MIRRORS	6	FAIR	0
LH FENDER	6	PAINTED	0
LH FRONT DOOR	6	PAINTED	0
LH REAR DOOR	6	FAIR	0
LH RUNNING BOARD	6	SCRATCH	0
LH QUARTER PANEL	6	PAINTED	0
FUEL LID	6	FAIR	0
REAR WINDSHIELD	6	FAIR	0
REAR BUMPER	6	PAINTED	0
TAIL LIGHT	6	FAIR	0
TRUNK LID/TAIL GATE	6	PAINTED	0
LUGGAGE COMPARTMENT LIGHT	6	FAIR	0
RH QUARTER PANEL	6	PAINTED	0
RH RUNNING BOARD	6	FAIR	0
RH REAR DOOR	6	PAINTED	0

Ordered by: Arvinder singh | Inspected date: 2019-05-14

Order Id: 72297

Overall Score



6/10



5,42,096



EXTERIOR (CONTINUED)







6/10


INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	6	FAIR	0
RH FENDER	6	PAINTED	0
BODY RUST	6	MINOR	0
ROOF (REGULAR)	6	FAIR	0
PAINT CONDITION	6	FAIR	0



IMAGES



DOCUMENTS



DESCRIPTION

fair condition,, minor scratch,, interior and exterior dirty

Ordered by: Arvinder singh | Inspected date: 2019-05-14

Order Id: 72297

Overall Score




6/10



5,42,096

IMAGES



Ordered by: Arvinder singh | Inspected date: 2019-05-14

Order Id: 72297

Overall Score



6/10



5,42,096

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.