


ECO INSPECTION CERTIFICATE

Premium

Order ID : 71484

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Caravan Car	Inspection Date : 2019-05-14	Location : GOREGAON WEST	Inspected By  Shashank Mahadik
-----------------------------	---------------------------------	-----------------------------	---

6/10

Overall Score

- ✔ Evaluated across 5 segments
- ✔ Covered 121+ checkpoints
- ✔ 116 does not need attention
- ✔ 1 Owner , 10 Years Vehicle Age
- ✔ No Accidental History

✔ **Verified Technician**

213+ vehicle inspected
1+ years experience





Honda Civic 1.8 V AT, 2009



VEHICLE INFORMATION

MAKE	HONDA	ENGINE NUMBER	
MODEL	CIVIC	REGISTRATION NO.	MH04DW7231
MFG. DATE	05/2008	VIN/CHASSIS NUMBER	104032
TRIM	1.8 V AT	ODOMETER READING	54011
COLOR	WHITE A	INSURANCE EXPIRY	2019-3-25
BODY TYPE	SEDAN	VEHICLE PASSING	PRIVATE
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	20,000	 RC COPY AVAILABLE	ORIGINAL	 BANK HYPOTHECATION	YES
 DENT	NO	 INSURANCE COPY AVAILABLE	NO	 BANK NOC	YES








Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

3,24,952




ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

 Interior	<div style="width: 60%;"></div>	6 / 10
 Wheel	<div style="width: 70%;"></div>	7 / 10
 Test Drive	<div style="width: 70%;"></div>	7 / 10
 Exterior	<div style="width: 60%;"></div>	6 / 10
 Hood	<div style="width: 60%;"></div>	6 / 10

TOTAL ESTIMATE SPEND 3,400



Ordered by: caravan car | Inspected date: 2019-05-14

Order Id: 71484

Overall Score **6/10**



3,24,952


INTERIOR

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	6	AVERAGE CONDITION	0
DOOR HINGES	6	NO DAMAGE	0
CARPET & FLOOR MAT	6	AVERAGE	0
SEAT & SEAT BELT	7	GOOD CONDITION	0
DASHBOARD & INSTRUMENT PANEL	7	GOOD CONDITION	0
HORN	7	GOOD CONDITION	0
SPEAKERS & MUSIC SYSTEM	7	GOOD CONDITION	0
HANDBRAKE	7	GOOD CONDITION	0
PEDALS	7	GOOD CONDITION	0
CENTRAL LOCK	7	GOOD CONDITION	0
A/C VENTS & HEATER	7	GOOD CONDITION	0
CUP HOLDERS	7	GOOD CONDITION	0
NAVIGATION (NO)	10		0
ODOMETER	7	GOOD CONDITION	0
HAZARD LIGHT	6	NO DAMAGE	0
STEERING-MOUNTED CONTROLS	0	N/A	0
POWER WINDOWS (YES)	5	SWITCH BOARD NEED TO CHANGE	3000

IMAGES





TEST DRIVE

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7	SMOOTH	0
BRAKE PERFORMANCE	7	GOOD	0
ENGINE NOISE	6	NORMAL SOUND	0
IGNITION SYSTEM	7	GOOD CONDITION	0
SUSPENSION PERFORMANCE	6	AVERAGE	0
SUSPENSION FRONT SHOCKS	6	AVERAGE CONDITION	0
SUSPENSION REAR SHOCKS	6	AVERAGE CONDITION	0
TRANSMISSION ENGAGE	7	GOOD	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0
CLUTCH PERFORMANCE	0	N/A	0



IMAGES




WHEEL

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7	GOOD TREAD CONDITION	0
SPARE TYRE (YES)	8	GOOD CONDITION	0
WHEEL ASSEMBLY (ALLOY RIM)	6	NO DAMAGE	0

 IMAGES



 HOOD



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	6	AVERAGE CONDITION	0
RH APRON	6	AVERAGE CONDITION	0
RADIATOR	7	WORKING GOOD	0
WIRING	6	NO DAMAGE	0
BATTERY	6	AVERAGE CONDITION	0
BRAKE FLUID LEVEL	7	MAXIMUM	0
ENGINE OIL	6	AVERAGE CONDITION	0
COOLANT LEVEL	7	MAXIMUM	0
BRAKE & COOLANT HOSE PIPES	6	NO DAMAGE	0
UNDERCARRIAGE	6	NO DAMAGE	0
EXHAUST SYSTEM	6	WORKING FINE	0

 IMAGES





Ordered by: caravan car | Inspected date: 2019-05-14

Order Id: 71484

Overall Score  **6/10**



3,24,952

 **EXTERIOR**

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7	GOOD CONDITION	0
FRONT BUMPER	7	GOOD CONDITION	0
HEAD LIGHTS	7	GOOD CONDITION	0
GRILLE	6	NO DAMAGE	0
TURN SIGNAL	7	GOOD CONDITION	0
HOOD	7	GOOD CONDITION	0
PILLAR	7	GOOD CONDITION	0
FRONT WINDSHIELD	7	GOOD CONDITION	0
SIDE VIEW MIRRORS	6	NO DAMAGE	0
LH FENDER	7	GOOD CONDITION	0
LH FRONT DOOR	7	GOOD CONDITION	0
LH REAR DOOR	7	GOOD CONDITION	0
LH RUNNING BOARD	7	GOOD CONDITION	0
LH QUARTER PANEL	7	GOOD CONDITION	0
FUEL LID	7	GOOD CONDITION	0
REAR WINDSHIELD	6	NO DAMAGE	0
REAR BUMPER	7	GOOD CONDITION	0
TAIL LIGHT	6	NO DAMAGE	0
TRUNK LID/TAIL GATE	7	GOOD CONDITION	0
RH QUARTER PANEL	7	GOOD CONDITION	0
RH RUNNING BOARD	6	NO DAMAGE	0
RH REAR DOOR	7	GOOD CONDITION	0
RH FRONT DOOR	7	GOOD CONDITION	0
RH FENDER	7	GOOD CONDITION	0

Ordered by: caravan car | Inspected date: 2019-05-14

Order Id: 71484

Overall Score **6/10**



3,24,952




EXTERIOR (CONTINUED)

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
BODY RUST	6	NO RUST	0
ROOF (REGULAR)	7	GOOD CONDITION	0
PAINT CONDITION	7	GOOD	0
FOG LAMPS	5	RH LAMP NEED TO REPLACE	400
LUGGAGE COMPARTMENT LIGHT	0	N/A	0

IMAGES





NEED ATTENTION



DOCUMENTS



DESCRIPTION

good car condition

Ordered by: caravan car | Inspected date: 2019-05-14

Order Id: 71484

Overall Score











6/10



3,24,952

IMAGES





Ordered by: caravan car | Inspected date: 2019-05-14

Order Id: 71484

Overall Score



6/10



3,24,952

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.