

# ECO INSPECTION CERTIFICATE

Premium

Order ID : 73311

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Rahul	Inspection Date : 2019-05-16	Location : GHAZIABAD
-----------------------	---------------------------------	-------------------------

## 5/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 109 does not need attention
- ✓ 1 Owner , 3 Years Vehicle Age
- ✓ No Accidental History

**Inspected By**

✓ **Verified Technician**

286+ vehicle inspected

1+ years experience

Kishan Kumar

## Maruti Suzuki Swift LDI, 2016



### VEHICLE INFORMATION

MAKE	MARUTI SUZUKI	ENGINE NUMBER	26591
MODEL	SWIFT	REGISTRATION NO.	DL14CC4566
MFG. DATE	12/2015	VIN/CHASSIS NUMBER	15932
TRIM	LDI	ODOMETER READING	40015
COLOR	SILVER	INSURANCE EXPIRY	2019-5-16
BODY TYPE	HATCHBACK	VEHICLE PASSING	PRIVATE
FUEL TYPE	DIESEL	ENGINE SOUND LINK	<a href="#">LISTEN ENGINE SOUND</a>

### KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	20,000	RC COPY AVAILABLE	ORIGINAL	BANK HYPOTHECATION	NO
DENT	NO	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

**4,54,564**




### ECO SCORE & REPAIR COST ESTIMATE

#### ECO SCORE

Interior	<div style="width: 60%;"></div>	6 / 10
Wheel	<div style="width: 50%;"></div>	5 / 10
Test Drive	<div style="width: 50%;"></div>	5 / 10
Exterior	<div style="width: 60%;"></div>	6 / 10
Hood	<div style="width: 60%;"></div>	6 / 10

#### TOTAL ESTIMATE SPEND 14,700



Ordered by: Rahul | Inspected date: 2019-05-16

Order Id: 73311

Overall Score  **5/10**



**4,54,564**

## INTERIOR

**6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7		0
DOOR HINGES	7		0
CARPET & FLOOR MAT	7		0
SEAT & SEAT BELT	7		0
DASHBOARD & INSTRUMENT PANEL	7		0
HORN	7		0
HANDBRAKE	7		0
PEDALS	7		0
A/C VENTS & HEATER	7		0
CUP HOLDERS	7		0
ODOMETER	7		0
POWER WINDOWS (YES - FRONT ONLY)	7		0
HAZARD LIGHT	7		0
SPEAKERS & MUSIC SYSTEM	0	NOT AVAILABLE MUSIC SYSTEM NEED TO NEW MUSIC SYSTEM	5000
STEERING-MOUNTED CONTROLS	0	NA	0
CENTRAL LOCK	5	NOT WORKING NEED TO CHECK AND REPAIR	1000
NAVIGATION (YES)	0	NA	0

## IMAGES



Ordered by: Rahul | Inspected date: 2019-05-16

Order Id: 73311

Overall Score



5/10



4,54,564

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	6	AVERAGE CONDITION	0
CLUTCH PERFORMANCE	7		0
ENGINE NOISE	6	AVERAGE CONDITION	0
IGNITION SYSTEM	7		0
SUSPENSION PERFORMANCE	7		0
SUSPENSION FRONT SHOCKS	7		0
SUSPENSION REAR SHOCKS	7		0
TRANSMISSION ENGAGE	7		0
BRAKE PERFORMANCE	4	BRAKE HARD NEED TO BE REPAIR	2500
CRUISE CONTROL (YES)	0	NA	0
REAR PARKING SENSORS (YES)	0	NA	0
REAR VIEW CAMERA (YES)	0	NA	0


IMAGES



WHEEL

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7		0
WHEEL ASSEMBLY (STEEL RIM)	7		0
SPARE TYRE (YES)	0	NOT AVAILABLE SPARE TIRE NEED TO NEW SPARE TIRE	4000

 IMAGES



 NEED ATTENTION 





 HOOD



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7		0
RH APRON	7		0
RADIATOR	6	AVERAGE CONDITION	0
WIRING	6	AVERAGE CONDITION	0
BATTERY	7		0
BRAKE FLUID LEVEL	6	AVERAGE CONDITION	0
ENGINE OIL	6	AVERAGE VISCOSITY	0
COOLANT LEVEL	6	MINIMUM LEVEL	0
BRAKE & COOLANT HOSE PIPES	6	AVERAGE CONDITION	0
UNDERCARRIAGE	6	AVERAGE CONDITION	0
EXHAUST SYSTEM	6	AVERAGE CONDITION	0

 IMAGES



Ordered by: Rahul | Inspected date: 2019-05-16

Order Id: 73311

Overall Score  **5/10**



**4,54,564**

 **EXTERIOR**

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7		0
FRONT BUMPER	6	SCRATCHES	100
HEAD LIGHTS	6	AVERAGE CONDITION	0
GRILLE	7		0
TURN SIGNAL	7		0
HOOD	6	AVERAGE CONDITION	0
PILLAR	6	AVERAGE CONDITION	0
FRONT WINDSHIELD	6	AVERAGE CONDITION	0
LH FENDER	6	AVERAGE CONDITION	0
LH FRONT DOOR	6	SCRATCHES	200
LH REAR DOOR	7		0
LH RUNNING BOARD	7		0
LH QUARTER PANEL	7		0
FUEL LID	7		0
REAR WINDSHIELD	6	AVERAGE CONDITION	0
TAIL LIGHT	7		0
TRUNK LID/TAIL GATE	7		0
LUGGAGE COMPARTMENT LIGHT	7		0
RH QUARTER PANEL	6	SCRATCHES	100
RH RUNNING BOARD	7		0
RH REAR DOOR	6	SCRATCHES	150
RH FRONT DOOR	7		0
RH FENDER	7		0
BODY RUST	7		0

Ordered by: Rahul | Inspected date: 2019-05-16

Order Id: 73311

Overall Score **5/10**



**4,54,564**

## EXTERIOR (CONTINUED)

**6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
ROOF (REGULAR)	7		0
PAINT CONDITION	7		0
FOG LAMPS	5	NOT WORKING NEED TO CHECK AND REPAIR	350
SIDE VIEW MIRRORS	4	LEFT SIDE MIRROR BROKEN NEED TO BE CHANGE	800
REAR BUMPER	5	SCRATCHES NEED TO BE REAPIR	500


## IMAGES







NEED ATTENTION ⚠



DOCUMENTS



DESCRIPTION

all scratches and service due and brake hard need to be repair and spare tire, and music system not a

Ordered by: Rahul | Inspected date: 2019-05-16

Order Id: 73311

Overall Score







5/10



4,54,564

IMAGES





Ordered by: Rahul | Inspected date: 2019-05-16

Order Id: 73311

Overall Score



5/10



4,54,564

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.