

# ECO INSPECTION CERTIFICATE

Premium


Order ID : 73309

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Rahul	Inspection Date : 2019-05-16	Location : GHAZIABAD
-----------------------	---------------------------------	-------------------------


## 6/10



**Overall Score**

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 118 does not need attention
- ✓ 1 Owner , 7 Years Vehicle Age
- ✓ No Accidental History

**Inspected By**



✓ **Verified Technician**

285+ vehicle inspected

1+ years experience

Kishan Kumar

## Hyundai I20 SPORTZ 1.4 CRDI, 2012



VEHICLE INFORMATION			
MAKE	HYUNDAI	ENGINE NUMBER	45000
MODEL	I20	REGISTRATION NO.	DL7CP0319
MFG. DATE	06/2012	VIN/CHASSIS NUMBER	42968
TRIM	SPORTZ 1.4 CRDI	ODOMETER READING	93653
COLOR	BRONZE	INSURANCE EXPIRY	2019-5-16
BODY TYPE	HATCHBACK	VEHICLE PASSING	PRIVATE
FUEL TYPE	DIESEL	ENGINE SOUND LINK	<a href="#">LISTEN ENGINE SOUND</a>

## KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	15,000	RC COPY AVAILABLE	ORIGINAL	BANK HYPOTHECATION	NO
DENT	NO	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



orangebookvalue.com

Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.

With this evaluation, the Fair Market Price for this vehicle comes to be:

# 3,37,011




Very Good Condition

## ECO SCORE & REPAIR COST ESTIMATE

**ECO SCORE**

Interior	<div style="width: 70%; background-color: #27ae60; height: 10px;"></div>	<b>7 / 10</b>
Wheel	<div style="width: 70%; background-color: #27ae60; height: 10px;"></div>	<b>7 / 10</b>
Test Drive	<div style="width: 60%; background-color: #f1c40f; height: 10px;"></div>	<b>6 / 10</b>
Exterior	<div style="width: 70%; background-color: #27ae60; height: 10px;"></div>	<b>7 / 10</b>
Hood	<div style="width: 70%; background-color: #27ae60; height: 10px;"></div>	<b>7 / 10</b>

**TOTAL ESTIMATE SPEND 500**



Interior: 0, Wheel: 0, Test Drive: 0, Exterior: 500, Hood: 0

Ordered by: Rahul | Inspected date: 2019-05-16

Order Id: 73309

Overall Score



6/10



3,37,011



## INTERIOR




7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7		0
DOOR HINGES	7		0
CARPET & FLOOR MAT	7		0
SEAT & SEAT BELT	7		0
DASHBOARD & INSTRUMENT PANEL	7		0
HORN	7		0
SPEAKERS & MUSIC SYSTEM	7		0
HANDBRAKE	7		0
STEERING-MOUNTED CONTROLS	7		0
PEDALS	7		0
CENTRAL LOCK	7		0
A/C VENTS & HEATER	7		0
CUP HOLDERS	7		0
ODOMETER	7		0
POWER WINDOWS (YES)	7		0
HAZARD LIGHT	7		0
NAVIGATION (YES)	0	NA	0



## IMAGES



Ordered by: Rahul | Inspected date: 2019-05-16

Order Id: 73309

Overall Score **6/10**




**3,37,011**

## TEST DRIVE

**6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7		0
BRAKE PERFORMANCE	7		0
CLUTCH PERFORMANCE	7		0
ENGINE NOISE	7		0
IGNITION SYSTEM	7		0
SUSPENSION PERFORMANCE	6	AVERAGE CONDITION	0
SUSPENSION FRONT SHOCKS	6	AVERAGE CONDITION	0
SUSPENSION REAR SHOCKS	6	AVERAGE CONDITION	0
TRANSMISSION ENGAGE	7		0
REAR PARKING SENSORS (YES)	7		0
REAR VIEW CAMERA (YES)	7		0
CRUISE CONTROL (YES)	0	NA	0

## IMAGES




## WHEEL

**7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7		0
SPARE TYRE (YES)	7		0
WHEEL ASSEMBLY (ALLOY RIM)	7		0

 IMAGES




 HOOD



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7		0
RH APRON	7		0
RADIATOR	6	AVERAGE CONDITION	0
WIRING	6	AVERAGE CONDITION	0
BATTERY	7		0
BRAKE FLUID LEVEL	7		0
ENGINE OIL	7		0
COOLANT LEVEL	7		0
BRAKE & COOLANT HOSE PIPES	7		0
UNDERCARRIAGE	7		0
EXHAUST SYSTEM	7		0

 IMAGES



Ordered by: Rahul | Inspected date: 2019-05-16

Order Id: 73309

Overall Score  **6/10**



**3,37,011**

 **EXTERIOR**

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7		0
FRONT BUMPER	6	SCRATCHES	150
HEAD LIGHTS	7		0
GRILLE	7		0
TURN SIGNAL	7		0
HOOD	6	AVERAGE CONDITION	0
PILLAR	7		0
FRONT WINDSHIELD	6	AVERAGE CONDITION	0
SIDE VIEW MIRRORS	7		0
LH FENDER	7		0
LH FRONT DOOR	7		0
LH REAR DOOR	7		0
LH RUNNING BOARD	7		0
LH QUARTER PANEL	7		0
FUEL LID	7		0
REAR WINDSHIELD	7		0
REAR BUMPER	6	SCRATCHES	150
TAIL LIGHT	7		0
TRUNK LID/TAIL GATE	7		0
LUGGAGE COMPARTMENT LIGHT	7		0
RH QUARTER PANEL	6	SCRATCHES	100
RH RUNNING BOARD	7		0
RH REAR DOOR	7		0
RH FRONT DOOR	7		0



Ordered by: Rahul | Inspected date: 2019-05-16

Order Id: 73309

Overall Score



6/10



3,37,011

## EXTERIOR (CONTINUED)




7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FENDER	7		0
BODY RUST	7		0
ROOF (REGULAR)	7		0
PAINT CONDITION	7		0
FOG LAMPS	5	LEFT FOG LAMP NOT WORKING NEED TO CHECK AND REPAIR	100

## IMAGES






## NEED ATTENTION ⚠



## DOCUMENTS



## DESCRIPTION

all body minor scratches



Ordered by: Rahul | Inspected date: 2019-05-16

Order Id: 73309

Overall Score



6/10




3,37,011

IMAGES







Ordered by: Rahul | Inspected date: 2019-05-16

Order Id: 73309

Overall Score



6/10



3,37,011

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.