

ECO INSPECTION CERTIFICATE

Premium

Order ID : 73625

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Gaurav	Inspection Date : 2019-05-16	Location : SEC40 GGN	Inspected By Verified Technician 725+ vehicle inspected 1+ years experience Gagan Gurawaliya
------------------------	---------------------------------	-------------------------	---

7/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 121 does not need attention
- ✓ 1 Owner , 2 Years Vehicle Age
- ✓ No Accidental History

Toyota Fortuner 2.8 4X2 AT, 2017



VEHICLE INFORMATION			
MAKE	TOYOTA	ENGINE NUMBER	120128
MODEL	FORTUNER	REGISTRATION NO.	DL8CAR9309
MFG. DATE	08/2017	VIN/CHASSIS NUMBER	620187
TRIM	2.8 4X2 AT	ODOMETER READING	36163
COLOR	WHITE	INSURANCE EXPIRY	2019-8-22
BODY TYPE	SUV	VEHICLE PASSING	PRIVATE
FUEL TYPE	DIESEL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS			
FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO
TYRE LIFE REMAINING (KM)	30,000	RC COPY AVAILABLE	ORIGINAL
DENT	NO	INSURANCE COPY AVAILABLE	YES (ZERO DEPRECIATION)
		SERVICE LOGS AVAILABLE	NO
		BANK HYPOTHECATION	YES
		BANK NOC	NO

Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

28,79,484

Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE		TOTAL ESTIMATE SPEND 4,100	
Interior	<div style="width: 80%;"></div> 8 / 10	Interior	0
Wheel	<div style="width: 70%;"></div> 7 / 10	Wheel	0
Test Drive	<div style="width: 80%;"></div> 8 / 10	Test Drive	0
Exterior	<div style="width: 80%;"></div> 8 / 10	Exterior	4,100
Hood	<div style="width: 80%;"></div> 8 / 10	Hood	0

Ordered by: Gaurav | Inspected date: 2019-05-16

Order Id: 73625

Overall Score



7/10



28,79,484



INTERIOR







8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	8	GOOD CONDITION	0
DOOR HINGES	8	GOOD CONDITION	0
CARPET & FLOOR MAT	8		0
SEAT & SEAT BELT	8	GOOD CONDITION	0
DASHBOARD & INSTRUMENT PANEL	8	GOOD CONDITION	0
HORN	8	GOOD CONDITION	0
SPEAKERS & MUSIC SYSTEM	8	GOOD CONDITION	0
HANDBRAKE	8	GOOD CONDITION	0
STEERING-MOUNTED CONTROLS	8	GOOD CONDITION	0
PEDALS	8	GOOD CONDITION	0
CENTRAL LOCK	8	GOOD CONDITION	0
A/C VENTS & HEATER	8	GOOD CONDITION	0
CUP HOLDERS	8	GOOD CONDITION	0
NAVIGATION (YES)	8	GOOD CONDITION	0
ODOMETER	8	GOOD CONDITION	0
POWER WINDOWS (YES)	8	GOOD CONDITION	0
HAZARD LIGHT	8	GOOD CONDITION	0



IMAGES



Ordered by: Gaurav | Inspected date: 2019-05-16

Order Id: 73625

Overall Score **7/10**





28,79,484

TEST DRIVE

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	8	GOOD CONDITION	0
BRAKE PERFORMANCE	8	GOOD CONDITION	0
CLUTCH PERFORMANCE	8	GOOD CONDITION	0
ENGINE NOISE	8	GOOD CONDITION	0
IGNITION SYSTEM	8	GOOD CONDITION	0
SUSPENSION PERFORMANCE	8	GOOD CONDITION	0
SUSPENSION FRONT SHOCKS	8	GOOD CONDITION	0
SUSPENSION REAR SHOCKS	8	GOOD CONDITION	0
TRANSMISSION ENGAGE	8	GOOD CONDITION	0
CRUISE CONTROL (YES)	8	GOOD CONDITION	0
REAR PARKING SENSORS (YES)	8	GOOD CONDITION	0
REAR VIEW CAMERA (YES)	8	GOOD CONDITION	0

IMAGES



WHEEL

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7	GOOD CONDITION	0
SPARE TYRE (YES)	7	GOOD CONDITION	0
WHEEL ASSEMBLY (ALLOY RIM)	7	GOOD CONDITION	0

 IMAGES



 HOOD



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	8	GOOD CONDITION	0
RH APRON	8	GOOD CONDITION	0
RADIATOR	8	GOOD CONDITION	0
WIRING	8	GOOD CONDITION	0
BATTERY	8	GOOD CONDITION	0
BRAKE FLUID LEVEL	8	MAX	0
ENGINE OIL	8	MAX	0
COOLANT LEVEL	8	MAX	0
BRAKE & COOLANT HOSE PIPES	8	GOOD CONDITION	0
UNDERCARRIAGE	8	GOOD CONDITION	0
EXHAUST SYSTEM	8	GOOD CONDITION	0

 IMAGES



Ordered by: Gaurav | Inspected date: 2019-05-16

Order Id: 73625

Overall Score



7/10



28,79,484



EXTERIOR



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	8	GOOD CONDITION	0
FRONT BUMPER	6	MINOR SCRATCHES	1000
HEAD LIGHTS	8	GOOD CONDITION	0
GRILLE	8	GOOD CONDITION	0
TURN SIGNAL	8	GOOD CONDITION	0
FOG LAMPS	8	GOOD CONDITION	0
HOOD	8	GOOD CONDITION	0
PILLAR	8	GOOD CONDITION	0
FRONT WINDSHIELD	7	GOOD VISIBILITY	0
SIDE VIEW MIRRORS	8	GOOD CONDITION	0
LH FENDER	6	MINOR SCRATCHES	800
LH FRONT DOOR	8	GOOD CONDITION	0
LH REAR DOOR	8	GOOD CONDITION	0
LH RUNNING BOARD	8	GOOD CONDITION	0
LH QUARTER PANEL	6	MINOR SCRATCHES	800
FUEL LID	8	GOOD CONDITION	0
REAR WINDSHIELD	8	GOOD VIDIBILITY	0
REAR BUMPER	6	MINOR SCRATCHES	1000
TAIL LIGHT	8	GOOD CONDITION	0
TRUNK LID/TAIL GATE	8	GOOD CONDITION	0
LUGGAGE COMPARTMENT LIGHT	8	GOOD CONDITION	0
RH QUARTER PANEL	6	MINOR SCRATCHES	500
RH RUNNING BOARD	8	GOOD CONDITION	0
RH REAR DOOR	8	GOOD CONDITION	0

Ordered by: Gaurav | Inspected date: 2019-05-16

Order Id: 73625

Overall Score **7/10**



28,79,484

EXTERIOR (CONTINUED)

8/10




INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	8	GOOD CONDITION	0
RH FENDER	8	GOOD CONDITION	0
BODY RUST	8	GOOD CONDITION	0
ROOF (REGULAR)	8	GOOD CONDITION	0
PAINT CONDITION	8	GOOD CONDITION	0

IMAGES





DOCUMENTS



DESCRIPTION

minor scratches

Ordered by: Gaurav | Inspected date: 2019-05-16

Order Id: 73625

Overall Score










7/10



28,79,484

 IMAGES





Ordered by: Gaurav | Inspected date: 2019-05-16

Order Id: 73625

Overall Score



7/10



28,79,484

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.