

ECO INSPECTION CERTIFICATE

Premium

Order ID : 74601

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.


Ordered By : RAJENDRA KUMAR	Inspection Date : 2019-05-17	Location : GHAZIABAD
--------------------------------	---------------------------------	-------------------------

5/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 111 does not need attention
- ✓ 2 Owners , 10 Years Vehicle Age
- ✓ No Accidental History

Inspected By



✓ **Verified Technician**
293+ vehicle inspected
1+ years experience

Kishan Kumar

Hyundai I20 MAGNA 1.2, 2009



VEHICLE INFORMATION			
MAKE	HYUNDAI	ENGINE NUMBER	51637
MODEL	I20	REGISTRATION NO.	UP16X4084
MFG. DATE	05/2009	VIN/CHASSIS NUMBER	53327
TRIM	MAGNA 1.2	ODOMETER READING	58209
COLOR	GREY	INSURANCE EXPIRY	2019-5-17
BODY TYPE	HATCHBACK	VEHICLE PASSING	PRIVATE
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	30,000	RC COPY AVAILABLE	ORIGINAL	BANK HYPOTHECATION	NO
DENT	NO	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.
With this evaluation, the Fair Market Price for this vehicle comes to be:

1,82,686




Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 60%;"></div>	6 / 10
Wheel	<div style="width: 70%;"></div>	7 / 10
Test Drive	<div style="width: 40%;"></div>	4 / 10
Exterior	<div style="width: 60%;"></div>	6 / 10
Hood	<div style="width: 70%;"></div>	7 / 10

TOTAL ESTIMATE SPEND 10,750



Ordered by: RAJENDRA KUMAR | Inspected date: 2019-05-17

Order Id: 74601

Overall Score  **5/10**



1,82,686

INTERIOR

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	6	AVERAGE CONDITION	0
DOOR HINGES	6	AVERAGE CONDITION	0
CARPET & FLOOR MAT	6	AVERAGE CONDITION	0
SEAT & SEAT BELT	7		0
DASHBOARD & INSTRUMENT PANEL	7		0
HORN	7		0
SPEAKERS & MUSIC SYSTEM	7		0
HANDBRAKE	7		0
PEDALS	7		0
CENTRAL LOCK	7		0
A/C VENTS & HEATER	6	AVERAGE CONDITION	0
CUP HOLDERS	7		0
ODOMETER	7		0
POWER WINDOWS (YES)	7		0
HAZARD LIGHT	7		0
STEERING-MOUNTED CONTROLS	0	NA	0
NAVIGATION (YES)	0	NA	0

IMAGES



Ordered by: RAJENDRA KUMAR | Inspected date: 2019-05-17

Order Id: 74601

Overall Score



5/10



1,82,686

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	6	AVERAGE CONDITION	0
BRAKE PERFORMANCE	6	AVERAGE CONDITION	0
IGNITION SYSTEM	7		0
SUSPENSION PERFORMANCE	6	AVERAGE CONDITION	0
SUSPENSION FRONT SHOCKS	6	AVERAGE CONDITION	0
SUSPENSION REAR SHOCKS	6	AVERAGE CONDITION	0
TRANSMISSION ENGAGE	7		0
CLUTCH PERFORMANCE	4	CLUTCH HARD NEED TO BE OVERHALL	5000
ENGINE NOISE	5	ENGINE NOISE NEED TO CHECK AND REPAIR	4000
CRUISE CONTROL (YES)	0	NA	0
REAR PARKING SENSORS (YES)	0	NA	0
REAR VIEW CAMERA (YES)	0	NA	0

 IMAGES

 WHEEL

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	8		0
SPARE TYRE (YES)	7		0
WHEEL ASSEMBLY (STEEL RIM)	6	AVERAGE CONDITION	0

 IMAGES




 HOOD



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	6	AVERAGE CONDITION	0
RH APRON	6	AVERAGE CONDITION	0
RADIATOR	6	AVERAGE CONDITION	0
WIRING	6	AVERAGE CONDITION	0
BATTERY	7		0
BRAKE FLUID LEVEL	7		0
ENGINE OIL	7		0
COOLANT LEVEL	7		0
BRAKE & COOLANT HOSE PIPES	6	AVERAGE CONDITION	0
UNDERCARRIAGE	7		0
EXHAUST SYSTEM	7		0

 IMAGES



Ordered by: RAJENDRA KUMAR | Inspected date: 2019-05-17

Order Id: 74601

Overall Score



5/10



1,82,686



EXTERIOR



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7		0
FRONT BUMPER	7		0
GRILLE	7		0
TURN SIGNAL	7		0
HOOD	6	AVERAGE CONDITION	0
PILLAR	6	AVERAGE CONDITION	0
FRONT WINDSHIELD	6	AVERAGE CONDITION	0
SIDE VIEW MIRRORS	6	AVERAGE CONDITION	0
LH FENDER	7		0
LH FRONT DOOR	7		0
LH REAR DOOR	7		0
LH RUNNING BOARD	7		0
LH QUARTER PANEL	7		0
FUEL LID	7		0
REAR WINDSHIELD	6	AVERAGE CONDITION	0
REAR BUMPER	7		0
TRUNK LID/TAIL GATE	7		0
LUGGAGE COMPARTMENT LIGHT	7		0
RH QUARTER PANEL	7		0
RH RUNNING BOARD	7		0
RH REAR DOOR	6	SCRATCHES	200
RH FRONT DOOR	6	SCRATCHES	200
RH FENDER	7		0
BODY RUST	6	AVERAGE CONDITION	0

Ordered by: RAJENDRA KUMAR | Inspected date: 2019-05-17

Order Id: 74601

Overall Score



5/10



1,82,686

EXTERIOR (CONTINUED)



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
ROOF (REGULAR)	6	AVERAGE CONDITION	0
PAINT CONDITION	6	AVERAGE CONDITION	0
HEAD LIGHTS	5	RIGHT HEAD LAMP NOT WORKING NEED TO CHECK AND REPAIR	150
FOG LAMPS	0	NA	0
TAIL LIGHT	5	LEFT TAIL LAMP BROKEN NEED TO BE CHANGE	1200

IMAGES




NEED ATTENTION





DOCUMENTS



DESCRIPTION

all body minor scratches and clutch hard need to overhall and engine noise need to repair left tail

Ordered by: RAJENDRA KUMAR | Inspected date: 2019-05-17

Order Id: 74601

Overall Score




5/10



1,82,686

IMAGES



Ordered by: RAJENDRA KUMAR | Inspected date: 2019-05-17

Order Id: 74601

Overall Score



5/10



1,82,686

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.