

ECO INSPECTION CERTIFICATE

Premium

Order ID : 73339

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Tayyab Quershi	Inspection Date : 2019-05-16	Location : JOGESHWARI WEST	Inspected By Verified Technician 221+ vehicle inspected 1+ years experience Shashank Mahadik
--------------------------------	---------------------------------	-------------------------------	--

6/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 118 does not need attention
- ✓ 1 Owner , 10 Years Vehicle Age
- ✓ No Accidental History

Hyundai Accent EXECUTIVE, 2009



VEHICLE INFORMATION

MAKE	HYUNDAI	ENGINE NUMBER	
MODEL	ACCENT	REGISTRATION NO.	MH04ED5819
MFG. DATE	09/2009	VIN/CHASSIS NUMBER	251671
TRIM	EXECUTIVE	ODOMETER READING	45946
COLOR	S BEIGE	INSURANCE EXPIRY	2019-2-12
BODY TYPE	SEDAN	VEHICLE PASSING	PRIVATE
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	10,000	RC COPY AVAILABLE	ORIGINAL	BANK HYPOTHECATION	NO
DENT	NO	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

1,57,303




ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 60%;"></div>	6 / 10
Wheel	<div style="width: 60%;"></div>	6 / 10
Test Drive	<div style="width: 70%;"></div>	7 / 10
Exterior	<div style="width: 60%;"></div>	6 / 10
Hood	<div style="width: 60%;"></div>	6 / 10

TOTAL ESTIMATE SPEND 3,000



Ordered by: tayyab quershi | Inspected date: 2019-05-16

Order Id: 73339

Overall Score



6/10



1,57,303



INTERIOR







6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7	GOOD CONDITION	0
DOOR HINGES	6	NO DAMAGE	0
CARPET & FLOOR MAT	6	AVERAGE	0
SEAT & SEAT BELT	6	AVERAGE CONDITION	0
DASHBOARD & INSTRUMENT PANEL	6	AVERAGE CONDITION	0
HORN	6	PROPER SOUND	0
SPEAKERS & MUSIC SYSTEM	6	WORKING FINE	0
HANDBRAKE	6	WORKING PROPERLY	0
PEDALS	6	WORKING PROPERLY	0
CENTRAL LOCK	6	WORKING FINE	0
A/C VENTS & HEATER	6	WORKING FINE	0
CUP HOLDERS	6	NO DAMAGE	0
NAVIGATION (NO)	10		0
ODOMETER	7	GOOD	0
POWER WINDOWS (YES)	7	ALL WORKING GOOD	0
HAZARD LIGHT	7	WORKING GOOD	0
STEERING-MOUNTED CONTROLS	0	N/A	0



IMAGES



Ordered by: tayyab quershi | Inspected date: 2019-05-16

Order Id: 73339

Overall Score



6/10



1,57,303


INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7	GOOD	0
BRAKE PERFORMANCE	6	WORKING FINE	0
CLUTCH PERFORMANCE	6	WORKING PROPERLY	0
IGNITION SYSTEM	7	GOOD CONDITION	0
SUSPENSION PERFORMANCE	6	FINE	0
SUSPENSION FRONT SHOCKS	6	NO DAMAGE	0
SUSPENSION REAR SHOCKS	6	NO DAMAGE	0
TRANSMISSION ENGAGE	6	WORKING FINE	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0
ENGINE NOISE	4	AVERAGE NOISE , NEED TO REPAIR FOR GASKET LEAKGE	3000

 IMAGES

 WHEEL

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	6	AVERAGE CONDITION	0
SPARE TYRE (YES)	6	AVERAGE CONDITION	0
WHEEL ASSEMBLY (STEEL RIM)	6	NO DAMAGE	0

 IMAGES



 HOOD




6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	6	AVERAGE CONDITION	0
RH APRON	6	AVERAGE CONDITION	0
RADIATOR	6	WORKING PROPERLY	0
WIRING	6	NO DAMAGE	0
BATTERY	7	GOOD CONDITION	0
BRAKE FLUID LEVEL	7	MAXIMUM	0
ENGINE OIL	6	ACCEPTABLE	0
COOLANT LEVEL	7	MAXIMUM	0
BRAKE & COOLANT HOSE PIPES	6	AVERAGE CONDITION	0
UNDERCARRIAGE	6	NO DAMAGE	0
EXHAUST SYSTEM	6	WORKING FINE	0

 IMAGES





Ordered by: tayyab quershi | Inspected date: 2019-05-16

Order Id: 73339

Overall Score  **6/10**



1,57,303

 **EXTERIOR**

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7	GOOD CONDITION	0
FRONT BUMPER	7	GOOD CONDITION	0
HEAD LIGHTS	7	GOOD CONDITION	0
GRILLE	7	GOOD CONDITION	0
TURN SIGNAL	7	GOOD CONDITION	0
HOOD	6	AVERAGE CONDITION	0
PILLAR	6	AVERAGE CONDITION	0
FRONT WINDSHIELD	6	AVERAGE CONDITION	0
SIDE VIEW MIRRORS	6	NO DAMAGE	0
LH FENDER	7	GOOD CONDITION	0
LH FRONT DOOR	7	GOOD CONDITION	0
LH REAR DOOR	7	GOOD CONDITION	0
LH RUNNING BOARD	6	AVERAGE CONDITION	0
LH QUARTER PANEL	7	GOOD CONDITION	0
FUEL LID	7	GOOD	0
REAR WINDSHIELD	6	NO DAMAGE	0
REAR BUMPER	7	GOOD CONDITION	0
TAIL LIGHT	7	GOOD CONDITION	0
TRUNK LID/TAIL GATE	7	GOOD CONDITION	0
LUGGAGE COMPARTMENT LIGHT	7	GOOD	0
RH QUARTER PANEL	7	GOOD CONDITION	0
RH RUNNING BOARD	6	ACCEPTABLE CONDITION	0
RH REAR DOOR	7	GOOD CONDITION	0
RH FRONT DOOR	7	GOOD CONDITION	0

Ordered by: tayyab quersh | Inspected date: 2019-05-16

Order Id: 73339

Overall Score **6/10**



1,57,303

EXTERIOR (CONTINUED)

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FENDER	7	GOOD CONDITION	0
BODY RUST	6	NO RUST	0
ROOF (REGULAR)	7	GOOD CONDITION	0
PAINT CONDITION	7	GOOD	0
FOG LAMPS	0	N/A	0

IMAGES





 **NEED ATTENTION** 



 **DOCUMENTS**



 **DESCRIPTION**

Engine gasket leakage , Body condition is good overall OK

Ordered by: tayyab quersh | Inspected date: 2019-05-16

Order Id: 73339

Overall Score




6/10



1,57,303

IMAGES















REGN. NO : MH04ED5819

REG. DT: 02/12/2009 03 SMC 01
 CH. NO : MALCG41GRM254024 MFG CD : HYUNDAI 08
 E NO : CHEERDANCH COLOUR : S BEIGE 05
 CLASS : LMV

NAME : NEELAM VAITY
 SWD OF : RAMESH
 ADDRESS : 5176 CHAYIA NAGESHWARI TEMPLE RD
 NAGHOLI NALLASOPARA W DIST THANE
 VASAI

HPL/LEASE : ACCENT GLE BS III Registering Authority
 MODEL : ACCENT GLE BS III RTO Thane
 BODY : SALOON NO. OF CYL : 4 UNLADEN WT : 1038
 WHEEL BASE : 2450 SEATING C : 5
 MFG DT : 09/2009 SEATING C : 5
 FUEL : PETROL STANDING C : 1405
 REG UP TO : 01/12/2024 CUCAP : 1405
 TAX UP TO : LTT CAISD SLNO : 9402394 Signature



Ordered by: tayyab quershi | Inspected date: 2019-05-16

Order Id: 73339

Overall Score



6/10



1,57,303

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.