


ECO INSPECTION CERTIFICATE

Premium

Order ID : 72055

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Bablu	Inspection Date : 2019-05-17	Location : MIRA ROAD	Inspected By  Praveen Singh
-----------------------	---------------------------------	-------------------------	--

6/10
Overall Score

- Evaluated across 5 segments
- Covered 121+ checkpoints
- 98 does not need attention
- 2 Owners , 11 Years Vehicle Age
- No Accidental History

Verified Technician
202+ vehicle inspected
1+ years experience

Toyota Innova 2.5 V 7 STR, 2008



VEHICLE INFORMATION

MAKE	TOYOTA	ENGINE NUMBER	
MODEL	INNOVA	REGISTRATION NO.	MH43V7168
MFG. DATE	05/2008	VIN/CHASSIS NUMBER	MBJ11JV4007134978
TRIM	2.5 V 7 STR	ODOMETER READING	184734
COLOR	L GREEN	INSURANCE EXPIRY	2018-11-30
BODY TYPE	SUV	VEHICLE PASSING	PRIVATE
FUEL TYPE	DIESEL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	1,000	RC COPY AVAILABLE	ORIGINAL	BANK HYPOTHECATION	YES
DENT	YES	INSURANCE COPY AVAILABLEN	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

3,31,972




ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 60%;"></div>	6 / 10
Wheel	<div style="width: 60%;"></div>	6 / 10
Test Drive	<div style="width: 70%;"></div>	7 / 10
Exterior	<div style="width: 50%;"></div>	5 / 10
Hood	<div style="width: 60%;"></div>	6 / 10

TOTAL ESTIMATE SPEND 56,700



Ordered by: bablu | Inspected date: 2019-05-17

Order Id: 72055

Overall Score



6/10



3,31,972



INTERIOR



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	6	ACCEPTABLE	0
DOOR HINGES	6	HINGE	0
CARPET & FLOOR MAT	6	ACCEPTABLE MAT	0
DASHBOARD & INSTRUMENT PANEL	6	WORKING	0
HORN	6	GOOD SOUND	0
HANDBRAKE	6	PROPER HOLD	0
PEDALS	6	OPERATING	0
CENTRAL LOCK	6	WORKING	0
A/C VENTS & HEATER	6	AVERAGE COOLING	0
CUP HOLDERS	6	AVERAGE	0
NAVIGATION (NO)	10		0
ODOMETER	6	WORKING	0
HAZARD LIGHT	6	WORKING	0
SEAT & SEAT BELT	5	NEED TO REPLACE SEAT	1000
SPEAKERS & MUSIC SYSTEM	5	BROKEN	0
STEERING-MOUNTED CONTROLS	5	NA	0
POWER WINDOWS (YES)	5	NEED TO PUT SWITCH	3000



IMAGES





TEST DRIVE

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	6	AVERAGE	0
BRAKE PERFORMANCE	6	AVERAGE	0
CLUTCH PERFORMANCE	6	AVERAGE	0
ENGINE NOISE	6	MINIMUM NOISE	0
IGNITION SYSTEM	6	WORKING	0
SUSPENSION PERFORMANCE	6	AVERAGE	0
SUSPENSION FRONT SHOCKS	6	MINIMUM SHOCK	0
SUSPENSION REAR SHOCKS	6	MINIMUM SHOCK	0
TRANSMISSION ENGAGE	6	PROPER ENGAGEMENT	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0



IMAGES



WHEEL

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
SPARE TYRE (YES)	6	AVERAGE	0
WHEEL ASSEMBLY (ALLOY RIM)	6	AVERAGE	0
TYRES	5	NEED TO CHANGE ALL TYRE	12000

 IMAGES



 NEED ATTENTION 






 HOOD



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	6	ACCEPTABLE	0
RH APRON	6	ACCEPTABLE	0
RADIATOR	6	WORKING	0
WIRING	6	ACCEPTABLE	0
BATTERY	6	AVERAGE	0
BRAKE FLUID LEVEL	6	MAX LEVEL	0
COOLANT LEVEL	6	MAX LEVEL	0
BRAKE & COOLANT HOSE PIPES	6	NO LEAKAGE	0
UNDERCARRIAGE	6	ACCEPTABLE CONDITION	0
EXHAUST SYSTEM	6	NO SMOKE DETECT	0
ENGINE OIL	5	NEED TO CHANGE	3000

 IMAGES



Ordered by: bablu | Inspected date: 2019-05-17

Order Id: 72055

Overall Score  **6/10**



3,31,972

 **EXTERIOR**

 **5/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
HEAD LIGHTS	6	AVERAGE	0
GRILLE	6	ACCEPTABLE	0
TURN SIGNAL	6	ACCEPTABLE	0
FOG LAMPS	6	NOT WORKING	0
HOOD	6	AVERAGE	0
PILLAR	6	RUSH ON IT	3000
SIDE VIEW MIRRORS	6	AVERAGE	0
FUEL LID	6	AVERAGE	0
REAR WINDSHIELD	6	CLEAR VISIBILITY	0
TRUNK LID/TAIL GATE	6	NEED TO REPAINT & REPAIR	2500
LUGGAGE COMPARTMENT LIGHT	6	NOT AVAILABLE	0
PAINT CONDITION	6	NEED TO REPAINT FULL CAR	0
LICENSE PLATE	5	NEED TO CHANGE	500
FRONT BUMPER	5	NEED TO CHANGE BUMPER	4000
FRONT WINDSHIELD	5	BROKEN GLASS	5000
LH FENDER	5	NEED TO REPAINT	1500
LH FRONT DOOR	4	NEED TO REPAINT & REPAIR	2500
LH REAR DOOR	5	NEED TO REPAINT & REPAIR	2500
LH RUNNING BOARD	5	NEED TO REPAINT	1500
LH QUARTER PANEL	5	NEED TO REPAINT	1500
REAR BUMPER	5	NEED TO REPAINT	1500
TAIL LIGHT	5	NEED TO CHANGE LEFT SIDE	700
RH QUARTER PANEL	5	NEED TO REPAINT	1500
RH RUNNING BOARD	5	NEED TO REPAINT	1500

Ordered by: bablu | Inspected date: 2019-05-17

Order Id: 72055

Overall Score



6/10



3,31,972



EXTERIOR (CONTINUED)




5/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH REAR DOOR	5	NEED TO REPAINT	1500
RH FRONT DOOR	4	NEED TO REPAINT & REPAIR	2500
RH FENDER	5	DENTING PAINTING WORK	2000
BODY RUST	5	MANY BODY RUSH	0
ROOF (REGULAR)	5	DENT ON IT	2000



IMAGES



NEED ATTENTION





DOCUMENTS



DESCRIPTION

not good car whole body is damage need to change all 4 tyre

Ordered by: bablu | Inspected date: 2019-05-17

Order Id: 72055

Overall Score







6/10



3,31,972

IMAGES





Ordered by: bablu | Inspected date: 2019-05-17

Order Id: 72055

Overall Score



6/10



3,31,972

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.