

# ECO INSPECTION CERTIFICATE

Premium

Order ID : 63528

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

<b>Ordered By :</b> Deepak Rajpal	<b>Inspection Date :</b> 2019-05-19	<b>Location :</b> LUDHIANA	<b>Inspected By</b>   <b>Verified Technician</b> 321+ vehicle inspected 1+ years experience <b>Pawan Kumar Gupta</b>
--------------------------------------	--	-------------------------------	--

**7/10**

**Overall Score**

- ✓ Evaluated across **5** segments
- ✓ Covered **121+** checkpoints
- ✓ **121** does not need attention
- ✓ **1** Owner , **9** Years Vehicle Age
- ✓ No Accidental History

## Honda City 1.5 V At, 2010



### VEHICLE INFORMATION

<b>MAKE</b>	HONDA	<b>ENGINE NUMBER</b>	
<b>MODEL</b>	CITY	<b>REGISTRATION NO.</b>	PB10CX 0088
<b>MFG. DATE</b>	01/2010	<b>VIN/CHASSIS NUMBER</b>	002645
<b>TRIM</b>	1.5 V AT	<b>ODOMETER READING</b>	56000
<b>COLOR</b>	WHITE	<b>INSURANCE EXPIRY</b>	2019-7-19
<b>BODY TYPE</b>	SEDAN	<b>VEHICLE PASSING</b>	PRIVATE
<b>FUEL TYPE</b>	PETROL	<b>ENGINE SOUND LINK</b>	<a href="#">LISTEN ENGINE SOUND</a>

### KEY HIGHLIGHTS

<b>FLOOD DAMAGE</b>	NO	<b>MAJOR ACCIDENT(S)</b>	NO	<b>SERVICE LOGS AVAILABLE</b>	NO
<b>TYRE LIFE REMAINING (KM)</b>	6,500	<b>RC COPY AVAILABLE</b>	ORIGINAL	<b>BANK HYPOTHECATION</b>	NO
<b>DENT</b>	NO	<b>INSURANCE COPY AVAILABLE</b>	NO	<b>BANK NOC</b>	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

**3,70,215**




Very Good Condition

### ECO SCORE & REPAIR COST ESTIMATE

#### ECO SCORE

<b>Interior</b>	<div style="width: 70%;"></div>	<b>7 / 10</b>
<b>Wheel</b>	<div style="width: 70%;"></div>	<b>7 / 10</b>
<b>Test Drive</b>	<div style="width: 70%;"></div>	<b>7 / 10</b>
<b>Exterior</b>	<div style="width: 70%;"></div>	<b>7 / 10</b>
<b>Hood</b>	<div style="width: 70%;"></div>	<b>7 / 10</b>

#### TOTAL ESTIMATE SPEND 0



Ordered by: Deepak Rajpal | Inspected date: 2019-05-19

Order Id: 63528

Overall Score



7/10



3,70,215



## INTERIOR






7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	8	GOOD	0
DOOR HINGES	7	OKK	0
CARPET & FLOOR MAT	7	GOOD	0
SEAT & SEAT BELT	7	SAFE	0
DASHBOARD & INSTRUMENT PANEL	7	GOOD	0
HORN	8	OKK	0
SPEAKERS & MUSIC SYSTEM	8	WORKING	0
HANDBRAKE	7	SAFE	0
STEERING-MOUNTED CONTROLS	8	GOOD	0
PEDALS	7	OK	0
CENTRAL LOCK	7	SAFE	0
A/C VENTS & HEATER	8	WORKING	0
CUP HOLDERS	7	GOOD	0
NAVIGATION (YES)	7	OKK	0
ODOMETER	7	GOOD	0
POWER WINDOWS (YES)	7	SAFE	0
HAZARD LIGHT	8	GOOD	0



## IMAGES



Ordered by: Deepak Rajpal | Inspected date: 2019-05-19

Order Id: 63528

Overall Score  **7/10**




**3,70,215**

## TEST DRIVE

**7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7	OKK	0
BRAKE PERFORMANCE	8	SAFE	0
CLUTCH PERFORMANCE	7	GOOD	0
ENGINE NOISE	7	LESS NOISE	0
IGNITION SYSTEM	8	SMOOTH	0
SUSPENSION PERFORMANCE	8	GOOD	0
SUSPENSION FRONT SHOCKS	8	OKK	0
SUSPENSION REAR SHOCKS	7	GOOD	0
TRANSMISSION ENGAGE	7	OKK	0
CRUISE CONTROL (YES)	7	OKK	0
REAR PARKING SENSORS (YES)	7	OKK	0
REAR VIEW CAMERA (YES)	7	OKK	0

## IMAGES




## WHEEL

**7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7	OKK	0
SPARE TYRE (YES)	7	OKK	0
WHEEL ASSEMBLY (STEEL RIM)	8	GOOD	0

 IMAGES





 HOOD

 7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7	OKK	0
RH APRON	7	GOOD	0
RADIATOR	7	OKK	0
WIRING	7	WORKING	0
BATTERY	7	OKK	0
BRAKE FLUID LEVEL	7	ABOVE AVRAGE	0
ENGINE OIL	7	OKK	0
COOLANT LEVEL	7	OKK	0
BRAKE & COOLANT HOSE PIPES	7	GOOD	0
UNDERCARRIAGE	7	OKK	0
EXHAUST SYSTEM	7	GOOD	0

 IMAGES





Ordered by: Deepak Rajpal | Inspected date: 2019-05-19

Order Id: 63528

Overall Score  **7/10**



**3,70,215**

 **EXTERIOR**

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7	GOOD	0
FRONT BUMPER	7	OKK	0
HEAD LIGHTS	8	WORKING	0
GRILLE	7	GOOD	0
TURN SIGNAL	7	OKK	0
FOG LAMPS	8	GOOD	0
HOOD	8	GOOD	0
PILLAR	7	GOOD	0
FRONT WINDSHIELD	8	NO SCRATCHES	0
SIDE VIEW MIRRORS	7	GOOD	0
LH FENDER	7	OKK	0
LH FRONT DOOR	8	SAFE	0
LH REAR DOOR	7	OKK	0
LH RUNNING BOARD	8	GOOD	0
LH QUARTER PANEL	7	GOOD	0
FUEL LID	7	OKK	0
REAR WINDSHIELD	8	NO SCRATCH	0
REAR BUMPER	8	GOOD	0
TAIL LIGHT	7	WORKING	0
TRUNK LID/TAIL GATE	7	OKK	0
LUGGAGE COMPARTMENT LIGHT	7	BETTER	0
RH QUARTER PANEL	8	OKK	0
RH RUNNING BOARD	7	GOOD	0
RH REAR DOOR	7	OKK	0

Ordered by: Deepak Rajpal | Inspected date: 2019-05-19

Order Id: 63528

Overall Score  **7/10**




**3,70,215**






**EXTERIOR (CONTINUED)**

**7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	8	SAFE	0
RH FENDER	7	GOOD	0
BODY RUST	7	NO RUST	0
ROOF (REGULAR)	7	OKK	0
PAINT CONDITION	8	GOOD	0

**IMAGES**





 DESCRIPTION

good



Ordered by: Deepak Rajpal | Inspected date: 2019-05-19

Order Id: 63528

Overall Score












7/10



3,70,215

IMAGES





Ordered by: Deepak Rajpal | Inspected date: 2019-05-19

Order Id: 63528

Overall Score



7/10



3,70,215



## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.