


ECO INSPECTION CERTIFICATE

Premium

Order ID : 75043

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

| | | | |
|------------------------------|---------------------------------|-------------------------|---|
| Ordered By : Aman Gajwani | Inspection Date : 2019-05-22 | Location : GHAZIABAD | Inspected By  Kishan Kumar |
|------------------------------|---------------------------------|-------------------------|---|

6/10
Overall Score

- Evaluated across 5 segments
- Covered 121+ checkpoints
- 112 does not need attention
- 1 Owner , 3 Years Vehicle Age
- No Accidental History

Verified Technician
303+ vehicle inspected
1+ years experience

Maruti Suzuki Alto 800 Lxi, 2016



VEHICLE INFORMATION

| | | | |
|-----------|---------------|--------------------|-------------------------------------|
| MAKE | MARUTI SUZUKI | ENGINE NUMBER | 94758 |
| MODEL | ALTO 800 | REGISTRATION NO. | DL3CCK8954 |
| MFG. DATE | 01/2016 | VIN/CHASSIS NUMBER | 26883 |
| TRIM | LXI | ODOMETER READING | 12701 |
| COLOR | SILVER | INSURANCE EXPIRY | 2019-5-22 |
| BODY TYPE | HATCHBACK | VEHICLE PASSING | PRIVATE |
| FUEL TYPE | PETROL | ENGINE SOUND LINK | LISTEN ENGINE SOUND |

KEY HIGHLIGHTS

| | | | | | |
|--------------------------|--------|--------------------------|----------|------------------------|----|
| FLOOD DAMAGE | NO | MAJOR ACCIDENT(S) | NO | SERVICE LOGS AVAILABLE | NO |
| TYRE LIFE REMAINING (KM) | 25,000 | RC COPY AVAILABLE | ORIGINAL | BANK HYPOTHECATION | NO |
| DENT | YES | INSURANCE COPY AVAILABLE | NO | BANK NOC | NO |



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

2,14,955




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

| | | |
|------------|---------------------------------|--------|
| Interior | <div style="width: 60%;"></div> | 6 / 10 |
| Wheel | <div style="width: 80%;"></div> | 8 / 10 |
| Test Drive | <div style="width: 50%;"></div> | 5 / 10 |
| Exterior | <div style="width: 60%;"></div> | 6 / 10 |
| Hood | <div style="width: 70%;"></div> | 7 / 10 |

TOTAL ESTIMATE SPEND 3,300



Ordered by: Aman Gajwani | Inspected date: 2019-05-22

Order Id: 75043

Overall Score



6/10



2,14,955



INTERIOR



6/10

| INSPECTION CHECKPOINTS | SCORE(X/10) | REMARKS/COMMENTS | OPTIONAL SPEND EST. (RS) |
|----------------------------------|-------------|------------------|--------------------------|
| DOOR PANEL | 7 | | 0 |
| DOOR HINGES | 7 | | 0 |
| CARPET & FLOOR MAT | 7 | | 0 |
| SEAT & SEAT BELT | 7 | | 0 |
| DASHBOARD & INSTRUMENT PANEL | 7 | | 0 |
| HORN | 7 | | 0 |
| SPEAKERS & MUSIC SYSTEM | 7 | | 0 |
| HANDBRAKE | 7 | | 0 |
| PEDALS | 7 | | 0 |
| A/C VENTS & HEATER | 7 | | 0 |
| CUP HOLDERS | 7 | | 0 |
| ODOMETER | 7 | | 0 |
| POWER WINDOWS (YES - FRONT ONLY) | 7 | | 0 |
| HAZARD LIGHT | 7 | | 0 |
| STEERING-MOUNTED CONTROLS | 0 | NA | 0 |
| CENTRAL LOCK | 0 | NA | 0 |
| NAVIGATION (YES) | 0 | NA | 0 |



IMAGES



Ordered by: Aman Gajwani | Inspected date: 2019-05-22

Order Id: 75043

Overall Score **6/10**



2,14,955

TEST DRIVE

5/10

| INSPECTION CHECKPOINTS | SCORE(X/10) | REMARKS/COMMENTS | OPTIONAL SPEND EST. (RS) |
|----------------------------|-------------|------------------|--------------------------|
| STEERING PERFORMANCE | 7 | | 0 |
| BRAKE PERFORMANCE | 7 | | 0 |
| CLUTCH PERFORMANCE | 7 | | 0 |
| ENGINE NOISE | 7 | | 0 |
| IGNITION SYSTEM | 7 | | 0 |
| SUSPENSION PERFORMANCE | 7 | | 0 |
| SUSPENSION FRONT SHOCKS | 7 | | 0 |
| SUSPENSION REAR SHOCKS | 7 | | 0 |
| TRANSMISSION ENGAGE | 7 | | 0 |
| CRUISE CONTROL (YES) | 0 | NA | 0 |
| REAR PARKING SENSORS (YES) | 0 | NA | 0 |
| REAR VIEW CAMERA (YES) | 0 | NA | 0 |

IMAGES




WHEEL

8/10

| INSPECTION CHECKPOINTS | SCORE(X/10) | REMARKS/COMMENTS | OPTIONAL SPEND EST. (RS) |
|----------------------------|-------------|------------------|--------------------------|
| TYRES | 7 | | 0 |
| SPARE TYRE (YES) | 9 | BRAND NEW | 0 |
| WHEEL ASSEMBLY (STEEL RIM) | 7 | | 0 |

 IMAGES




 HOOD



7/10

| INSPECTION CHECKPOINTS | SCORE(X/10) | REMARKS/COMMENTS | OPTIONAL SPEND EST. (RS) |
|----------------------------|-------------|------------------|--------------------------|
| LH APRON | 7 | | 0 |
| RH APRON | 7 | | 0 |
| RADIATOR | 7 | | 0 |
| WIRING | 7 | | 0 |
| BATTERY | 7 | | 0 |
| BRAKE FLUID LEVEL | 7 | | 0 |
| ENGINE OIL | 7 | | 0 |
| COOLANT LEVEL | 7 | | 0 |
| BRAKE & COOLANT HOSE PIPES | 7 | | 0 |
| UNDERCARRIAGE | 7 | | 0 |
| EXHAUST SYSTEM | 7 | | 0 |

 IMAGES



Ordered by: Aman Gajwani | Inspected date: 2019-05-22

Order Id: 75043

Overall Score



6/10



2,14,955



EXTERIOR



6/10

| INSPECTION CHECKPOINTS | SCORE(X/10) | REMARKS/COMMENTS | OPTIONAL SPEND EST. (RS) |
|---------------------------|-------------|------------------|--------------------------|
| LICENSE PLATE | 7 | | 0 |
| FRONT BUMPER | 7 | | 0 |
| HEAD LIGHTS | 7 | | 0 |
| GRILLE | 7 | | 0 |
| TURN SIGNAL | 7 | | 0 |
| HOOD | 6 | MINOR DENT | 150 |
| PILLAR | 7 | | 0 |
| FRONT WINDSHIELD | 7 | | 0 |
| SIDE VIEW MIRRORS | 7 | | 0 |
| LH FENDER | 7 | | 0 |
| LH FRONT DOOR | 6 | SCRATCHES | 250 |
| LH REAR DOOR | 6 | SCRATCHES | 300 |
| LH QUARTER PANEL | 6 | SCRATCHES | 200 |
| FUEL LID | 7 | | 0 |
| REAR WINDSHIELD | 7 | | 0 |
| REAR BUMPER | 7 | | 0 |
| TRUNK LID/TAIL GATE | 7 | | 0 |
| LUGGAGE COMPARTMENT LIGHT | 7 | | 0 |
| RH QUARTER PANEL | 6 | SCRATCHES | 200 |
| RH RUNNING BOARD | 7 | | 0 |
| RH REAR DOOR | 6 | SCRATCHES | 250 |
| RH FRONT DOOR | 6 | SCRATCHES | 150 |
| RH FENDER | 6 | SCRATCHES | 200 |
| BODY RUST | 7 | | 0 |

Ordered by: Aman Gajwani | Inspected date: 2019-05-22

Order Id: 75043

Overall Score **6/10**



2,14,955



EXTERIOR (CONTINUED)

6/10

| INSPECTION CHECKPOINTS | SCORE(X/10) | REMARKS/COMMENTS | OPTIONAL SPEND EST. (RS) |
|------------------------|-------------|--|--------------------------|
| ROOF (REGULAR) | 7 | | 0 |
| PAINT CONDITION | 7 | | 0 |
| FOG LAMPS | 0 | NA | 0 |
| LH RUNNING BOARD | 5 | DENT AND SCRATCHES NEED TO BE REPAIR | 600 |
| TAIL LIGHT | 5 | RIGHT TAIL LIGHT BROKEN NEED TO CHANGE | 1000 |

IMAGES





NEED ATTENTION ⚠



DOCUMENTS



DESCRIPTION

all body scratches and dent need to be repair and right side tail light broken need to change

Ordered by: Aman Gajwani | Inspected date: 2019-05-22

Order Id: 75043

Overall Score




6/10



2,14,955

IMAGES





Ordered by: Aman Gajwani | Inspected date: 2019-05-22

Order Id: 75043

Overall Score



6/10



2,14,955

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.