



ECO INSPECTION CERTIFICATE

Premium

Order ID : 74994

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Nayeem .	Inspection Date : 2019-05-21	Location : HYDERABAD	 Inspected By  Verified Technician 51+ vehicle inspected 1+ years experience Tata Uday Kumar
--------------------------	---------------------------------	-------------------------	--

9/10

Overall Score

- ✔ Evaluated across **5** segments
- ✔ Covered **121+** checkpoints
- ✔ **121** does not need attention
- ✔ **1** Owner , **9** Years Vehicle Age
- ✔ No Accidental History









Maruti Suzuki Alto K10 LXI, 2010



VEHICLE INFORMATION

MAKE	MARUTI SUZUKI	ENGINE NUMBER	F8DN514275
MODEL	ALTO K10	REGISTRATION NO.	AP28BX8716
MFG. DATE	12/2013	VIN/CHASSIS NUMBER	MA3EUA61S00358017MD
TRIM	LXI	ODOMETER READING	67316
COLOR	RED	INSURANCE EXPIRY	2019-12-25
BODY TYPE	SEDAN	VEHICLE PASSING	PRIVATE
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	30,000	 RC COPY AVAILABLE	ORIGINAL	 BANK HYPOTHECATION	NO
 DENT	NO	 INSURANCE COPY AVAILABLE	NO	 BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

1,58,154




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

 Interior	<div style="width: 100%; height: 10px; background-color: green;"></div>	10 / 10
 Wheel	<div style="width: 90%; height: 10px; background-color: green;"></div>	9 / 10
 Test Drive	<div style="width: 100%; height: 10px; background-color: green;"></div>	10 / 10
 Exterior	<div style="width: 100%; height: 10px; background-color: green;"></div>	10 / 10
 Hood	<div style="width: 100%; height: 10px; background-color: green;"></div>	10 / 10

TOTAL ESTIMATE SPEND 0



Ordered by: Nayeem . | Inspected date: 2019-05-21

Order Id: 74994

Overall Score



9/10



1,58,154



INTERIOR




10/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	10		0
DOOR HINGES	9		0
CARPET & FLOOR MAT	10		0
SEAT & SEAT BELT	10		0
DASHBOARD & INSTRUMENT PANEL	10		0
HORN	10		0
SPEAKERS & MUSIC SYSTEM	10		0
HANDBRAKE	10		0
STEERING-MOUNTED CONTROLS	9		0
PEDALS	10		0
CENTRAL LOCK	10		0
A/C VENTS & HEATER	10		0
CUP HOLDERS	10		0
NAVIGATION (YES)	10		0
ODOMETER	10		0
POWER WINDOWS (YES)	10		0
HAZARD LIGHT	10		0



IMAGES



Ordered by: Nayeem . | Inspected date: 2019-05-21

Order Id: 74994

Overall Score **9/10**



1,58,154

TEST DRIVE

10/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	9		0
BRAKE PERFORMANCE	10		0
CLUTCH PERFORMANCE	10		0
ENGINE NOISE	9		0
IGNITION SYSTEM	10		0
SUSPENSION PERFORMANCE	10		0
SUSPENSION FRONT SHOCKS	10		0
SUSPENSION REAR SHOCKS	10		0
TRANSMISSION ENGAGE	10		0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0

IMAGES




WHEEL

9/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	9		0
SPARE TYRE (YES)	9		0
WHEEL ASSEMBLY (STEEL RIM)	9		0

 IMAGES



 HOOD

10/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	10		0
RH APRON	10		0
RADIATOR	10		0
WIRING	10		0
BATTERY	9		0
BRAKE FLUID LEVEL	10		0
ENGINE OIL	10		0
COOLANT LEVEL	10		0
BRAKE & COOLANT HOSE PIPES	10		0
UNDERCARRIAGE	10		0
EXHAUST SYSTEM	10		0

 IMAGES



Ordered by: Nayeem . | Inspected date: 2019-05-21

Order Id: 74994

Overall Score  **9/10**



1,58,154

 **EXTERIOR**

 **10/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	10		0
FRONT BUMPER	10		0
HEAD LIGHTS	10		0
GRILLE	10		0
TURN SIGNAL	10		0
FOG LAMPS	10		0
HOOD	10		0
PILLAR	10		0
FRONT WINDSHIELD	9		0
SIDE VIEW MIRRORS	9		0
LH FENDER	10		0
LH FRONT DOOR	10		0
LH REAR DOOR	10		0
LH RUNNING BOARD	10		0
LH QUARTER PANEL	10		0
FUEL LID	10		0
REAR WINDSHIELD	10		0
REAR BUMPER	10		0
TAIL LIGHT	10		0
TRUNK LID/TAIL GATE	10		0
LUGGAGE COMPARTMENT LIGHT	10		0
RH QUARTER PANEL	10		0
RH RUNNING BOARD	10		0
RH REAR DOOR	10		0

Ordered by: Nayeem . | Inspected date: 2019-05-21

Order Id: 74994

Overall Score **9/10**





1,58,154

EXTERIOR (CONTINUED)


10/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	10		0
RH FENDER	10		0
BODY RUST	10		0
ROOF (REGULAR)	10		0
PAINT CONDITION	10		0

IMAGES



DOCUMENTS



DESCRIPTION

good car

Ordered by: Nayeem . | Inspected date: 2019-05-21

Order Id: 74994

Overall Score








9/10



1,58,154

IMAGES



Ordered by: Nayeem . | Inspected date: 2019-05-21

Order Id: 74994

Overall Score



9/10



1,58,154

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.