


ECO INSPECTION CERTIFICATE

Premium

Order ID : 74594

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Mahesh Choudshetty	Inspection Date : 2019-05-20	Location : BANGALORE	Inspected By  Shreelal R
------------------------------------	---------------------------------	-------------------------	---

6/10

Overall Score

- ✔ Evaluated across **6** segments
- ✔ Covered **121+** checkpoints
- ✔ **120** does not need attention
- ✔ **1** Owner , **9** Years Vehicle Age
- ✔ No Accidental History

✔ **Verified Technician**

526+ vehicle inspected
1+ years experience










Tvs Wego 110CC, 2010



VEHICLE INFORMATION

MAKE	TVS	ENGINE NUMBER	1034904
MODEL	WEGO	REGISTRATION NO.	KA04HE0879
YEAR	2010	VIN/CHASSIS NUMBER	MD626AG4XA1H32293
TRIM	110CC	ODOMETER READING	35400
COLOR	WHITE	INSURANCE EXPIRY	2018-12-28
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY OBSERVATIONS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	10,000	 RC COPY AVAILABLE	ORIGINAL	 BANK HYPOTHECATION	NO
 DENT	NO	 INSURANCE COPY AVAILABLE	NO	 BANK NOC	NO









Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

19,084




ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

 Tyre	<div style="width: 60%; background-color: yellow;"></div>	6 / 10
 Control	<div style="width: 60%; background-color: yellow;"></div>	6 / 10
 Light	<div style="width: 60%; background-color: yellow;"></div>	6 / 10
 Oil	<div style="width: 70%; background-color: green;"></div>	7 / 10
 Chassis	<div style="width: 60%; background-color: yellow;"></div>	6 / 10
 Stand	<div style="width: 60%; background-color: yellow;"></div>	6 / 10

TOTAL ESTIMATE SPEND 300



www.droom.in/eco

eco@droom.in

Contact No. 18004070707 (Toll Free)

-a service by .in

Ordered by: mahesh Choudshetty | Inspected date: 2019-05-20

Order Id: 74594

Overall Score



6/10



19,084






TYRE





6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRONT TYRE CONDITION & AIR PRESSURE	6		0
REAR TYRE CONDITION & AIR PRESSURE	6		0
WHEEL SPOKES FRONT	6		0
WHEEL SPOKES REAR	6		0
WHEEL RIM FRONT	6		0
WHEEL RIM REAR	6		0
WHEEL BEARINGS FRONT	6		0
WHEEL BEARINGS REAR	6		0
WHEEL SEALS FRONT	6		0
WHEEL SEALS REAR	6		0
BRAKE FUNCTION FRONT	6		0
BRAKE FUNCTION REAR	6		0
BRAKES CONDITION FRONT	6		0
BRAKES CONDITION REAR	6		0

IMAGES





Ordered by: mahesh Choudshetty | Inspected date: 2019-05-20

Order Id: 74594

Overall Score **6/10**



19,084

STAND

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
CENTRE STAND CONDITION	6		0
CENTRE STAND RETENTION	6		0
SIDE STAND CONDITION	6		0
SIDE STAND RETENTION	6		0

IMAGES




CONTROL

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
HANDLEBARS CONDITION	6		0
LEVERS & PEDAL CONDITION	6		0
PIVOTS	6		0
CABLES CONDITION	6		0
CABLES ROUTING	6		0
HOSES CONDITION	6		0
HOSES ROUTING	6		0
THROTTLE OPERATION	6		0

IMAGES




OIL

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LEVELS - ENGINE OIL	6		0
LEVELS - GEAR OIL/SHAFT DRIVE (NO)	10		0
LEVELS - HYDRAULIC FLUID (NO)	10		0
LEVELS - COOLANT (NO)	10		0
LEVELS - FUEL	6		0
LEAKS - ENGINE OIL	6		0
LEAKS - GEAR OIL	6		0
LEAKS - HYDRAULIC FLUID	6		0
LEAKS - COOLANT	6		0
LEAKS - FUEL	6		0

IMAGES



Ordered by: mahesh Choudshetty | Inspected date: 2019-05-20

Order Id: 74594

Overall Score



6/10



19,084


LIGHT



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
BATTERY CONDITION	6		0
BATTERY VENT TUBE	6		0
HEADLAMP CONDITION	7		0
TAILLAMP/BRAKELAMP CONDITION	6		0
TAILLAMP/BRAKELAMP OPERATION	6		0
TURN SIGNALS OPERATION FRONT LEFT	6		0
TURN SIGNALS OPERATION FRONT RIGHT	6		0
TURN SIGNALS OPERATION REAR LEFT	6		0
TURN SIGNALS OPERATION REAR RIGHT	6		0
SWITCHES OPERATION	6		0
MIRRORS AIM	6		0
LENSES & REFLECTORS CONDITION	6		0
WIRING CONDITION	6		0
WIRING ROUTING	6		0
MIRRORS CONDITION	0	NOT HAVING	300

IMAGES



Ordered by: mahesh Choudshetty | Inspected date: 2019-05-20

Order Id: 74594

Overall Score



6/10



19,084



NEED ATTENTION



CHASSIS



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRAME CONDITION	6		0
FRAME STEERING-HEAD BEARINGS	6		0
FRAME SWINGARM BUSHINGS	6		0
SUSPENSION FRONT FORKS LEFT	6		0
SUSPENSION FRONT FORKS RIGHT	6		0
SUSPENSION REAR SHOCKS LEFT	6		0
SUSPENSION REAR SHOCKS RIGHT	6		0
CHAIN/BELT TENSION	6		0
CHAIN/BELT LUBRICATION	6		0
CHAIN/BELT SPROCKETS	6		0
FASTENERS THREADED	6		0
FASTENERS CLIPS & COTTER PINS	6		0
ENGINE	6		0
TRANSMISSION	6		0

Ordered by: mahesh Choudshetty | Inspected date: 2019-05-20

Order Id: 74594

Overall Score




6/10



19,084

IMAGES



DOCUMENTS



DESCRIPTION

insurance expired

Ordered by: mahesh Choudshetty | Inspected date: 2019-05-20

Order Id: 74594

Overall Score




6/10



19,084

 IMAGES



Ordered by: mahesh Choudshetty | Inspected date: 2019-05-20

Order Id: 74594

Overall Score



6/10



19,084

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.