


# ECO INSPECTION CERTIFICATE

Premium

Order ID : 76302

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

<b>Ordered By :</b> Inderpreet Singh	<b>Inspection Date :</b> 2019-05-24	<b>Location :</b> JALANDHAR	<b>Inspected By</b>   <b>HARPREET SINGH</b>
---	--	--------------------------------	---

## 8/10

**Overall Score**

- ✔ Evaluated across **5** segments
- ✔ Covered **121+** checkpoints
- ✔ **121** does not need attention
- ✔ **1** Owner , **1** Year Vehicle Age
- ✔ No Accidental History

- ✔ **Verified Technician**
- 66+ vehicle inspected
- 1+ years experience

## Honda Wr-V VX DIESEL, 2018



### VEHICLE INFORMATION

<b>MAKE</b>	HONDA	<b>ENGINE NUMBER</b>	27365
<b>MODEL</b>	WR-V	<b>REGISTRATION NO.</b>	PB09AF3547
<b>MFG. DATE</b>	02/2018	<b>VIN/CHASSIS NUMBER</b>	23151
<b>TRIM</b>	VX DIESEL	<b>ODOMETER READING</b>	026206
<b>COLOR</b>	WHITE	<b>INSURANCE EXPIRY</b>	2019-5-2
<b>BODY TYPE</b>	SEDAN	<b>VEHICLE PASSING</b>	PRIVATE
<b>FUEL TYPE</b>	DIESEL	<b>ENGINE SOUND LINK</b>	<a href="#">LISTEN ENGINE SOUND</a>

### KEY HIGHLIGHTS

<b>FLOOD DAMAGE</b>	NO	<b>MAJOR ACCIDENT(S)</b>	NO	<b>SERVICE LOGS AVAILABLE</b>	NO
<b>TYRE LIFE REMAINING (KM)</b>	15,000	<b>RC COPY AVAILABLE</b>	ORIGINAL	<b>BANK HYPOTHECATION</b>	NO
<b>DENT</b>	NO	<b>INSURANCE COPY AVAILABLE</b>	NO	<b>BANK NOC</b>	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

**9,23,842**




Very Good Condition

### ECO SCORE & REPAIR COST ESTIMATE

#### ECO SCORE

<b>Interior</b>	<div style="width: 70%; background-color: #00a651;"></div>	<b>7 / 10</b>
<b>Wheel</b>	<div style="width: 80%; background-color: #00a651;"></div>	<b>8 / 10</b>
<b>Test Drive</b>	<div style="width: 80%; background-color: #00a651;"></div>	<b>8 / 10</b>
<b>Exterior</b>	<div style="width: 80%; background-color: #00a651;"></div>	<b>8 / 10</b>
<b>Hood</b>	<div style="width: 80%; background-color: #00a651;"></div>	<b>8 / 10</b>

#### TOTAL ESTIMATE SPEND 0



Ordered by: Inderpreet Singh | Inspected date: 2019-05-24

Order Id: 76302

Overall Score



8/10



9,23,842



## INTERIOR





7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7	GOOD	0
DOOR HINGES	8	EXCELENT GOOD	0
CARPET & FLOOR MAT	7	GOOD	0
SEAT & SEAT BELT	8	EXCELENT GOOD	0
DASHBOARD & INSTRUMENT PANEL	7	GOOD	0
HORN	8	EXCELENT GOOD	0
SPEAKERS & MUSIC SYSTEM	7	GOOD	0
HANDBRAKE	8	EXCELENT GOOD	0
STEERING-MOUNTED CONTROLS	7	GOOD	0
PEDALS	8	EXCELENT GOOD	0
CENTRAL LOCK	7	GOOD	0
A/C VENTS & HEATER	8	EXCELENT GOOD	0
CUP HOLDERS	7	GOOD	0
NAVIGATION (YES)	8	EXCELENT GOOD	0
ODOMETER	7	GOOD	0
POWER WINDOWS (YES)	8	EXCELENT GOOD	0
HAZARD LIGHT	7	GOOD	0



## IMAGES



Ordered by: Inderpreet Singh | Inspected date: 2019-05-24

Order Id: 76302

Overall Score  **8/10**




**9,23,842**

## TEST DRIVE

**8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7	GOOD	0
BRAKE PERFORMANCE	8	EXCELENT GOOD	0
CLUTCH PERFORMANCE	7	GOOD	0
ENGINE NOISE	8	EXCELENT GOOD	0
IGNITION SYSTEM	7	GOOD	0
SUSPENSION PERFORMANCE	8	EXCELENT GOOD	0
SUSPENSION FRONT SHOCKS	7	GOOD	0
SUSPENSION REAR SHOCKS	8	EXCELENT GOOD	0
TRANSMISSION ENGAGE	7	GOOD	0
CRUISE CONTROL (YES)	8	EXCELENT GOOD	0
REAR PARKING SENSORS (YES)	7	GOOD	0
REAR VIEW CAMERA (YES)	8	EXCELENT GOOD	0

## IMAGES




## WHEEL

**8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	8	EXCELENT GOOD	0
SPARE TYRE (YES)	7	GOOD	0
WHEEL ASSEMBLY (STEEL RIM)	8	EXCELENT GOOD	0

 IMAGES



 HOOD



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	8	EXCELENT GOOD	0
RH APRON	7	GOOD	0
RADIATOR	8	EXCELENT GOOD	0
WIRING	7	GOOD	0
BATTERY	8	EXCELENT GOOD	0
BRAKE FLUID LEVEL	7	GOOD	0
ENGINE OIL	8	EXCELENT GOOD	0
COOLANT LEVEL	7	GOOD	0
BRAKE & COOLANT HOSE PIPES	8	EXCELENT GOOD	0
UNDERCARRIAGE	7	GOOD	0
EXHAUST SYSTEM	8	EXCELENT GOOD	0

 IMAGES





Ordered by: Inderpreet Singh | Inspected date: 2019-05-24

Order Id: 76302

Overall Score  **8/10**



**9,23,842**

 **EXTERIOR**

 **8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7	GOOD	0
FRONT BUMPER	8	EXCELENT GOOD	0
HEAD LIGHTS	7	GOOD	0
GRILLE	8	EXCELENT GOOD	0
TURN SIGNAL	7	GOOD	0
FOG LAMPS	8	EXCELENT GOOD	0
HOOD	8	EXCELENT GOOD	0
PILLAR	8	EXCELENT GOOD	0
FRONT WINDSHIELD	7	GOOD	0
SIDE VIEW MIRRORS	8	EXCELENT GOOD	0
LH FENDER	7	GOOD	0
LH FRONT DOOR	8	EXCELENT GOOD	0
LH REAR DOOR	8	EXCELENT GOOD	0
LH RUNNING BOARD	7	GOOD	0
LH QUARTER PANEL	8	EXCELENT GOOD	0
FUEL LID	8	EXCELENT GOOD	0
REAR WINDSHIELD	7	GOOD	0
REAR BUMPER	8	EXCELENT GOOD	0
TAIL LIGHT	8	EXCELENT GOOD	0
TRUNK LID/TAIL GATE	7	GOOD	0
LUGGAGE COMPARTMENT LIGHT	8	EXCELENT GOOD	0
RH QUARTER PANEL	7	GOOD	0
RH RUNNING BOARD	8	EXCELENT GOOD	0
RH REAR DOOR	7	GOOD	0

Ordered by: Inderpreet Singh | Inspected date: 2019-05-24

Order Id: 76302

Overall Score  **8/10**



**9,23,842**


**EXTERIOR (CONTINUED)**

**8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	8	EXCELENT GOOD	0
RH FENDER	7	GOOD	0
BODY RUST	8	EXCELENT GOOD	0
ROOF (REGULAR)	7	GOOD	0
PAINT CONDITION	8	EXCELENT GOOD	0

**IMAGES**





## DOCUMENTS



## DESCRIPTION

excellent good



Ordered by: Inderpreet Singh | Inspected date: 2019-05-24

Order Id: 76302

Overall Score













8/10



9,23,842

IMAGES





Ordered by: Inderpreet Singh | Inspected date: 2019-05-24

Order Id: 76302

Overall Score



8/10



9,23,842

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.