

ECO INSPECTION CERTIFICATE

Premium

Order ID : 76952

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Inderpreet Singh	Inspection Date : 2019-05-25	Location : JALANDHAR	Inspected By HARPREET SINGH
---	--	--------------------------------	--

7/10

Overall Score

- ✔ Evaluated across **5** segments
- ✔ Covered **121+** checkpoints
- ✔ **120** does not need attention
- ✔ **1** Owner , **1** Year Vehicle Age
- ✔ No Accidental History

✔ **Verified Technician**

69+ vehicle inspected
1+ years experience

Toyota Innova Crysta 2.8 ZX AT 7 STR, 2018



VEHICLE INFORMATION			
MAKE	TOYOTA	ENGINE NUMBER	89932
MODEL	INNOVA CRYSTA	REGISTRATION NO.	PB02DN1449
MFG. DATE	05/2018	VIN/CHASSIS NUMBER	784272
TRIM	2.8 ZX AT 7 STR	ODOMETER READING	19917
COLOR	GREY METALIC	INSURANCE EXPIRY	2019-5-2
BODY TYPE	SEDAN	VEHICLE PASSING	PRIVATE
FUEL TYPE	DIESEL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	16,000	RC COPY AVAILABLE	ORIGINAL	BANK HYPOTHECATION	YES
DENT	NO	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO

Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.
With this evaluation, the Fair Market Price for this vehicle comes to be:

22,66,691

Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 70%; background-color: green;"></div>	7 / 10
Wheel	<div style="width: 70%; background-color: green;"></div>	7 / 10
Test Drive	<div style="width: 80%; background-color: green;"></div>	8 / 10
Exterior	<div style="width: 80%; background-color: green;"></div>	8 / 10
Hood	<div style="width: 80%; background-color: green;"></div>	8 / 10

TOTAL ESTIMATE SPEND 0

0

0

0

0

0

Ordered by: Inderpreet Singh | Inspected date: 2019-05-25

Order Id: 76952

Overall Score



7/10



22,66,691



INTERIOR




7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7	GOOD	0
DOOR HINGES	8	EXCELENT GOOD	0
CARPET & FLOOR MAT	7	GOOD	0
SEAT & SEAT BELT	8	EXCELENT GOOD	0
DASHBOARD & INSTRUMENT PANEL	7	GOOD	0
HORN	7	GOOD	0
SPEAKERS & MUSIC SYSTEM	8	EXCELENT GOOD	0
HANDBRAKE	7	GOOD	0
STEERING-MOUNTED CONTROLS	8	EXCELENT GOOD	0
PEDALS	7	GOOD	0
CENTRAL LOCK	8	EXCELENT GOOD	0
A/C VENTS & HEATER	7	GOOD	0
CUP HOLDERS	8	EXCELENT GOOD	0
NAVIGATION (YES)	7	GOOD	0
ODOMETER	8	EXCELENT GOOD	0
POWER WINDOWS (YES)	7	GOOD	0
HAZARD LIGHT	8	EXCELENT GOOD	0



IMAGES



Ordered by: Inderpreet Singh | Inspected date: 2019-05-25

Order Id: 76952

Overall Score **7/10**



22,66,691

TEST DRIVE

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7	GOOD	0
BRAKE PERFORMANCE	8	EXCELENT GOOD	0
CLUTCH PERFORMANCE	7	GOOD	0
ENGINE NOISE	8	EXCELENT GOOD	0
IGNITION SYSTEM	7	GOOD	0
SUSPENSION PERFORMANCE	8	EXCELENT GOOD	0
SUSPENSION FRONT SHOCKS	7	GOOD	0
SUSPENSION REAR SHOCKS	8	EXCELENT GOOD	0
TRANSMISSION ENGAGE	7	GOOD	0
CRUISE CONTROL (YES)	8	EXCELENT GOOD	0
REAR PARKING SENSORS (YES)	7	GOOD	0
REAR VIEW CAMERA (YES)	8	EXCELENT GOOD	0

IMAGES




WHEEL

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7	GOOD	0
SPARE TYRE (YES)	8	EXCELENT GOOD	0
WHEEL ASSEMBLY (STEEL RIM)	7		0

 IMAGES




 HOOD

 8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	8	EXCELENT GOOD	0
RH APRON	7	GOOD	0
RADIATOR	8	EXCELENT GOOD	0
WIRING	8	EXCELENT GOOD	0
BATTERY	8	EXCELENT GOOD	0
BRAKE FLUID LEVEL	8	EXCELENT GOOD	0
ENGINE OIL	8	EXCELENT GOOD	0
COOLANT LEVEL	8	EXCELENT GOOD	0
BRAKE & COOLANT HOSE PIPES	8	EXCELENT GOOD	0
UNDERCARRIAGE	8	EXCELENT GOOD	0
EXHAUST SYSTEM	8	EXCELENT GOOD	0

 IMAGES





Ordered by: Inderpreet Singh | Inspected date: 2019-05-25

Order Id: 76952

Overall Score  **7/10**



22,66,691

 **EXTERIOR**

 **8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7	GOOD	0
FRONT BUMPER	8	EXCELENT GOOD	0
HEAD LIGHTS	7	GOOD	0
GRILLE	8	EXCELENT GOOD	0
TURN SIGNAL	8	GOOD	0
FOG LAMPS	8	EXCELENT GOOD	0
HOOD	7	GOOD	0
PILLAR	8	EXCELENT GOOD	0
FRONT WINDSHIELD	7	GOOD	0
SIDE VIEW MIRRORS	8	EXCELENT GOOD	0
LH FENDER	7	GOOD	0
LH FRONT DOOR	8	EXCELENT GOOD	0
LH REAR DOOR	8	EXCELENT GOOD	0
LH RUNNING BOARD	8	EXCELENT GOOD	0
LH QUARTER PANEL	8	EXCELENT GOOD	0
FUEL LID	8	EXCELENT GOOD	0
REAR WINDSHIELD	8	EXCELENT GOOD	0
REAR BUMPER	8	EXCELENT GOOD	0
TAIL LIGHT	8	EXCELENT GOOD	0
TRUNK LID/TAIL GATE	8	EXCELENT GOOD	0
RH QUARTER PANEL	8	EXCELENT GOOD	0
RH RUNNING BOARD	8	EXCELENT GOOD	0
RH REAR DOOR	8	EXCELENT GOOD	0
RH FRONT DOOR	8	EXCELENT GOOD	0

Ordered by: Inderpreet Singh | Inspected date: 2019-05-25

Order Id: 76952

Overall Score **7/10**



22,66,691


EXTERIOR (CONTINUED)

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FENDER	8	EXCELENT GOOD	0
BODY RUST	7	GOOD	0
ROOF (REGULAR)	8	EXCELENT GOOD	0
PAINT CONDITION	8	EXCELENT GOOD	0
LUGGAGE COMPARTMENT LIGHT	5	NEUTRAL	0

IMAGES






 **NEED ATTENTION** 



 **DOCUMENTS**



 **DESCRIPTION**

excellent good

Ordered by: Inderpreet Singh | Inspected date: 2019-05-25

Order Id: 76952

Overall Score











7/10



22,66,691

IMAGES





Ordered by: Inderpreet Singh | Inspected date: 2019-05-25

Order Id: 76952

Overall Score



7/10



22,66,691

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.