


ECO INSPECTION CERTIFICATE

Premium

Order ID : 76063

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Caravan Car	Inspection Date : 2019-05-25	Location : GOREGAON WEST	Inspected By  Verified Technician 244+ vehicle inspected 1+ years experience Shashank Mahadik
------------------------------------	--	------------------------------------	--

7/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 120 does not need attention
- ✓ 1 Owner , 2 Years Vehicle Age
- ✓ No Accidental History

Hyundai Elite I20 SPORTZ 1.2, 2017



VEHICLE INFORMATION			
MAKE	HYUNDAI	ENGINE NUMBER	
MODEL	ELITE I20	REGISTRATION NO.	MH47W6398
MFG. DATE	05/2017	VIN/CHASSIS NUMBER	M391891
TRIM	SPORTZ 1.2	ODOMETER READING	14255
COLOR	GREY	INSURANCE EXPIRY	2019-9-25
BODY TYPE	HATCHBACK	VEHICLE PASSING	PRIVATE
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS			
FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO
TYRE LIFE REMAINING (KM)	20,000	RC COPY AVAILABLE	ORIGINAL
DENT	NO	INSURANCE COPY AVAILABLE	YES (COMPREHENSIVE)
		SERVICE LOGS AVAILABLE	NO
		BANK HYPOTHECATION	NO
		BANK NOC	YES



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.
With this evaluation, the Fair Market Price for this vehicle comes to be:

6,00,816



Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE		TOTAL ESTIMATE SPEND 0	
Interior	<div style="width: 80%;"></div> 8 / 10		0
Wheel	<div style="width: 70%;"></div> 7 / 10		0
Test Drive	<div style="width: 80%;"></div> 8 / 10		0
Exterior	<div style="width: 70%;"></div> 7 / 10		0
Hood	<div style="width: 70%;"></div> 7 / 10		0

Ordered by: caravan car | Inspected date: 2019-05-25

Order Id: 76063

Overall Score **7/10**




6,00,816

INTERIOR

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7	GOOD CONDITION	0
DOOR HINGES	7	GOOD CONDITION	0
CARPET & FLOOR MAT	7	GOOD CONDITION	0
SEAT & SEAT BELT	8	GOOD CONDITION	0
DASHBOARD & INSTRUMENT PANEL	8	GOOD CONDITION	0
HORN	8	GOOD SOUND	0
SPEAKERS & MUSIC SYSTEM	8	GOOD CONDITION	0
HANDBRAKE	8	GOOD CONDITION	0
STEERING-MOUNTED CONTROLS	8	GOOD CONDITION	0
PEDALS	8	GOOD WORKING	0
CENTRAL LOCK	8	GOOD	0
A/C VENTS & HEATER	8	GOOD COOLING	0
CUP HOLDERS	8	GOOD CONDITION	0
NAVIGATION (NO)	10		0
ODOMETER	8	GOOD CONDITION	0
POWER WINDOWS (YES)	8	ALL WORKING GOOD	0
HAZARD LIGHT	8	GOOD CONDITION	0

IMAGES





TEST DRIVE

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	8	SMOOTH	0
BRAKE PERFORMANCE	8	GOOD WORKING	0
CLUTCH PERFORMANCE	8	GOOD	0
ENGINE NOISE	7	MINIMUM	0
IGNITION SYSTEM	8	GOOD WORKING	0
SUSPENSION PERFORMANCE	7	GOOD	0
SUSPENSION FRONT SHOCKS	7	GOOD CONDITION	0
SUSPENSION REAR SHOCKS	7	GOOD CONDITION	0
TRANSMISSION ENGAGE	8	SMOOTH	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0



IMAGES




WHEEL

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7	GOOD CONDITION	0
SPARE TYRE (YES)	8	GOOD CONDITION	0
WHEEL ASSEMBLY (STEEL RIM)	7	GOOD CONDITION	0

 IMAGES




 HOOD



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7	GOOD CONDITION	0
RH APRON	7	GOOD CONDITION	0
RADIATOR	7	GOOD WORKING	0
WIRING	7	GOOD CONDITION	0
BATTERY	7	GOOD CONDITION	0
BRAKE FLUID LEVEL	6	MORE THAN AVERAGE	0
ENGINE OIL	6	GOOD CONDITION	0
COOLANT LEVEL	6	AVERAGE LEVEL	0
BRAKE & COOLANT HOSE PIPES	7	GOOD CONDITION	0
UNDERCARRIAGE	7	GOOD CONDITION	0
EXHAUST SYSTEM	7	GOOD WORKING	0

 IMAGES





Ordered by: caravan car | Inspected date: 2019-05-25

Order Id: 76063

Overall Score  **7/10**



6,00,816

 **EXTERIOR**

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	8	BOTH GOOD CONDITION	0
FRONT BUMPER	8	GOOD CONDITION	0
HEAD LIGHTS	8	GOOD CONDITION	0
GRILLE	8	GOOD CONDITION	0
TURN SIGNAL	8	GOOD CONDITION	0
FOG LAMPS	8	GOOD WORKING	0
HOOD	8	GOOD CONDITION	0
PILLAR	8	GOOD CONDITION	0
FRONT WINDSHIELD	7	GOOD CONDITION	0
SIDE VIEW MIRRORS	7	GOOD CONDITION	0
LH FENDER	8	GOOD CONDITION	0
LH FRONT DOOR	8	GOOD CONDITION	0
LH REAR DOOR	8	GOOD CONDITION	0
LH RUNNING BOARD	7	GOOD CONDITION	0
LH QUARTER PANEL	8	GOOD CONDITION	0
FUEL LID	8	GOOD CONDITION	0
REAR WINDSHIELD	7	GOOD CONDITION	0
REAR BUMPER	8	GOOD CONDITION	0
TAIL LIGHT	7	GOOD CONDITION	0
TRUNK LID/TAIL GATE	7	GOOD CONDITION	0
RH QUARTER PANEL	8	GOOD CONDITION	0
RH RUNNING BOARD	7	GOOD CONDITION	0
RH REAR DOOR	7	GOOD CONDITION	0
RH FRONT DOOR	8	GOOD CONDITION	0

Ordered by: caravan car | Inspected date: 2019-05-25

Order Id: 76063

Overall Score **7/10**



6,00,816


EXTERIOR (CONTINUED)

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FENDER	8	GOOD CONDITION	0
BODY RUST	7	NO RUST	0
ROOF (REGULAR)	7	GOOD CONDITION	0
PAINT CONDITION	8	GOOD	0
LUGGAGE COMPARTMENT LIGHT	0	N/A	0

IMAGES






 **NEED ATTENTION** 



 **DOCUMENTS**



 **DESCRIPTION**

Very good car condition

Ordered by: caravan car | Inspected date: 2019-05-25

Order Id: 76063

Overall Score




7/10



6,00,816

IMAGES





Ordered by: caravan car | Inspected date: 2019-05-25

Order Id: 76063

Overall Score



7/10



6,00,816



DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.