




ECO INSPECTION CERTIFICATE

Premium

Order ID : 73299






121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Mukta	Inspection Date : 2019-05-21	Location : JAIPUR	 Inspected By  VICKY KUMAR  Verified Technician 196+ vehicle inspected 1+ years experience
-----------------------	---------------------------------	----------------------	--

8/10

Overall Score

-  Evaluated across **5** segments
-  Covered **121+** checkpoints
-  **121** does not need attention
-  **1** Owner , **3** Years Vehicle Age
-  No Accidental History









Volkswagen Vento 1.6 MPI HIGHLINE PLUS, 2016



VEHICLE INFORMATION

MAKE	VOLKSWAGEN	ENGINE NUMBER	440310
MODEL	VENTO	REGISTRATION NO.	RJ44CA1306
MFG. DATE	01/2016	VIN/CHASSIS NUMBER	047215
TRIM	1.6 MPI HIGHLINE PLUS	ODOMETER READING	33201
COLOR	WHITE	INSURANCE EXPIRY	2019-5-21
BODY TYPE	SEDAN	VEHICLE PASSING	PRIVATE
FUEL TYPE	DIESEL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	9,000	 RC COPY AVAILABLE	ORIGINAL	 BANK HYPOTHECATION	NO
 DENT	NO	 INSURANCE COPY AVAILABLE	NO	 BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

7,73,936




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

 Interior	<div style="width: 80%;"></div>	8 / 10
 Wheel	<div style="width: 80%;"></div>	8 / 10
 Test Drive	<div style="width: 80%;"></div>	8 / 10
 Exterior	<div style="width: 80%;"></div>	8 / 10
 Hood	<div style="width: 80%;"></div>	8 / 10

TOTAL ESTIMATE SPEND 0



Ordered by: Mukta | Inspected date: 2019-05-21

Order Id: 73299

Overall Score



8/10



7,73,936



INTERIOR





8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	9		0
DOOR HINGES	8		0
CARPET & FLOOR MAT	8		0
SEAT & SEAT BELT	8		0
DASHBOARD & INSTRUMENT PANEL	9		0
HORN	8		0
SPEAKERS & MUSIC SYSTEM	8		0
HANDBRAKE	9		0
STEERING-MOUNTED CONTROLS	8		0
PEDALS	9		0
CENTRAL LOCK	8		0
A/C VENTS & HEATER	9		0
CUP HOLDERS	8		0
NAVIGATION (YES)	8		0
ODOMETER	9		0
POWER WINDOWS (YES)	8		0
HAZARD LIGHT	8		0



IMAGES





TEST DRIVE




8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	8		0
BRAKE PERFORMANCE	9		0
CLUTCH PERFORMANCE	8		0
ENGINE NOISE	8		0
IGNITION SYSTEM	9		0
SUSPENSION PERFORMANCE	8		0
SUSPENSION FRONT SHOCKS	9		0
SUSPENSION REAR SHOCKS	9		0
TRANSMISSION ENGAGE	8		0
CRUISE CONTROL (YES)	8		0
REAR PARKING SENSORS (YES)	8		0
REAR VIEW CAMERA (YES)	9		0



IMAGES




WHEEL



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	8		0
SPARE TYRE (YES)	8		0
WHEEL ASSEMBLY (ALLOY RIM)	9		0

 IMAGES




 HOOD




8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	8		0
RH APRON	9		0
RADIATOR	8		0
WIRING	9		0
BATTERY	8		0
BRAKE FLUID LEVEL	9		0
ENGINE OIL	8		0
COOLANT LEVEL	8		0
BRAKE & COOLANT HOSE PIPES	7		0
UNDERCARRIAGE	9		0
EXHAUST SYSTEM	8		0

 IMAGES





Ordered by: Mukta | Inspected date: 2019-05-21

Order Id: 73299

Overall Score



8/10



7,73,936



EXTERIOR



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	9		0
FRONT BUMPER	8		0
HEAD LIGHTS	8		0
GRILLE	9		0
TURN SIGNAL	8		0
FOG LAMPS	8		0
HOOD	8		0
PILLAR	9		0
FRONT WINDSHIELD	8		0
SIDE VIEW MIRRORS	8		0
LH FENDER	9		0
LH FRONT DOOR	8		0
LH REAR DOOR	8		0
LH RUNNING BOARD	9		0
LH QUARTER PANEL	8		0
FUEL LID	9		0
REAR WINDSHIELD	8		0
REAR BUMPER	8	REFUSED	0
TAIL LIGHT	8	REFUSED	0
TRUNK LID/TAIL GATE	9	REFUSED	0
LUGGAGE COMPARTMENT LIGHT	8	REFUSED	0
RH QUARTER PANEL	9		0
RH RUNNING BOARD	9		0
RH REAR DOOR	8		0

Ordered by: Mukta | Inspected date: 2019-05-21

Order Id: 73299

Overall Score



8/10



7,73,936



EXTERIOR (CONTINUED)




8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	8		0
RH FENDER	9		0
BODY RUST	9		0
ROOF (REGULAR)	8		0
PAINT CONDITION	9		0




IMAGES





 DOCUMENTS



RC/OL STATUS	
Registration No:	RJ44CA1306
Registration Date:	16-Aug-2016
Chassis No:	MECL16020T00000
Engine No:	CS5400000
Owner Name:	KAMAL KUMAR SARAN
Vehicle Class:	MOTOR CAR (L&V)
Fuel Type:	PETROL
Maker / Model:	OTHERS / VENTO 1.6 MPI
Fitness Upto:	15-Aug-2021
Insurance Upto:	16-Jul-2019
Fuel Norms:	BHARAT STAGE IV
Road Tax Paid Upto:	11-Jul-2021

 DESCRIPTION

good

Ordered by: Mukta | Inspected date: 2019-05-21

Order Id: 73299

Overall Score






8/10



7,73,936










IMAGES





REGULATORY STATUS

Registration No:	RJ44CA1306	Registration Date:	16-Aug-2016
Chassis No:	MEAL150087E00000	Engine No:	CL5400000
Owner Name:	KAMAL KUMAR SARKAR		
Vehicle Class:	MOTORCAR (L&V)	Fuel Type:	PETROL
Make / Model:	OTHERS / VENTO 1.6 MPI		
Fitness Up to:	15-Aug-2031	Insurance Up to:	16-Jul-2019
Fuel Norm:	BHARAT STAGE IV	Road Tax Paid Up to:	11-Jul-2031



Ordered by: Mukta | Inspected date: 2019-05-21

Order Id: 73299

Overall Score



8/10



7,73,936

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.