


ECO INSPECTION CERTIFICATE

Premium

Order ID : 76916

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Monika Sharma	Inspection Date : 2019-05-24	Location : GHAZIABAD	Inspected By  Kishan Kumar
-------------------------------	---------------------------------	-------------------------	---

6/10

Overall Score

- ✔ Evaluated across **5** segments
- ✔ Covered **121+** checkpoints
- ✔ **116** does not need attention
- ✔ **1** Owner , **3** Years Vehicle Age
- ✔ No Accidental History

✔ **Verified Technician**

316+ vehicle inspected
1+ years experience

Volkswagen Polo HIGHLINE 1.5L (D), 2016



VEHICLE INFORMATION			
MAKE	VOLKSWAGEN	ENGINE NUMBER	33080
MODEL	POLO	REGISTRATION NO.	UP16BF3681
MFG. DATE	04/2016	VIN/CHASSIS NUMBER	84444
TRIM	HIGHLINE 1.5L (D)	ODOMETER READING	89270
COLOR	FLASH RED	INSURANCE EXPIRY	2019-6-5
BODY TYPE	HATCHBACK	VEHICLE PASSING	PRIVATE
FUEL TYPE	DIESEL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS			
FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO
TYRE LIFE REMAINING (KM)	25,000	RC COPY AVAILABLE	ORIGINAL
DENT	NO	INSURANCE COPY AVAILABLE	YES (COMPREHENSIVE)
		SERVICE LOGS AVAILABLE	NO
		BANK HYPOTHECATION	YES
		BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.
With this evaluation, the Fair Market Price for this vehicle comes to be:

5,17,339




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 60%; background: linear-gradient(to right, yellow 60%, gray 40%);"></div>	6 / 10
Wheel	<div style="width: 70%; background: linear-gradient(to right, green 70%, gray 30%);"></div>	7 / 10
Test Drive	<div style="width: 50%; background: linear-gradient(to right, orange 50%, gray 50%);"></div>	5 / 10
Exterior	<div style="width: 70%; background: linear-gradient(to right, green 70%, gray 30%);"></div>	7 / 10
Hood	<div style="width: 70%; background: linear-gradient(to right, green 70%, gray 30%);"></div>	7 / 10

TOTAL ESTIMATE SPEND **250**



Ordered by: Monika Sharma | Inspected date: 2019-05-24

Order Id: 76916

Overall Score  **6/10**



5,17,339

INTERIOR

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7		0
DOOR HINGES	7		0
CARPET & FLOOR MAT	7		0
SEAT & SEAT BELT	7		0
DASHBOARD & INSTRUMENT PANEL	7		0
HORN	7		0
SPEAKERS & MUSIC SYSTEM	7		0
HANDBRAKE	7		0
PEDALS	7		0
CENTRAL LOCK	7		0
A/C VENTS & HEATER	7		0
CUP HOLDERS	7		0
ODOMETER	7		0
POWER WINDOWS (YES)	7		0
HAZARD LIGHT	7		0
STEERING-MOUNTED CONTROLS	0	NA	0
NAVIGATION (YES)	0	NA	0

IMAGES



Ordered by: Monika Sharma | Inspected date: 2019-05-24

Order Id: 76916

Overall Score



6/10



5,17,339



TEST DRIVE




5/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7		0
BRAKE PERFORMANCE	7		0
CLUTCH PERFORMANCE	7		0
ENGINE NOISE	7		0
IGNITION SYSTEM	7		0
SUSPENSION PERFORMANCE	7		0
SUSPENSION FRONT SHOCKS	7		0
SUSPENSION REAR SHOCKS	7		0
TRANSMISSION ENGAGE	8		0
CRUISE CONTROL (YES)	0	NA	0
REAR PARKING SENSORS (YES)	0	NA	0
REAR VIEW CAMERA (YES)	0	NA	0



IMAGES




WHEEL



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7		0
SPARE TYRE (YES)	8		0
WHEEL ASSEMBLY (ALLOY RIM)	7		0

 IMAGES




 HOOD



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7		0
RH APRON	7		0
RADIATOR	7		0
WIRING	7		0
BATTERY	7		0
BRAKE FLUID LEVEL	7		0
ENGINE OIL	7		0
COOLANT LEVEL	7		0
BRAKE & COOLANT HOSE PIPES	7		0
UNDERCARRIAGE	7		0
EXHAUST SYSTEM	7		0

 IMAGES



Ordered by: Monika Sharma | Inspected date: 2019-05-24

Order Id: 76916

Overall Score  **6/10**



5,17,339

 **EXTERIOR**

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7		0
FRONT BUMPER	6	SCRATCHES	250
HEAD LIGHTS	7		0
GRILLE	7		0
TURN SIGNAL	7		0
FOG LAMPS	7		0
HOOD	7		0
PILLAR	7		0
FRONT WINDSHIELD	6	AVERAGE CONDITION	0
SIDE VIEW MIRRORS	7		0
LH FENDER	7		0
LH FRONT DOOR	7		0
LH REAR DOOR	7		0
LH RUNNING BOARD	7		0
LH QUARTER PANEL	7		0
FUEL LID	7		0
REAR WINDSHIELD	7		0
REAR BUMPER	7		0
TAIL LIGHT	7		0
TRUNK LID/TAIL GATE	7		0
LUGGAGE COMPARTMENT LIGHT	7		0
RH QUARTER PANEL	7		0
RH RUNNING BOARD	7		0
RH REAR DOOR	7		0

Ordered by: Monika Sharma | Inspected date: 2019-05-24

Order Id: 76916

Overall Score **6/10**



5,17,339

EXTERIOR (CONTINUED)




7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	7		0
RH FENDER	7		0
BODY RUST	7		0
ROOF (REGULAR)	7		0
PAINT CONDITION	7		0

IMAGES



DOCUMENTS



DESCRIPTION

all body scratches

Ordered by: Monika Sharma | Inspected date: 2019-05-24

Order Id: 76916

Overall Score




6/10



5,17,339

IMAGES



Ordered by: Monika Sharma | Inspected date: 2019-05-24

Order Id: 76916

Overall Score



6/10



5,17,339

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.