

# ECO INSPECTION CERTIFICATE

Premium

Order ID : 76817

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Anshul Chawla	Inspection Date : 2019-05-24	Location : GHAZIABAD	Inspected By  Kishan Kumar
-------------------------------	---------------------------------	-------------------------	----------------------------------

**8/10**  
Overall Score

- Evaluated across 5 segments
- Covered 121+ checkpoints
- 120 does not need attention
- 1 Owner , 2 Years Vehicle Age
- No Accidental History

Verified Technician  
310+ vehicle inspected  
1+ years experience

## Toyota Innova Crysta 2.8 Z 7 STR AT, 2017



### VEHICLE INFORMATION

MAKE	TOYOTA	ENGINE NUMBER	59285
MODEL	INNOVA CRYSTA	REGISTRATION NO.	UP16BL0205
MFG. DATE	01/2017	VIN/CHASSIS NUMBER	67007
TRIM	2.8 Z 7 STR AT	ODOMETER READING	51410
COLOR	RED	INSURANCE EXPIRY	2020-1-31
BODY TYPE	MUV	VEHICLE PASSING	PRIVATE
FUEL TYPE	DIESEL	ENGINE SOUND LINK	<a href="#">LISTEN ENGINE SOUND</a>

### KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	30,000	RC COPY AVAILABLE	ORIGINAL	BANK HYPOTHECATION	YES
DENT	NO	INSURANCE COPY AVAILABLE	YES (ZERO DEPRECIATION)	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

**20,23,606**




Very Good Condition

### ECO SCORE & REPAIR COST ESTIMATE

#### ECO SCORE

Interior	<div style="width: 80%;"></div>	8 / 10
Wheel	<div style="width: 80%;"></div>	8 / 10
Test Drive	<div style="width: 80%;"></div>	8 / 10
Exterior	<div style="width: 80%;"></div>	8 / 10
Hood	<div style="width: 80%;"></div>	8 / 10

#### TOTAL ESTIMATE SPEND 0



Ordered by: Anshul Chawla | Inspected date: 2019-05-24

Order Id: 76817

Overall Score  **8/10**



**20,23,606**

## INTERIOR

**8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	8		0
DOOR HINGES	8		0
CARPET & FLOOR MAT	8		0
SEAT & SEAT BELT	8		0
DASHBOARD & INSTRUMENT PANEL	8		0
HORN	8		0
SPEAKERS & MUSIC SYSTEM	8		0
HANDBRAKE	8		0
STEERING-MOUNTED CONTROLS	8		0
PEDALS	8		0
CENTRAL LOCK	8		0
A/C VENTS & HEATER	8		0
CUP HOLDERS	8		0
ODOMETER	8		0
POWER WINDOWS (YES)	8		0
HAZARD LIGHT	8		0
NAVIGATION (YES)	0	NA	0

## IMAGES



Ordered by: Anshul Chawla | Inspected date: 2019-05-24

Order Id: 76817

Overall Score  **8/10**



**20,23,606**

## TEST DRIVE

**8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	8		0
BRAKE PERFORMANCE	8		0
CLUTCH PERFORMANCE	8		0
ENGINE NOISE	8		0
IGNITION SYSTEM	8		0
SUSPENSION PERFORMANCE	8		0
SUSPENSION FRONT SHOCKS	8		0
SUSPENSION REAR SHOCKS	8		0
TRANSMISSION ENGAGE	8		0
CRUISE CONTROL (YES)	8		0
REAR PARKING SENSORS (YES)	8		0
REAR VIEW CAMERA (YES)	8		0

## IMAGES




## WHEEL

**8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	8		0
SPARE TYRE (YES)	9	BRAND NEW	0
WHEEL ASSEMBLY (ALLOY RIM)	8		0

 IMAGES




 HOOD



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	8		0
RH APRON	8		0
RADIATOR	8		0
WIRING	8		0
BATTERY	8		0
BRAKE FLUID LEVEL	8		0
ENGINE OIL	8		0
COOLANT LEVEL	8		0
BRAKE & COOLANT HOSE PIPES	8		0
UNDERCARRIAGE	8		0
EXHAUST SYSTEM	8		0

 IMAGES



Ordered by: Anshul Chawla | Inspected date: 2019-05-24

Order Id: 76817

Overall Score  **8/10**



**20,23,606**

 **EXTERIOR**

 **8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7		0
FRONT BUMPER	8		0
HEAD LIGHTS	8		0
GRILLE	8		0
TURN SIGNAL	8		0
FOG LAMPS	8		0
HOOD	8		0
PILLAR	8		0
FRONT WINDSHIELD	8		0
SIDE VIEW MIRRORS	8		0
LH FENDER	8		0
LH FRONT DOOR	8		0
LH REAR DOOR	8		0
LH RUNNING BOARD	8		0
LH QUARTER PANEL	8		0
FUEL LID	8		0
REAR WINDSHIELD	8		0
REAR BUMPER	8		0
TAIL LIGHT	8		0
TRUNK LID/TAIL GATE	8		0
LUGGAGE COMPARTMENT LIGHT	8		0
RH QUARTER PANEL	8		0
RH RUNNING BOARD	8		0
RH REAR DOOR	8		0

Ordered by: Anshul Chawla | Inspected date: 2019-05-24

Order Id: 76817

Overall Score



8/10



20,23,606



## EXTERIOR (CONTINUED)



8/10


INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	8		0
RH FENDER	8		0
BODY RUST	8		0
ROOF (REGULAR)	8		0
PAINT CONDITION	8		0



## IMAGES



## DOCUMENTS



## DESCRIPTION

all body minor scratches

Ordered by: Anshul Chawla | Inspected date: 2019-05-24

Order Id: 76817

Overall Score




8/10



20,23,606

IMAGES





Ordered by: Anshul Chawla | Inspected date: 2019-05-24

Order Id: 76817

Overall Score



8/10



20,23,606

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.