

ECO INSPECTION CERTIFICATE

Premium

Order ID : 75828

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : MOHAMMED MUZAFFAR	Inspection Date : 2019-05-22	Location : HYDERABAD
--	--	--------------------------------

9/10

Overall Score

- ✔ Evaluated across **5** segments
- ✔ Covered **121+** checkpoints
- ✔ **121** does not need attention
- ✔ **1** Owner , **13** Years Vehicle Age
- ✔ No Accidental History

Inspected By

✔ **Verified Technician**

93+ vehicle inspected

1+ years experience

Sharan Kumar Bandi

Tata Indigo LX, 2006



VEHICLE INFORMATION

MAKE	TATA	ENGINE NUMBER	NOT THERE
MODEL	INDIGO	REGISTRATION NO.	AP9BD9889
MFG. DATE	08/2006	VIN/CHASSIS NUMBER	607154GTZPA0579
TRIM	LX	ODOMETER READING	99163
COLOR	GREY	INSURANCE EXPIRY	2016-8-1
BODY TYPE	SEDAN	VEHICLE PASSING	PRIVATE
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	15,000	RC COPY AVAILABLE	ORIGINAL	BANK HYPOTHECATION	NO
DENT	NO	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

1,08,815




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 100%; height: 10px; background-color: #007bff;"></div>	10 / 10
Wheel	<div style="width: 80%; height: 10px; background-color: #007bff;"></div>	8 / 10
Test Drive	<div style="width: 90%; height: 10px; background-color: #007bff;"></div>	9 / 10
Exterior	<div style="width: 80%; height: 10px; background-color: #007bff;"></div>	8 / 10
Hood	<div style="width: 100%; height: 10px; background-color: #007bff;"></div>	10 / 10

TOTAL ESTIMATE SPEND **3,500**



Ordered by: MOHAMMED MUZAFFAR | Inspected date: 2019-05-22

Order Id: 75828

Overall Score



9/10



1,08,815



INTERIOR





10/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	10		0
DOOR HINGES	10		0
CARPET & FLOOR MAT	10		0
SEAT & SEAT BELT	10		0
DASHBOARD & INSTRUMENT PANEL	10		0
HORN	9		0
SPEAKERS & MUSIC SYSTEM	10		0
HANDBRAKE	9		0
STEERING-MOUNTED CONTROLS	9		0
PEDALS	9		0
CENTRAL LOCK	9		0
A/C VENTS & HEATER	9		0
CUP HOLDERS	9		0
NAVIGATION (NO)	10		0
ODOMETER	10		0
POWER WINDOWS (YES - FRONT ONLY)	10		0
HAZARD LIGHT	10		0



IMAGES



Ordered by: MOHAMMED MUZAFFAR | Inspected date: 2019-05-22

Order Id: 75828

Overall Score **9/10**





1,08,815

TEST DRIVE

9/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	9		0
BRAKE PERFORMANCE	8		0
CLUTCH PERFORMANCE	9		0
ENGINE NOISE	9		0
IGNITION SYSTEM	9		0
SUSPENSION PERFORMANCE	9		0
SUSPENSION FRONT SHOCKS	9		0
SUSPENSION REAR SHOCKS	9		0
TRANSMISSION ENGAGE	9		0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0

IMAGES



WHEEL

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	8	NEED TO BE CHANGED	3500
SPARE TYRE (YES)	8		0
WHEEL ASSEMBLY (STEEL RIM)	8		0

 IMAGES



 HOOD

10/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	10		0
RH APRON	10		0
RADIATOR	10		0
WIRING	10		0
BATTERY	10		0
BRAKE FLUID LEVEL	10		0
ENGINE OIL	10		0
COOLANT LEVEL	10		0
BRAKE & COOLANT HOSE PIPES	10		0
UNDERCARRIAGE	10		0
EXHAUST SYSTEM	10		0

 IMAGES



Ordered by: MOHAMMED MUZAFFAR | Inspected date: 2019-05-22

Order Id: 75828

Overall Score  **9/10**



1,08,815

 **EXTERIOR**

 **8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	10		0
FRONT BUMPER	8		0
HEAD LIGHTS	8		0
GRILLE	8		0
TURN SIGNAL	8		0
FOG LAMPS	8		0
HOOD	8		0
PILLAR	8		0
FRONT WINDSHIELD	8		0
SIDE VIEW MIRRORS	8		0
LH FENDER	8		0
LH FRONT DOOR	8		0
LH REAR DOOR	8		0
LH RUNNING BOARD	8		0
LH QUARTER PANEL	8		0
FUEL LID	8		0
REAR WINDSHIELD	8		0
REAR BUMPER	8		0
TAIL LIGHT	8		0
TRUNK LID/TAIL GATE	8		0
LUGGAGE COMPARTMENT LIGHT	8		0
RH QUARTER PANEL	8		0
RH RUNNING BOARD	8		0
RH REAR DOOR	8		0

Ordered by: MOHAMMED MUZAFFAR | Inspected date: 2019-05-22

Order Id: 75828

Overall Score **9/10**



1,08,815

EXTERIOR (CONTINUED)

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	8		0
RH FENDER	8		0
BODY RUST	8		0
ROOF (REGULAR)	10		0
PAINT CONDITION	10		0

IMAGES



DESCRIPTION

good

Ordered by: MOHAMMED MUZAFFAR | Inspected date: 2019-05-22

Order Id: 75828

Overall Score




9/10



1,08,815

IMAGES



Ordered by: MOHAMMED MUZAFFAR | Inspected date: 2019-05-22

Order Id: 75828

Overall Score



9/10



1,08,815

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.