


ECO INSPECTION CERTIFICATE

Premium

Order ID : 76247

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Amit Malhotra	Inspection Date : 2019-05-23	Location : DELHI	Inspected By  Parvesh Kumar Verified Technician 267+ vehicle inspected 1+ years experience
--------------------------------------	--	----------------------------	--

7/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 119 does not need attention
- ✓ 2 Owners , 8 Years Vehicle Age
- ✓ No Accidental History










Skoda Laura ELEGANCE 2.0 TDI CR MT, 2011



VEHICLE INFORMATION

MAKE	SKODA	ENGINE NUMBER	08471
MODEL	LAURA	REGISTRATION NO.	DL7CK8573
MFG. DATE	04/2011	VIN/CHASSIS NUMBER	151747
TRIM	ELEGANCE 2.0 TDI CR MT	ODOMETER READING	86282
COLOR	SILVER	INSURANCE EXPIRY	2019-5-23
BODY TYPE	SEDAN	VEHICLE PASSING	PRIVATE
FUEL TYPE	DIESEL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	16,800	 RC COPY AVAILABLE	ORIGINAL	 BANK HYPOTHECATION	NOT APPLICABLE
 DENT	NO	 INSURANCE COPY AVAILABLE	NO	 BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

4,33,040




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

 Interior	<div style="width: 70%;"></div>	7 / 10
 Wheel	<div style="width: 70%;"></div>	7 / 10
 Test Drive	<div style="width: 80%;"></div>	8 / 10
 Exterior	<div style="width: 70%;"></div>	7 / 10
 Hood	<div style="width: 70%;"></div>	7 / 10

TOTAL ESTIMATE SPEND 2,850



Ordered by: Amit Malhotra | Inspected date: 2019-05-23

Order Id: 76247

Overall Score



7/10



4,33,040



INTERIOR






7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7	GOOD	0
DOOR HINGES	7	GOOD	0
CARPET & FLOOR MAT	7	GOOD	0
SEAT & SEAT BELT	8	WORKING	0
DASHBOARD & INSTRUMENT PANEL	8	GOOD	0
HORN	7	WORKING	0
SPEAKERS & MUSIC SYSTEM	7	YES	0
HANDBRAKE	7	YES	0
STEERING-MOUNTED CONTROLS	7	YES	0
PEDALS	7	GOOD	0
CENTRAL LOCK	7	YES	0
A/C VENTS & HEATER	7	YES	0
CUP HOLDERS	7	YES	0
NAVIGATION (NO)	10		0
ODOMETER	8	WORKING	0
POWER WINDOWS (YES)	7	WORKING	0
HAZARD LIGHT	7	YES	0



IMAGES





TEST DRIVE

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	8	GOOD	0
BRAKE PERFORMANCE	8	WORKING PROPERLY	0
CLUTCH PERFORMANCE	7	GOOD	0
ENGINE NOISE	7	NORMAL SOUND	0
IGNITION SYSTEM	7	GOOD	0
SUSPENSION PERFORMANCE	7	GOOD	0
SUSPENSION FRONT SHOCKS	7	GOOD	0
SUSPENSION REAR SHOCKS	7	GOOD	0
TRANSMISSION ENGAGE	7	GOOD	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (YES)	7	YES	0
REAR VIEW CAMERA (NO)	10		0



IMAGES




WHEEL

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7	GOOD	0
SPARE TYRE (YES)	7	GOOD	0
WHEEL ASSEMBLY (ALLOY RIM)	7	GOOD	0

 IMAGES




 HOOD



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7	GOOD	0
RH APRON	7	GOOD	0
RADIATOR	7	GOOD	0
WIRING	7	GOOD	0
BATTERY	7	GOOD	0
BRAKE FLUID LEVEL	7	MAXIMUM	0
ENGINE OIL	7	MAXIMUM	0
COOLANT LEVEL	7	MAXIMUM	0
BRAKE & COOLANT HOSE PIPES	7	GOOD	0
UNDERCARRIAGE	7	GOOD	0
EXHAUST SYSTEM	7	GOOD	0

 IMAGES



Ordered by: Amit Malhotra | Inspected date: 2019-05-23

Order Id: 76247

Overall Score  **7/10**



4,33,040

 **EXTERIOR**

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	8	GOOD	0
FRONT BUMPER	8	GOOD	0
GRILLE	7	GOOD	0
TURN SIGNAL	7	WORKING	0
FOG LAMPS	10	NA	0
HOOD	8	GOOD	0
PILLAR	8	GOOD	0
FRONT WINDSHIELD	8	GOOD	0
SIDE VIEW MIRRORS	8	GOOD	0
LH FENDER	8	GOOD	0
LH FRONT DOOR	8	GOOD	0
LH REAR DOOR	8	GOOD	0
LH RUNNING BOARD	8	GOOD	0
LH QUARTER PANEL	8	GOOD	0
FUEL LID	7	WORKING	0
REAR WINDSHIELD	7	GOOD	0
TAIL LIGHT	7	WORKING	0
TRUNK LID/TAIL GATE	7	GOOD	0
LUGGAGE COMPARTMENT LIGHT	8	YES	0
RH QUARTER PANEL	8	GOOD	0
RH RUNNING BOARD	8	GOOD	0
RH REAR DOOR	7	GOOD	0
RH FRONT DOOR	7	GOOD	0
RH FENDER	8	GOOD	0

Ordered by: Amit Malhotra | Inspected date: 2019-05-23

Order Id: 76247

Overall Score **7/10**




4,33,040





EXTERIOR (CONTINUED)

7/10


INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
BODY RUST	7	NO	0
ROOF (REGULAR)	8	GOOD	0
PAINT CONDITION	8	GOOD	0
HEAD LIGHTS	3	ONE SIDE NOT WORKING	2500
REAR BUMPER	5	BUMPER COVER NEED TO REPLACE	350

IMAGES





NEED ATTENTION



DOCUMENTS



DESCRIPTION

good condition of vehicle

Ordered by: Amit Malhotra | Inspected date: 2019-05-23

Order Id: 76247

Overall Score




7/10



4,33,040

IMAGES











REGN. NO : DL7CK8573 HP/PG

REGD DT: 06/02/11 CH NO: 7188970384-M147
 E NO: CL008411
 O/SNO: 50
 COLOUR: BR SILVER
 MFR: MARUTI SUZUKI INDIA PVT LTD
 VEN CL: Motor Car

NAME : ROHIT BHATIA
RESID OF : 10P BHATIA
ADDRESS : E 102 GROUND FLOOR GREATER KALASH,
 SOUTH DELHI PART II, New Delhi, Delhi
 110088

MODEL: SWIFT
 BODY: SALOON
 NO OF CYL: 4
 WHEELS: 4
 FUEL: DIESEL
 REGD UPTO: 06/06/2025
 TAX UPTO: QTY

WHEEL BASE: 0800mm
 UNLADEN WGT: 900kg
 SEATING C: 04
 SIGNATURE: [Signature]
 REGISTRAR AUTHORITY: [Signature]
 CU CAP: 011568



Ordered by: Amit Malhotra | Inspected date: 2019-05-23

Order Id: 76247

Overall Score



7/10



4,33,040

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.