

ECO INSPECTION CERTIFICATE

Premium

Order ID : 76186

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By :
Manoj Sharma

Inspection Date :
2019-05-28

Location :
THANE

6/10



Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 116 does not need attention
- ✓ 1 Owner , 3 Years Vehicle Age
- ✓ No Accidental History

Inspected By



Sagar Chavan

- ✓ Verified Technician
- 241+ vehicle inspected
- 1+ years experience

Toyota Etios G, 2016



VEHICLE INFORMATION

MAKE	TOYOTA	ENGINE NUMBER	
MODEL	ETIOS	REGISTRATION NO.	MH02EE0889
MFG. DATE	12/2015	VIN/CHASSIS NUMBER	MBJB29BT500103695
TRIM	G	ODOMETER READING	44779
COLOR	SILVER	INSURANCE EXPIRY	2019-4-18
BODY TYPE	SEDAN	VEHICLE PASSING	PRIVATE
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	20,000	RC COPY AVAILABLE	ORIGINAL	BANK HYPOTHECATION	NOT APPLICABLE
DENT	NO	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

5,12,858




ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 60%;"></div>	6 / 10
Wheel	<div style="width: 60%;"></div>	6 / 10
Test Drive	<div style="width: 70%;"></div>	7 / 10
Exterior	<div style="width: 60%;"></div>	6 / 10
Hood	<div style="width: 60%;"></div>	6 / 10

TOTAL ESTIMATE SPEND 0



Ordered by: manoj sharma | Inspected date: 2019-05-28

Order Id: 76186

Overall Score



6/10



5,12,858



INTERIOR






6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	6	NO DAMAGE	0
DOOR HINGES	6	NO DAMAGE	0
CARPET & FLOOR MAT	6	NO DAMAGE	0
SEAT & SEAT BELT	6	WORKING CONDITION	0
DASHBOARD & INSTRUMENT PANEL	6	NO DAMAGE	0
HORN	6	GOOD SOUND	0
SPEAKERS & MUSIC SYSTEM	6	WORKING CONDITION	0
HANDBRAKE	6	WORKING CONDITION	0
STEERING-MOUNTED CONTROLS	6	NO DAMAGE	0
PEDALS	6	WORKING CONDITION	0
CENTRAL LOCK	6	WORKING CONDITION	0
A/C VENTS & HEATER	6	GOOD COOLING	0
CUP HOLDERS	6	NO DAMAGE	0
NAVIGATION (NO)	10		0
ODOMETER	6	WORKING CONDITION	0
POWER WINDOWS (YES)	6	WORKING CONDITION	0
HAZARD LIGHT	6	WORKING CONDITION	0



IMAGES



Ordered by: manoj sharma | Inspected date: 2019-05-28

Order Id: 76186

Overall Score **6/10**



5,12,858

TEST DRIVE

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	6	GOOD PERFORMANCE	0
BRAKE PERFORMANCE	6	GOOD PERFORMANCE	0
ENGINE NOISE	6	MINIMUM	0
IGNITION SYSTEM	6	WORKING CONDITION	0
SUSPENSION PERFORMANCE	6	WORKING CONDITION	0
TRANSMISSION ENGAGE	6	SMOOTHLY TRANSFER	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0
CLUTCH PERFORMANCE	5	AVERAGE PERFORMANCE	0
SUSPENSION FRONT SHOCKS	5	AVERAGE CONDITION	0
SUSPENSION REAR SHOCKS	5	AVERAGE CONDITION	0

IMAGES




WHEEL

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	6	NORMAL WEAR & TEAR	0
SPARE TYRE (YES)	6	NO DAMAGE	0
WHEEL ASSEMBLY (STEEL RIM)	6	NO DAMAGE	0

 IMAGES




 HOOD



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	6	NO DAMAGE	0
RH APRON	6	NO DAMAGE	0
RADIATOR	6	WORKING CONDITION	0
WIRING	6	NO DAMAGE	0
BATTERY	6	GOOD CONDITION	0
BRAKE FLUID LEVEL	6	MAXIMUM	0
ENGINE OIL	6	GOOD CONDITION	0
COOLANT LEVEL	6	MAXIMUM	0
BRAKE & COOLANT HOSE PIPES	6	NO DAMAGE	0
UNDERCARRIAGE	6	WORKING CONDITION	0
EXHAUST SYSTEM	6	WORKING CONDITION	0

 IMAGES





Ordered by: manoj sharma | Inspected date: 2019-05-28

Order Id: 76186

Overall Score  **6/10**



5,12,858

 **EXTERIOR**

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	6	NO DAMAGE	0
FRONT BUMPER	6	NO DAMAGE	0
HEAD LIGHTS	6	WORKING CONDITION	0
GRILLE	6	NO DAMAGE	0
TURN SIGNAL	6	WORKING CONDITION	0
FOG LAMPS	6	NOT AVAILABLE	0
HOOD	6	GOOD CONDITION	0
PILLAR	6	NO DAMAGE	0
FRONT WINDSHIELD	6	CLEAR VISIBILITY	0
SIDE VIEW MIRRORS	6	NO DAMAGE	0
LH FENDER	6	NO DAMAGE	0
LH FRONT DOOR	6	NO DAMAGE	0
LH REAR DOOR	6	NO DAMAGE	0
LH RUNNING BOARD	6	NO DAMAGE	0
FUEL LID	6	WORKING CONDITION	0
REAR WINDSHIELD	6	NO DAMAGE	0
TAIL LIGHT	6	WORKING CONDITION	0
TRUNK LID/TAIL GATE	6	NO DAMAGE	0
LUGGAGE COMPARTMENT LIGHT	6	WORKING CONDITION	0
RH QUARTER PANEL	6	NO DAMAGE	0
RH RUNNING BOARD	6	GOOD CONDITION	0
RH REAR DOOR	6	GOOD CONDITION	0
RH FRONT DOOR	6	NO DAMAGE	0
RH FENDER	6	NO DAMAGE	0

Ordered by: manoj sharma | Inspected date: 2019-05-28

Order Id: 76186

Overall Score **6/10**



5,12,858








EXTERIOR (CONTINUED)

6/10


INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
BODY RUST	6	NOT AVAILABLE	0
ROOF (REGULAR)	6	NO DAMAGE	0
PAINT CONDITION	6	GOOD CONDITION	0
LH QUARTER PANEL	5	AVERAGE CONDITION	0
REAR BUMPER	5	AVERAGE CONDITION	0

IMAGES







 **NEED ATTENTION** 



 **DOCUMENTS**



 **DESCRIPTION**

good condition car

Ordered by: manoj sharma | Inspected date: 2019-05-28

Order Id: 76186

Overall Score



6/10



5,12,858

IMAGES





Ordered by: manoj sharma | Inspected date: 2019-05-28

Order Id: 76186

Overall Score



6/10



5,12,858

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.