


ECO INSPECTION CERTIFICATE

Premium

Order ID : 73242

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Surrender	Inspection Date : 2019-06-03	Location : DELHI	Inspected By  Verified Technician 438+ vehicle inspected 1+ years experience Abid Ali
---------------------------	---------------------------------	---------------------	---

6/10

Overall Score

- ✓ Evaluated across 6 segments
- ✓ Covered 121+ checkpoints
- ✓ 109 does not need attention
- ✓ 1 Owner , 15 Years Vehicle Age
- ✓ No Accidental History

Bajaj Pulsar 150cc, 2004



VEHICLE INFORMATION

MAKE	BAJAJ	ENGINE NUMBER	A50548
MODEL	PULSAR	REGISTRATION NO.	DL11SD2279
YEAR	2004	VIN/CHASSIS NUMBER	A51128
TRIM	150CC	ODOMETER READING	48172
COLOR	BLUE METAL	INSURANCE EXPIRY	2006-6-3
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY OBSERVATIONS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	1,000	RC COPY AVAILABLE	ORIGINAL	BANK HYPOTHECATION	NOT APPLICABLE
DENT	NO	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

9,869




ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Tyre	<div style="width: 70%;"></div>	7 / 10
Control	<div style="width: 70%;"></div>	7 / 10
Light	<div style="width: 40%;"></div>	4 / 10
Oil	<div style="width: 60%;"></div>	6 / 10
Chassis	<div style="width: 60%;"></div>	6 / 10
Stand	<div style="width: 60%;"></div>	6 / 10

TOTAL ESTIMATE SPEND 1,000



www.droom.in/eco

eco@droom.in

Contact No. 18004070707 (Toll Free)

-a service by .in

Ordered by: Surender | Inspected date: 2019-06-03

Order Id: 73242

Overall Score



6/10



9,869



TYRE



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRONT TYRE CONDITION & AIR PRESSURE	6	FAIR	0
REAR TYRE CONDITION & AIR PRESSURE	6	FAIR	0
WHEEL SPOKES FRONT	7	GOOD	0
WHEEL SPOKES REAR	7	GOOD	0
WHEEL RIM FRONT	7	GOOD	0
WHEEL RIM REAR	7	GOOD	0
WHEEL BEARINGS FRONT	7	GOOD	0
WHEEL BEARINGS REAR	7	GOOD	0
WHEEL SEALS FRONT	7	GOOD	0
WHEEL SEALS REAR	7	GOOD	0
BRAKE FUNCTION FRONT	7	GOOD	0
BRAKE FUNCTION REAR	7	GOOD	0
BRAKES CONDITION FRONT	7	GOOD	0
BRAKES CONDITION REAR	7	GOOD	0

IMAGES



Ordered by: Surender | Inspected date: 2019-06-03

Order Id: 73242

Overall Score



6/10



9,869

STAND



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
CENTRE STAND CONDITION	6	FAIR	0
CENTRE STAND RETENTION	6	FAIR	0
SIDE STAND CONDITION	6	FAIR	0
SIDE STAND RETENTION	6	FAIR	0

IMAGES



CONTROL



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
HANDLEBARS CONDITION	7	GOOD	0
LEVERS & PEDAL CONDITION	7	GOOD	0
PIVOTS	7	GOOD	0
CABLES CONDITION	6	FAIR	0
CABLES ROUTING	6	FAIR	0
HOSES CONDITION	6	FAIR	0
HOSES ROUTING	6	FAIR	0
THROTTLE OPERATION	7	GOOD	0

Ordered by: Surender | Inspected date: 2019-06-03

Order Id: 73242

Overall Score **6/10**



9,869

IMAGES




OIL

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LEVELS - ENGINE OIL	6	FAIR	0
LEVELS - GEAR OIL/SHAFT DRIVE (YES)	6	FAIR	0
LEVELS - HYDRAULIC FLUID (NO)	10		0
LEVELS - COOLANT (NO)	10		0
LEVELS - FUEL	6	FAIR	0
LEAKS - ENGINE OIL	6	FAIR	0
LEAKS - GEAR OIL	6	FAIR	0
LEAKS - FUEL	6	FAIR	0
LEAKS - HYDRAULIC FLUID	0	NA	0
LEAKS - COOLANT	0	NA	0

IMAGES



Ordered by: Surender | Inspected date: 2019-06-03

Order Id: 73242

Overall Score



6/10



9,869

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
BATTERY VENT TUBE	6	FAIR	0
SWITCHES OPERATION	7	GOOD	0
LENSES & REFLECTORS CONDITION	7	GOOD	0
WIRING CONDITION	7	GOOD	0
WIRING ROUTING	7	GOOD	0
BATTERY CONDITION	4	DISCHARGE NEED TO CHARGE	300
HEADLAMP CONDITION	5	NOT WORKING NEED TO CHANGE BULB	100
TAILLAMP/BRAKELAMP CONDITION	5	NOT WORKING NEED TO CHANGE BULB	100
TAILLAMP/BRAKELAMP OPERATION	0	NOT WORKING NEED TO CHANGE BULB	0
TURN SIGNALS OPERATION FRONT LEFT	4	NOT WORKING NEED TO CHANGE	50
TURN SIGNALS OPERATION FRONT RIGHT	3	NOT WORKING NEED TO CHANGE	50
TURN SIGNALS OPERATION REAR LEFT	3	NOT WORKING NEED TO CHANGE	50
TURN SIGNALS OPERATION REAR RIGHT	3	NOT WORKING NEED TO CHANGE	50
MIRRORS CONDITION	0	NOT FIX MIRROR NEED TO FIX NEW MIRROR FIX	300
MIRRORS AIM	0	NOT FIX MIRROR NEED TO FIX NEW MIRROR FIX	0

 IMAGES


Ordered by: Surender | Inspected date: 2019-06-03

Order Id: 73242

Overall Score





6/10



9,869



NEED ATTENTION



CHASSIS



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRAME CONDITION	6	FAIR	0
FRAME STEERING-HEAD BEARINGS	6	FAIR	0
FRAME SWINGARM BUSHINGS	6	FAIR	0
SUSPENSION FRONT FORKS LEFT	6	FAIR	0
SUSPENSION FRONT FORKS RIGHT	6	FAIR	0
SUSPENSION REAR SHOCKS LEFT	6	FAIR	0
SUSPENSION REAR SHOCKS RIGHT	6	FAIR	0
CHAIN/BELT TENSION	6	FAIR	0
CHAIN/BELT LUBRICATION	6	FAIR	0
CHAIN/BELT SPROCKETS	6	FAIR	0
FASTENERS THREADED	6	FAIR	0
FASTENERS CLIPS & COTTER PINS	6	FAIR	0
ENGINE	6	FAIR	0
TRANSMISSION	6	FAIR	0

Ordered by: Surender | Inspected date: 2019-06-03

Order Id: 73242

Overall Score




6/10



9,869

IMAGES



DOCUMENTS



DESCRIPTION

Fair condition vehicle Seat cover broken need to change

Ordered by: Surender | Inspected date: 2019-06-03

Order Id: 73242

Overall Score



6/10



9,869

IMAGES



Ordered by: Surender | Inspected date: 2019-06-03

Order Id: 73242

Overall Score



6/10



9,869

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.