

ECO INSPECTION CERTIFICATE

Premium


Order ID : 79165

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : SUDHIR KUMAR MANOCHA	Inspection Date : 2019-06-03	Location : FARIDABAD
---	--	--------------------------------


6/10



Overall Score

- ✔ Evaluated across **5** segments
- ✔ Covered **121+** checkpoints
- ✔ **121** does not need attention
- ✔ **1** Owner , **10** Years Vehicle Age
- ✔ No Accidental History

Inspected By



✔ **Verified Technician**

879+ vehicle inspected

1+ years experience

Lokesh Kumar










Fiat Punto EMOTION 1.2, 2009



VEHICLE INFORMATION

MAKE	FIAT	ENGINE NUMBER	03144
MODEL	PUNTO	REGISTRATION NO.	HR26AY4685
MFG. DATE	08/2009	VIN/CHASSIS NUMBER	002035
TRIM	EMOTION 1.2	ODOMETER READING	53740
COLOR	E RED	INSURANCE EXPIRY	2019-8-13
BODY TYPE	HATCHBACK	VEHICLE PASSING	PRIVATE
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	18,000	 RC COPY AVAILABLE	ORIGINAL	 BANK HYPOTHECATION	NOT APPLICABLE
 DENT	NO	 INSURANCE COPY AVAILABLE	YES (COMPREHENSIVE)	 BANK NOC	NO








Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

1,36,386




ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

 Interior	<div style="width: 60%;"></div>	6 / 10
 Wheel	<div style="width: 60%;"></div>	6 / 10
 Test Drive	<div style="width: 70%;"></div>	7 / 10
 Exterior	<div style="width: 60%;"></div>	6 / 10
 Hood	<div style="width: 60%;"></div>	6 / 10

TOTAL ESTIMATE SPEND 0



Ordered by: SUDHIR KUMAR MANOCHA | Inspected date: 2019-06-03

Order Id: 79165

Overall Score



6/10



1,36,386



INTERIOR







6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	6	FAIR	0
DOOR HINGES	6	FAIR	0
CARPET & FLOOR MAT	6	FAIR	0
SEAT & SEAT BELT	6	FAIR	0
DASHBOARD & INSTRUMENT PANEL	6	FAIR	0
HORN	6	FAIR	0
SPEAKERS & MUSIC SYSTEM	6	FAIR	0
HANDBRAKE	6	FAIR	0
STEERING-MOUNTED CONTROLS	6	FAIR	0
PEDALS	6	FAIR	0
CENTRAL LOCK	6	FAIR	0
A/C VENTS & HEATER	6	FAIR	0
CUP HOLDERS	6	FAIR	0
NAVIGATION (NO)	10		0
ODOMETER	6	FAIR	0
POWER WINDOWS (YES)	6	FAIR	0
HAZARD LIGHT	6	FAIR	0



IMAGES



Ordered by: SUDHIR KUMAR MANOCHA | Inspected date: 2019-06-03

Order Id: 79165

Overall Score



6/10



1,36,386



TEST DRIVE



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	6	FAIR	0
BRAKE PERFORMANCE	6	FAIR	0
CLUTCH PERFORMANCE	6	FAIR	0
ENGINE NOISE	6	MINOR	0
IGNITION SYSTEM	6	FAIR	0
SUSPENSION PERFORMANCE	6	FAIR	0
SUSPENSION FRONT SHOCKS	6	FAIR	0
SUSPENSION REAR SHOCKS	6	FAIR	0
TRANSMISSION ENGAGE	6	FAIR	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0



IMAGES



WHEEL



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7	GOOD	0
SPARE TYRE (YES)	6	FAIR	0
WHEEL ASSEMBLY (ALLOY RIM)	6	FAIR	0

 IMAGES



 HOOD



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	6	FAIR	0
RH APRON	6	FAUR	0
RADIATOR	6	FAIR	0
WIRING	6	FAIR	0
BATTERY	6	FAIR	0
BRAKE FLUID LEVEL	6	FAIR	0
ENGINE OIL	6	FAIR	0
COOLANT LEVEL	6	FAIR	0
BRAKE & COOLANT HOSE PIPES	6	FAIR	0
UNDERCARRIAGE	6	FAIR	0
EXHAUST SYSTEM	6	FAIR	0

 IMAGES



Ordered by: SUDHIR KUMAR MANOCHA | Inspected date: 2019-06-03

Order Id: 79165

Overall Score



6/10



1,36,386



EXTERIOR



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	6	FAIR	0
FRONT BUMPER	6	PAINTED	0
HEAD LIGHTS	6	FAIR	0
GRILLE	6	FAIR	0
TURN SIGNAL	6	FAIR	0
FOG LAMPS	6	FAIR	0
HOOD	6	FAIR	0
PILLAR	6	FAIR	0
FRONT WINDSHIELD	6	FAIR	0
SIDE VIEW MIRRORS	6	FAIR	0
LH FENDER	6	PAINTED	0
LH FRONT DOOR	6	FAIR	0
LH REAR DOOR	6	FAIR	0
LH RUNNING BOARD	6	FAIR	0
LH QUARTER PANEL	6	PAINTED	0
FUEL LID	6	FAIR	0
REAR WINDSHIELD	6	FAIR	0
REAR BUMPER	6	PAINTED	0
TAIL LIGHT	6	FAIR	0
TRUNK LID/TAIL GATE	6	FAIR	0
LUGGAGE COMPARTMENT LIGHT	6	FAIR	0
RH QUARTER PANEL	6	PAINTED	0
RH RUNNING BOARD	6	FAIR	0
RH REAR DOOR	6	FAIR	0

Ordered by: SUDHIR KUMAR MANOCHA | Inspected date: 2019-06-03

Order Id: 79165

Overall Score



6/10



1,36,386



EXTERIOR (CONTINUED)






6/10



INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	6	FAIR	0
RH FENDER	6	PAINTED	0
BODY RUST	6	MINOR	0
ROOF (REGULAR)	6	FAIR	0
PAINT CONDITION	6	FAIR	0



IMAGES



DOCUMENTS



DESCRIPTION

fair condition,, minor scratch,, interior and exterior dirty

Ordered by: SUDHIR KUMAR MANOCHA | Inspected date: 2019-06-03

Order Id: 79165

Overall Score




6/10



1,36,386

IMAGES



Ordered by: SUDHIR KUMAR MANOCHA | Inspected date: 2019-06-03

Order Id: 79165

Overall Score



6/10



1,36,386

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.