

ECO INSPECTION CERTIFICATE

Premium

Order ID : 76795

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Suhailpasha Pasha	Inspection Date : 2019-06-04	Location : BANGALORE
--	--	--------------------------------

8/10

Overall Score

- ✔ Evaluated across **5** segments
- ✔ Covered **121+** checkpoints
- ✔ **119** does not need attention
- ✔ **2** Owners , **8** Years Vehicle Age
- ✔ No Accidental History

Inspected By



✔ **Verified Technician**

234+ vehicle inspected

1+ years experience

Abhishek By










Hyundai I10 Sportz 1.2 Kappa2, 2011



VEHICLE INFORMATION

MAKE	HYUNDAI	ENGINE NUMBER	G4LABM6804
MODEL	I10	REGISTRATION NO.	KA51MM8698
MFG. DATE	05/2011	VIN/CHASSIS NUMBER	MALAN51CLBM923859
TRIM	SPORTZ 1.2 KAPPA2	ODOMETER READING	88486
COLOR	WHITE	INSURANCE EXPIRY	2019-5-10
BODY TYPE	HATCHBACK	VEHICLE PASSING	PRIVATE
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	25,000	 RC COPY AVAILABLE	DUPLICATE	 BANK HYPOTHECATION	NOT APPLICABLE
 DENT	NO	 INSURANCE COPY AVAILABLE	NO	 BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:




Orange Book Value Not Available

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

 Interior	<div style="width: 80%;"></div>	8 / 10
 Wheel	<div style="width: 80%;"></div>	8 / 10
 Test Drive	<div style="width: 80%;"></div>	8 / 10
 Exterior	<div style="width: 70%;"></div>	7 / 10
 Hood	<div style="width: 80%;"></div>	8 / 10

TOTAL ESTIMATE SPEND 7,500



Ordered by: suhailpasha pasha | Inspected date: 2019-06-04

Order Id: 76795

Overall Score



8/10



Orange Book Value Not Available



INTERIOR






8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	8		0
DOOR HINGES	7		0
CARPET & FLOOR MAT	8		0
SEAT & SEAT BELT	8		0
DASHBOARD & INSTRUMENT PANEL	8		0
HORN	8		0
SPEAKERS & MUSIC SYSTEM	8		0
HANDBRAKE	7		0
STEERING-MOUNTED CONTROLS	7		0
PEDALS	8		0
CENTRAL LOCK	8		0
A/C VENTS & HEATER	8		0
CUP HOLDERS	8		0
NAVIGATION (NO)	10		0
ODOMETER	8		0
POWER WINDOWS (YES)	8		0
HAZARD LIGHT	8		0



IMAGES





TEST DRIVE




8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	8		0
BRAKE PERFORMANCE	8		0
CLUTCH PERFORMANCE	7		0
ENGINE NOISE	8		0
IGNITION SYSTEM	8		0
SUSPENSION PERFORMANCE	8		0
SUSPENSION FRONT SHOCKS	8		0
SUSPENSION REAR SHOCKS	7		0
TRANSMISSION ENGAGE	8		0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0



IMAGES



WHEEL



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	8		0
SPARE TYRE (YES)	7		0
WHEEL ASSEMBLY (STEEL RIM)	8		0

 IMAGES



 HOOD



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	8		0
RH APRON	8		0
RADIATOR	8		0
WIRING	8		0
BATTERY	8		0
BRAKE FLUID LEVEL	7		0
ENGINE OIL	7		0
COOLANT LEVEL	7		0
BRAKE & COOLANT HOSE PIPES	8		0
UNDERCARRIAGE	8		0
EXHAUST SYSTEM	8		0

 IMAGES



Ordered by: suhailpasha pasha | Inspected date: 2019-06-04

Order Id: 76795

Overall Score



8/10



Orange Book Value Not Available



EXTERIOR



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7		0
FRONT BUMPER	8		0
HEAD LIGHTS	6	HIGH BEAM NOT WORKING	1000
GRILLE	8		0
TURN SIGNAL	8		0
HOOD	8		0
PILLAR	8		0
FRONT WINDSHIELD	6		0
SIDE VIEW MIRRORS	8		0
LH FENDER	8		0
LH FRONT DOOR	8		0
LH REAR DOOR	8		0
LH RUNNING BOARD	8		0
LH QUARTER PANEL	8		0
FUEL LID	8		0
REAR WINDSHIELD	8		0
REAR BUMPER	7		0
TAIL LIGHT	8		0
LUGGAGE COMPARTMENT LIGHT	8		0
RH QUARTER PANEL	8		0
RH RUNNING BOARD	8		0
RH REAR DOOR	8		0
RH FRONT DOOR	8		0
RH FENDER	8		0

Ordered by: suhailpasha pasha | Inspected date: 2019-06-04

Order Id: 76795

Overall Score **8/10**



Orange Book Value Not Available





EXTERIOR (CONTINUED)

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
BODY RUST	8		0
ROOF (REGULAR)	8		0
PAINT CONDITION	8		0
FOG LAMPS	2	NOT WORKING	2500
TRUNK LID/TAIL GATE	5	SHOCKS WEEK	4000

IMAGES






NEED ATTENTION



DOCUMENTS



DESCRIPTION

good condition

Ordered by: suhailpasha pasha | Inspected date: 2019-06-04

Order Id: 76795

Overall Score














8/10



Orange Book Value Not Available

IMAGES





Ordered by: suhailpasha pasha | Inspected date: 2019-06-04

Order Id: 76795

Overall Score



8/10



Orange Book Value Not Available



DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.