


ECO INSPECTION CERTIFICATE

Premium

Order ID : 81086

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Sourabh	Inspection Date : 2019-06-07	Location : PUNE	 <p>Inspected By</p> <p>Verified Technician 79+ vehicle inspected 1+ years experience</p> <p>Ameya Aranke</p>
<p>7/10</p> <p>Overall Score</p> <ul style="list-style-type: none"> Evaluated across 5 segments Covered 121+ checkpoints 121 does not need attention 3 Years Vehicle Age Accidental History Reported 			

Renault Kwid RXT OPT, 2016



VEHICLE INFORMATION

MAKE	RENAULT	ENGINE NUMBER	29936
MODEL	KWID	REGISTRATION NO.	DL8CY9051
MFG. DATE	02/2016	VIN/CHASSIS NUMBER	MEE8BA002G2325035
TRIM	RXT OPT	ODOMETER READING	44516
COLOR	BRONZE	INSURANCE EXPIRY	2020-3-30
BODY TYPE	SEDAN	VEHICLE PASSING	PRIVATE
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

- FLOOD DAMAGE
- TYRE LIFE REMAINING (KM)
- DENT
- MAJOR ACCIDENT(S)
- RC COPY AVAILABLE
- INSURANCE COPY AVAILABLE
- SERVICE LOGS AVAILABLE
- BANK HYPOTHECATION
- BANK NOC
- ORIGINAL
- YES (COMPREHENSIVE)



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

2,81,565




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 70%;"></div>	7 / 10
Wheel	<div style="width: 70%;"></div>	7 / 10
Test Drive	<div style="width: 80%;"></div>	8 / 10
Exterior	<div style="width: 70%;"></div>	7 / 10
Hood	<div style="width: 70%;"></div>	7 / 10

TOTAL ESTIMATE SPEND 0



Ordered by: Sourabh | Inspected date: 2019-06-07

Order Id: 81086

Overall Score



7/10



2,81,565



INTERIOR





7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7	GOOD CONDITION	0
DOOR HINGES	7	GOOD HINGS	0
CARPET & FLOOR MAT	7	GOOD	0
SEAT & SEAT BELT	7	GOOD MOVE	0
DASHBOARD & INSTRUMENT PANEL	7	WORKING	0
HORN	7	WORKING	0
SPEAKERS & MUSIC SYSTEM	7	GOOD SOUND	0
HANDBRAKE	7	PROPER HOLD	0
STEERING-MOUNTED CONTROLS	6	NOT AVAILABLE	0
PEDALS	7	GOOD	0
CENTRAL LOCK	7	WORKING	0
A/C VENTS & HEATER	7	GOOD COOLING	0
CUP HOLDERS	7	GOOD	0
NAVIGATION (NO)	10		0
ODOMETER	7	GOOD CONDITION	0
POWER WINDOWS (YES)	7	WORKING	0
HAZARD LIGHT	7	WORKING	0



IMAGES



Ordered by: Sourabh | Inspected date: 2019-06-07

Order Id: 81086

Overall Score **7/10**




2,81,565

TEST DRIVE

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7	GOOD	0
BRAKE PERFORMANCE	8	GOOD	0
CLUTCH PERFORMANCE	7	GOOD	0
ENGINE NOISE	7	WORKING	0
IGNITION SYSTEM	7	WORKING	0
SUSPENSION PERFORMANCE	7	GOOD	0
SUSPENSION FRONT SHOCKS	7	NO SHOCKS	0
SUSPENSION REAR SHOCKS	7	NO SHOCKS	0
TRANSMISSION ENGAGE	8	GOOD ENGAGE	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0

IMAGES



WHEEL

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7	BETTER CONDITION	0
SPARE TYRE (YES)	7	GOOD	0
WHEEL ASSEMBLY (STEEL RIM)	7	GOOD CONDITION	0

 IMAGES




 HOOD



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7	GOOD	0
RH APRON	7	GOOD	0
RADIATOR	7	GOOD	0
WIRING	7	GOOD	0
BATTERY	7	GOOD	0
BRAKE FLUID LEVEL	7	MAX	0
ENGINE OIL	8	MAX	0
COOLANT LEVEL	7	MAX	0
BRAKE & COOLANT HOSE PIPES	7	GOOD	0
UNDERCARRIAGE	7	NO RUSTY	0
EXHAUST SYSTEM	7	NO SMOKE	0

 IMAGES



Ordered by: Sourabh | Inspected date: 2019-06-07

Order Id: 81086

Overall Score  **7/10**



2,81,565

 **EXTERIOR**

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7	GOOD	0
FRONT BUMPER	7	GOOD CONDITION	0
HEAD LIGHTS	7	GOOD CONDITION	0
GRILLE	7	GOOD CONDITION	0
TURN SIGNAL	8	GOOD	0
FOG LAMPS	8	GOOD	0
HOOD	7	GOOD CONDITION	0
PILLAR	7	GOOD CONDITION	0
FRONT WINDSHIELD	8	GOOD VISIBILITY	0
SIDE VIEW MIRRORS	8	GOOD CONDITION	0
LH FENDER	7	GOOD CONDITION	0
LH FRONT DOOR	7	GOOD CONDITION	0
LH REAR DOOR	7	GOOD CONDITION	0
LH RUNNING BOARD	7	GOOD CONDITION	0
LH QUARTER PANEL	8	GOOD CONDITION	0
FUEL LID	7	GOOD CONDITION	0
REAR WINDSHIELD	8	GOOD VISIBILITY	0
REAR BUMPER	8	GOOD CONDITION	0
TAIL LIGHT	8	GOOD CONDITION	0
TRUNK LID/TAIL GATE	8	GOOD CONDITION	0
LUGGAGE COMPARTMENT LIGHT	7	GOOD SPACE	0
RH QUARTER PANEL	8	GOOD CONDITION	0
RH RUNNING BOARD	8	GOOD CONDITION	0
RH REAR DOOR	7	GOOD CONDITION	0

Ordered by: Sourabh | Inspected date: 2019-06-07

Order Id: 81086

Overall Score



7/10



2,81,565



EXTERIOR (CONTINUED)



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	8	GOOD CONDITION	0
RH FENDER	7	GOOD CONDITION	0
BODY RUST	8	NO BODY RUST	0
ROOF (REGULAR)	8	GOOD CONDITION	0
PAINT CONDITION	7	GOOD CONDITION	0





IMAGES





 DOCUMENTS



Ordered by: Sourabh | Inspected date: 2019-06-07

Order Id: 81086

Overall Score





7/10



2,81,565

 IMAGES





Ordered by: Sourabh | Inspected date: 2019-06-07

Order Id: 81086

Overall Score



7/10



2,81,565

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.