

# ECO INSPECTION CERTIFICATE

Premium

Order ID : 47127

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : SUNANDA BANKA	Inspection Date : 2019-03-05	Valid Till : 2019-06-06
-------------------------------	---------------------------------	----------------------------

## 6/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 121 does not need attention
- ✓ 2 Owners , 2 Years Vehicle Age
- ✓ No Accidental History

**Inspected By**

✓ **Verified Technician**  
22+ vehicle inspected  
1+ years experience

**Mrinmoy Samai**

## Mahindra Kuv100 Nxt K6 PLUS 5 STR, 2017



### VEHICLE INFORMATION

MAKE	MAHINDRA	TRANSMISSION TYPE	MANUAL
MODEL	KUV100 NXT	REGISTRATION NO.	WB24AK6309
YEAR	2017	VIN/CHASIS NUMBER	MA1VA2RBCH6A88820
TRIM	K6 PLUS 5 STR	KMS RUN	54952
COLOR	RED	INSURANCE EXPIRY	2018-12-14
BODY TYPE	OTHER	LOCATION	HAZRA
FUEL TYPE	PETROL	ENGINE SOUND LINK	<a href="#">LISTEN ENGINE SOUND</a>

### KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	30,000	RC COPY AVAILABLE	YES (ORIGINAL)	BANK HYPOTHECATION	NO
DENT	NO	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

**4,50,322**




### ECO SCORE & REPAIR COST ESTIMATE

#### ECO SCORE

Interior	<div style="width: 60%;"></div>	6 / 10
Wheel	<div style="width: 60%;"></div>	6 / 10
Test Drive	<div style="width: 70%;"></div>	7 / 10
Exterior	<div style="width: 60%;"></div>	6 / 10
Hood	<div style="width: 60%;"></div>	6 / 10

#### TOTAL ESTIMATE SPEND 0



Ordered by: SUNANDA BANKA | Inspected date: 2019-03-05

Order Id: 47127

Overall Score



6/10



4,50,322



## INTERIOR










6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	6	OK	0
DOOR HINGES	6	OK	0
CARPET & FLOOR MAT	6	OK	0
SEAT & SEAT BELT	6	OK	0
DASHBOARD & INSTRUMENT PANEL	6	OK	0
HORN	6	OK	0
SPEAKERS & MUSIC SYSTEM	6	GOOD CONDITION	0
HANDBRAKE	6	OK	0
STEERING-MOUNTED CONTROLS	6	OK	0
PEDALS	6	OK	0
CENTRAL LOCK	6	OK	0
A/C VENTS & HEATER	6	OK	0
CUP HOLDERS	6	OK	0
NAVIGATION (NO)	10		0
ODOMETER	6	OK	0
POWER WINDOWS (YES)	6	OK	0
HAZARD LIGHT	6	OK	0



## IMAGES





## TEST DRIVE




7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	6	GOOD	0
BRAKE PERFORMANCE	6	OK	0
CLUTCH PERFORMANCE	6	OK	0
ENGINE NOISE	6	OK	0
IGNITION SYSTEM	6	OK	0
SUSPENSION PERFORMANCE	6	OK	0
SUSPENSION FRONT SHOCKS	6	OK	0
SUSPENSION REAR SHOCKS	6	OK	0
TRANSMISSION ENGAGE	6	OK	0
CRUISE CONTROL (YES)	6	OK	0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0



## IMAGES



## WHEEL



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	6	OK	0
SPARE TYRE (YES)	6	OK	0
WHEEL ASSEMBLY (ALLOY RIM)	6	OK	0

## IMAGES



## HOOD




6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	6	OK	0
RH APRON	6	OK	0
RADIATOR	6	OK	0
WIRING	6	OK	0
BATTERY	6	OK	0
BRAKE FLUID LEVEL	6	FULL	0
ENGINE OIL	6	FULL	0
COOLANT LEVEL	6	FULL	0
BRAKE & COOLANT HOSE PIPES	6	OK	0
UNDERCARRIAGE	6	GOOD	0
EXHAUST SYSTEM	6	OK	0

## IMAGES





Ordered by: SUNANDA BANKA | Inspected date: 2019-03-05

Order Id: 47127

Overall Score  **6/10**



**4,50,322**

 **EXTERIOR**

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	6	GOOD	0
FRONT BUMPER	6	OK	0
HEAD LIGHTS	6	OK	0
GRILLE	6	OK	0
TURN SIGNAL	6	OK	0
FOG LAMPS	6	NA	0
HOOD	6	OK	0
PILLAR	6	OK	0
FRONT WINDSHIELD	6	GOOD CONDITION	0
SIDE VIEW MIRRORS	6	OK	0
LH FENDER	6	OK	0
LH FRONT DOOR	6	OK	0
LH REAR DOOR	6	OK	0
LH RUNNING BOARD	6	OK	0
LH QUARTER PANEL	6	OK	0
FUEL LID	6	OK	0
REAR WINDSHIELD	6	OK	0
REAR BUMPER	6	OK	0
TAIL LIGHT	6	OK	0
TRUNK LID/TAIL GATE	6	OK	0
LUGGAGE COMPARTMENT LIGHT	6	OK	0
RH QUARTER PANEL	6	OK	0
RH RUNNING BOARD	6	OK	0
RH REAR DOOR	6	OK	0

Ordered by: SUNANDA BANKA | Inspected date: 2019-03-05

Order Id: 47127

Overall Score  **6/10**



**4,50,322**

## EXTERIOR (CONTINUED)


**6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	6	OK	0
RH FENDER	6	OK	0
BODY RUST	6	NA	0
ROOF (REGULAR)	6	OK	0
PAINT CONDITION	6	GOOD	0

## IMAGES







 **DOCUMENTS**



 **DESCRIPTION**

this car is very good condition.



Ordered by: SUNANDA BANKA | Inspected date: 2019-03-05

Order Id: 47127

Overall Score




6/10



4,50,322



IMAGES













Ordered by: SUNANDA BANKA | Inspected date: 2019-03-05

Order Id: 47127

Overall Score



6/10



4,50,322

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.