

# ECO INSPECTION CERTIFICATE

Premium

Order ID : 46059

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.


<b>Ordered By :</b> TECHNO JUSTCARS 365 PRIVATE LIMITED	<b>Inspection Date :</b> 2019-03-08	<b>Valid Till :</b> 2019-06-08
---	--	-----------------------------------

## 10/10

**Overall Score**

- ✔ Evaluated across **5** segments
- ✔ Covered **121+** checkpoints
- ✔ **120** does not need attention
- ✔ **1** Owner , **4** Years Vehicle Age
- ✔ No Accidental History

**Inspected By**



✔ **Verified Technician**

61+ vehicle inspected

1+ years experience

**Sanjeev Kumar**




## Mahindra Tuv300 T8 AMT, 2015



### VEHICLE INFORMATION

<b>MAKE</b>	MAHINDRA	<b>TRANSMISSION TYPE</b>	MANUAL
<b>MODEL</b>	TUV300	<b>REGISTRATION NO.</b>	KA01MM7025
<b>YEAR</b>	2015	<b>VIN/CHASIS NUMBER</b>	MA1NA2SMEF6K45205
<b>TRIM</b>	T8 AMT	<b>KMS RUN</b>	37807
<b>COLOR</b>	RED	<b>INSURANCE EXPIRY</b>	2019-2-14
<b>BODY TYPE</b>	SEDAN	<b>LOCATION</b>	KASTURI NAGAR
<b>FUEL TYPE</b>	DIESEL	<b>ENGINE SOUND LINK</b>	<a href="#">LISTEN ENGINE SOUND</a>

### KEY HIGHLIGHTS

 <b>FLOOD DAMAGE</b>	NO	 <b>MAJOR ACCIDENT(S)</b>	NO	 <b>SERVICE LOGS AVAILABLE</b>	NO
 <b>TYRE LIFE REMAINING (KM)</b>	30,000	 <b>RC COPY AVAILABLE</b>	YES (ORIGINAL)	 <b>BANK HYPOTHECATION</b>	NO
 <b>DENT</b>	NO	 <b>INSURANCE COPY AVAILABLE</b>	NO	 <b>BANK NOC</b>	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

## 6,39,453




Very Good Condition

### ECO SCORE & REPAIR COST ESTIMATE

#### ECO SCORE

 <b>Interior</b>	<div style="width: 100%; height: 10px; background-color: green;"></div>	<b>10 / 10</b>
 <b>Wheel</b>	<div style="width: 100%; height: 10px; background-color: green;"></div>	<b>10 / 10</b>
 <b>Test Drive</b>	<div style="width: 100%; height: 10px; background-color: green;"></div>	<b>10 / 10</b>
 <b>Exterior</b>	<div style="width: 100%; height: 10px; background-color: green;"></div>	<b>10 / 10</b>
 <b>Hood</b>	<div style="width: 100%; height: 10px; background-color: green;"></div>	<b>10 / 10</b>

#### TOTAL ESTIMATE SPEND 250



Ordered by: TECHNO JUSTCARS 365 PRIVATE LIMITED | Inspected date: 2019-03-08

Order Id: 46059

Overall Score  **10/10**






**6,39,453**

## INTERIOR

10/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	10		0
DOOR HINGES	10		0
CARPET & FLOOR MAT	10		0
SEAT & SEAT BELT	10		0
DASHBOARD & INSTRUMENT PANEL	10		0
HORN	10		0
SPEAKERS & MUSIC SYSTEM	10		0
HANDBRAKE	10		0
STEERING-MOUNTED CONTROLS	10		0
PEDALS	10		0
CENTRAL LOCK	10		0
A/C VENTS & HEATER	10		0
CUP HOLDERS	10		0
NAVIGATION (NO)	10		0
ODOMETER	10		0
POWER WINDOWS (YES)	10		0
HAZARD LIGHT	10		0

## IMAGES



Ordered by: TECHNO JUSTCARS 365 PRIVATE LIMITED | Inspected date: 2019-03-08

Order Id: 46059

Overall Score  **10/10**



**6,39,453**

## TEST DRIVE

**10/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	10		0
BRAKE PERFORMANCE	10		0
CLUTCH PERFORMANCE	10		0
ENGINE NOISE	10		0
IGNITION SYSTEM	10		0
SUSPENSION PERFORMANCE	10		0
SUSPENSION FRONT SHOCKS	10		0
SUSPENSION REAR SHOCKS	10		0
TRANSMISSION ENGAGE	10		0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (YES)	10		0
REAR VIEW CAMERA (NO)	10		0

## IMAGES




## WHEEL

**10/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	10		0
SPARE TYRE (YES)	10		0
WHEEL ASSEMBLY (ALLOY RIM)	9		0

 IMAGES





 HOOD

10/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	10		0
RH APRON	10		0
RADIATOR	10		0
WIRING	10		0
BATTERY	8		0
BRAKE FLUID LEVEL	10		0
ENGINE OIL	9		0
COOLANT LEVEL	9		0
BRAKE & COOLANT HOSE PIPES	10		0
UNDERCARRIAGE	10		0
EXHAUST SYSTEM	10		0

 IMAGES







Ordered by: TECHNO JUSTCARS 365 PRIVATE LIMITED | Inspected date: 2019-03-08

Order Id: 46059

Overall Score  **10/10**



**6,39,453**

 **EXTERIOR**

 **10/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRONT BUMPER	10		0
HEAD LIGHTS	10		0
GRILLE	10		0
TURN SIGNAL	10		0
FOG LAMPS	9		0
HOOD	10		0
PILLAR	10		0
FRONT WINDSHIELD	10		0
SIDE VIEW MIRRORS	10		0
LH FENDER	10		0
LH FRONT DOOR	10		0
LH REAR DOOR	10		0
LH RUNNING BOARD	8		0
LH QUARTER PANEL	10		0
FUEL LID	10		0
REAR WINDSHIELD	10		0
REAR BUMPER	9		0
TAIL LIGHT	10		0
TRUNK LID/TAIL GATE	10		0
LUGGAGE COMPARTMENT LIGHT	10		0
RH QUARTER PANEL	10		0
RH RUNNING BOARD	10		0
RH REAR DOOR	10		0
RH FRONT DOOR	10		0

Ordered by: TECHNO JUSTCARS 365 PRIVATE LIMITED | Inspected date: 2019-03-08

Order Id: 46059

Overall Score  **10/10**



**6,39,453**

EXTERIOR (CONTINUED)








10/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FENDER	8		0
BODY RUST	10		0
ROOF (REGULAR)	10		0
PAINT CONDITION	10		0
LICENSE PLATE	5	BROKEN	250

IMAGES







 **NEED ATTENTION** 



 **DOCUMENTS**



 **DESCRIPTION**

vehicle is good condition



Ordered by: TECHNO JUSTCARS 365 PRIVATE LIMITED | Inspected date: 2019-03-08


Order Id: 46059

Overall Score



6,39,453

IMAGES







Ordered by: TECHNO JUSTCARS 365 PRIVATE LIMITED | Inspected date: 2019-03-08

Order Id: 46059

Overall Score  10/10



6,39,453

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.