

# ECO INSPECTION CERTIFICATE

Premium

Order ID : 46664

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Somu Sil	Inspection Date : 2019-03-08	Valid Till : 2019-06-13
--------------------------	---------------------------------	----------------------------

## 6/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 120 does not need attention
- ✓ 1 Owner , 7 Years Vehicle Age
- ✓ No Accidental History

**Inspected By**

✓ **Verified Technician**

623+ vehicle inspected

1+ years experience

**Lokesh Kumar**

## Toyota Prius 1.8, 2012



VEHICLE INFORMATION			
MAKE	TOYOTA	TRANSMISSION TYPE	AUTOMATIC
MODEL	PRIUS	REGISTRATION NO.	DL3CBX0711
YEAR	2012	VIN/CHASIS NUMBER	121853
TRIM	1.8	KMS RUN	112698
COLOR	SILVER	INSURANCE EXPIRY	2018-12-14
BODY TYPE	SEDAN	LOCATION	DELHI
FUEL TYPE	PETROL	ENGINE SOUND LINK	<a href="#">LISTEN ENGINE SOUND</a>

KEY HIGHLIGHTS			
FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO
TYRE LIFE REMAINING (KM)	28,000	RC COPY AVAILABLE	YES (ORIGINAL)
DENT	NO	INSURANCE COPY AVAILABLE	NO
		SERVICE LOGS AVAILABLE	NO
		BANK HYPOTHECATION	YES
		BANK NOC	YES

Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.  
With this evaluation, the Fair Market Price for this vehicle comes to be:

## 11,28,388

## ECO SCORE & REPAIR COST ESTIMATE

**ECO SCORE**

Interior	<div style="width: 70%; background-color: green; height: 10px;"></div>	7 / 10
Wheel	<div style="width: 70%; background-color: green; height: 10px;"></div>	7 / 10
Test Drive	<div style="width: 70%; background-color: green; height: 10px;"></div>	7 / 10
Exterior	<div style="width: 60%; background-color: yellow; height: 10px;"></div>	6 / 10
Hood	<div style="width: 60%; background-color: yellow; height: 10px;"></div>	6 / 10

**TOTAL ESTIMATE SPEND 1,500**

Ordered by: Somu Sil | Inspected date: 2019-03-08

Order Id: 46664

Overall Score



6/10



11,28,388



## INTERIOR





7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7	GOOD	0
DOOR HINGES	6	FAIR	0
CARPET & FLOOR MAT	6	FAIR	0
DASHBOARD & INSTRUMENT PANEL	7	GOOD	0
HORN	7	GOOD	0
SPEAKERS & MUSIC SYSTEM	7	GOOD	0
HANDBRAKE	6	FAIR	0
STEERING-MOUNTED CONTROLS	7	GOOD	0
PEDALS	6	FAIR	0
CENTRAL LOCK	7	GOOD	0
A/C VENTS & HEATER	7	GOOD	0
CUP HOLDERS	6	FAIR	0
NAVIGATION (NO)	10		0
ODOMETER	6	FAIR	0
POWER WINDOWS (YES)	7	GOOD	0
HAZARD LIGHT	6	FAIR	0
SEAT & SEAT BELT	5	REAR SEAT DIRTY	1500



## IMAGES



Ordered by: Somu Sil | Inspected date: 2019-03-08

Order Id: 46664

Overall Score **6/10**



**11,28,388**

## TEST DRIVE

**7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7	GOOD	0
BRAKE PERFORMANCE	7	GOOD	0
CLUTCH PERFORMANCE	7	GOOD	0
ENGINE NOISE	6	MINOR	0
IGNITION SYSTEM	6	FAIR	0
SUSPENSION PERFORMANCE	7	GOOD	0
SUSPENSION FRONT SHOCKS	7	GOOD	0
SUSPENSION REAR SHOCKS	7	GOOD	0
TRANSMISSION ENGAGE	6	FAIR	0
CRUISE CONTROL (YES)	6	FAIR	0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0

## IMAGES




## WHEEL

**7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7	GOOD	0
SPARE TYRE (YES)	7	GOOD	0
WHEEL ASSEMBLY (ALLOY RIM)	6	FAIR	0

 IMAGES



 HOOD



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	6	FAIR	0
RH APRON	6	FAIR	0
RADIATOR	6	FAIR	0
WIRING	6	FAIR	0
BATTERY	6	FAIR	0
BRAKE FLUID LEVEL	6	FAIR	0
ENGINE OIL	6	FAIR	0
COOLANT LEVEL	6	FAIR	0
BRAKE & COOLANT HOSE PIPES	6	FAIR	0
UNDERCARRIAGE	6	FAIR	0
EXHAUST SYSTEM	6	FAIR	0

 IMAGES



Ordered by: Somu Sil | Inspected date: 2019-03-08

Order Id: 46664

Overall Score  **6/10**



**11,28,388**

 **EXTERIOR**

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	6	FAIR	0
FRONT BUMPER	6	PAINTED	0
HEAD LIGHTS	7	GOOD	0
GRILLE	6	FAIR	0
TURN SIGNAL	6	FAIR	0
FOG LAMPS	7	GOOD	0
HOOD	6	PAINTED	0
PILLAR	6	PAINTED	0
FRONT WINDSHIELD	6	FAIR	0
SIDE VIEW MIRRORS	7	GOOD	0
LH FENDER	6	PAINTED	0
LH FRONT DOOR	6	PAINTED	0
LH REAR DOOR	6	PAINTED	0
LH RUNNING BOARD	6	PAINTED	0
LH QUARTER PANEL	6	PAINTED	0
FUEL LID	6	FAIR	0
REAR WINDSHIELD	6	FAIR	0
REAR BUMPER	6	PAINTED	0
TAIL LIGHT	6	FAIR	0
TRUNK LID/TAIL GATE	6	FAIR	0
LUGGAGE COMPARTMENT LIGHT	6	FAIR	0
RH QUARTER PANEL	6	PAINTED	0
RH RUNNING BOARD	6	PAINTED.	0
RH REAR DOOR	6	PAINTED	0



Ordered by: Somu Sil | Inspected date: 2019-03-08

Order Id: 46664

Overall Score  **6/10**



**11,28,388**

## EXTERIOR (CONTINUED)


**6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	6	PAINTED	0
RH FENDER	6	PAINTED	0
BODY RUST	6	MINOR	0
ROOF (REGULAR)	6	FAIR	0
PAINT CONDITION	6	FAIR	0

## IMAGES



## DOCUMENTS



## DESCRIPTION

fair condition



Ordered by: Somu Sil | Inspected date: 2019-03-08

Order Id: 46664

Overall Score




6/10



11,28,388

IMAGES





Ordered by: Somu Sil | Inspected date: 2019-03-08

Order Id: 46664

Overall Score



6/10



11,28,388

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.